

Attachment A

Prevailing Wage Documentation

Information Bulletin ***Occupational Classifications***

The Connecticut Department of Labor has the responsibility to properly determine "job classification" on prevailing wage projects covered under C.G.S. Section 31-53.

♪ Note: This information is intended to provide a sample of some occupational classifications for guidance purposes only. It is not an all-inclusive list of each occupation's duties. This list is being provided only to highlight some areas where a contractor may be unclear regarding the proper classification.

Below are additional clarifications of specific job duties performed for certain classifications:

Asbestos Insulator

- Handle, install, apply, fabricate, distribute, prepare, alter, repair, or dismantle heat and frost insulation, including penetration and fire stopping work on all penetration fire stop systems.

Carpenter

- Assembly and installation of modular furniture/furniture systems.
[New] a. Free-standing furniture is not covered. This includes: student chairs, study top desks, book box desks, computer furniture, dictionary stand, atlas stand, wood shelving, two- position information access station, file cabinets, storage cabinets, tables, etc.
- Applies fire stopping materials on fire resistive joint systems only.
- Installation of insulated material of all types whether blown, nailed or attached in other ways to walls, ceilings and floors of buildings.
- Installation of curtain/window walls only where attached to wood or metal studs.

Cleaning Laborer

- The clean up of any construction debris and the general cleaning, including sweeping, wash down, mopping, wiping of the construction facility, washing, polishing, dusting, etc., prior to the issuance of a certificate of occupancy falls under the *Labor classification*.

Delivery Personnel (Revised)

- If delivery of supplies/building materials is to one common point and stockpiled there, prevailing wages are not required. If the delivery personnel are involved in the distribution of the material to multiple locations within the construction site then they would have to be paid prevailing wages for the type of work performed: laborer, equipment operator, electrician, ironworker, plumber, etc.
- An example of this would be where delivery of drywall is made to a building and the delivery personnel distribute the drywall from one "stockpile" location to further sub-locations on each floor. Distribution of material around a construction site is the job of a laborer/tradesman and not a delivery personnel.

Electrician

- Installation or maintenance of telecommunication, LAN wiring or computer equipment.
- Low voltage wiring.

Fork Lift Operator

- Laborers Group 4) Mason Tenders - operates forklift solely to assist a mason to a maximum height of nine (9) feet only.
- Power Equipment Operator Group 9 - operates forklift to assist any trade, and to assist a mason to a height over nine (9) feet.

Glaziers

- Installs light metal sash, head sills, and 2-story aluminum storefronts.
- Installation of aluminum window walls and curtain walls is the "joint work" of the Glaziers and Ironworkers classification which requires either a blended rate or equal composite workforce.

Ironworkers

- Handling, sorting, and installation of reinforcing steel (rebar).
- Installation of aluminum window walls and curtain walls is the "joint work" of the Glaziers and Ironworkers classification which requires either a blended rate or equal composite workforce. Insulated metal and insulated composite panels are still installed by the Ironworker.
- Metal bridge rail (traffic), metal bridge handrail, and decorative security fence installation.

Insulator

- Installing fire stopping systems/materials for "Penetration Firestop Systems": transit to cables, electrical conduits, insulated pipes, sprinkler pipe penetrations, ductwork behind radiation, electrical cable trays, fire rated pipe penetrations, natural polypropylene, HVAC ducts, plumbing bare metal, telephone and communication wires, and boiler room ceilings. Past practice using the applicable licensed trades, Plumber, Sheet Metal, Sprinkler Fitter, and Electrician, is not inconsistent with the Insulator classification and would be permitted.

Lead Paint Removal

- Painter Rate
 1. Removal of lead paint from bridges.
 2. Removal of lead paint as preparation of any surface to be repainted.
 3. Where removal is on a Demolition project prior to reconstruction.
- Laborer Rate
 1. Removal of lead paint from any surface NOT to be repainted.
 2. Where removal is on a *TOTAL* Demolition project only.

Roofers


- Preparation of surface, tear-off and/or removal of any type of roofing, and/or clean-up of any areas where a roof is to be relaid.

Sheet Metal Worker

- Fabrication, handling, assembling, erecting, altering, repairing, etc. of coated metal material panels and composite metal material panels when used on building exteriors and interiors as soffits, fascia, louvers, partitions, wall panel siding, canopies, cornice, column covers, awnings, beam covers, cladding, sun shades, lighting troughs, spires, ornamental roofing, metal ceilings, mansards, copings, ornamental and ventilation hoods, vertical and horizontal siding panels, trim, etc. The sheet metal classification also applies to the vast variety of coated metal material panels and composite metal material panels that have evolved over the years as an alternative to conventional ferrous and non-ferrous metals like steel, iron, tin, copper, brass, bronze, aluminum, etc. Insulated metal and insulated composite panels are still installed by the Iron Worker. Fabrication, handling, assembling, erecting, altering, repairing, etc. of architectural metal roof, standing seam roof, composite metal roof, metal and composite bathroom/toilet partitions, aluminum gutters, metal and composite lockers and shelving, kitchen equipment, and walk-in coolers.

Truck Drivers

- Truck Drivers delivering asphalt are covered under prevailing wage while on the site and directly involved in the paving operation.
- Material men and deliverymen are not covered under prevailing wage as long as they are not directly involved in the construction process. If, they unload the material, they would then be covered by prevailing wage for the classification they are performing work in: laborer, equipment operator, etc.
- Hauling material off site is not covered provided they are not dumping it at a location outlined above.
- Driving a truck on site and moving equipment or materials on site would be considered covered work, as this is part of the construction process.

 Any questions regarding the proper classification should be directed to the Contract Compliance Unit, Wage and Workplace Standards Division, Connecticut Department of Labor, 200 Folly Brook Blvd, Wethersfield, CT 06 109 at (860) 263-6543.


~NOTICE~

TO ALL CONTRACTING AGENCIES

Please be advised that Connecticut General Statutes Section 31-53, requires the contracting agency to certify to the Department of Labor, the total dollar amount of work to be done in connection with such public works project, regardless of whether such project consists of one or more contracts.

Please find the attached “Contracting Agency Certification Form” to be completed and returned to the Department of Labor, Wage and Workplace Standards Division, Public Contract Compliance Unit.

 Inquiries can be directed to (860)263-6543.



CONNECTICUT DEPARTMENT OF LABOR
WAGE AND WORKPLACE STANDARDS DIVISION
CONTRACT COMPLIANCE UNIT

CONTRACTING AGENCY CERTIFICATION FORM

I, _____, acting in my official capacity as _____,
authorized representative title

for _____, located at _____,
contracting agency address

do hereby certify that the total dollar amount of work to be done in connection with

_____, located at _____,
project name and number address

shall be \$ _____, which includes all work, regardless of whether such project
consists of one or more contracts.

CONTRACTOR INFORMATION

Name: _____

Address: _____

Authorized Representative: _____

Approximate Starting Date: _____

Approximate Completion Date: _____

Signature

Date

Return To: Connecticut Department of Labor
Wage & Workplace Standards Division
Contract Compliance Unit
200 Folly Brook Blvd.
Wethersfield, CT 06109

Date Issued: _____

Informational Bulletin

THE 10-HOUR OSHA CONSTRUCTION SAFETY AND HEALTH COURSE

(applicable to public building contracts entered into *on or after July 1, 2007*, where the total cost of all work to be performed is at least \$100,000)

- (1) This requirement was created by Public Act No. 06-175, which is codified in Section 31-53b of the Connecticut General Statutes (pertaining to the prevailing wage statutes);
- (2) The course is required for public building construction contracts (projects funded in whole or in part by the state or any political subdivision of the state) entered into on or after July 1, 2007;
- (3) It is required of private employees (not state or municipal employees) and apprentices who perform manual labor for a general contractor or subcontractor on a public building project where the total cost of all work to be performed is at least \$100,000;
- (4) The ten-hour construction course pertains to the ten-hour Outreach Course conducted in accordance with federal OSHA Training Institute standards, and, for telecommunications workers, a ten-hour training course conducted in accordance with federal OSHA standard, 29 CFR 1910.268;
- (5) The internet website for the federal OSHA Training Institute is http://www.osha.gov/fso/ote/training/edcenters/fact_sheet.html;
- (6) The statutory language leaves it to the contractor and its employees to determine who pays for the cost of the ten-hour Outreach Course;
- (7) Within 30 days of receiving a contract award, a general contractor must furnish proof to the Labor Commissioner that all employees and apprentices performing manual labor on the project will have completed such a course;
- (8) Proof of completion may be demonstrated through either: (a) the presentation of a *bona fide* student course completion card issued by the federal OSHA Training Institute; *or* (2) the presentation of documentation provided to an employee by a trainer certified by the Institute pending the actual issuance of the completion card;
- (9) Any card with an issuance date more than 5 years prior to the commencement date of the construction project shall not constitute proof of compliance;

- (10) Each employer shall affix a copy of the construction safety course completion card to the certified payroll submitted to the contracting agency in accordance with Conn. Gen. Stat. § 31-53(f) on which such employee's name first appears;
- (11) Any employee found to be in non-compliance shall be subject to removal from the worksite if such employee does not provide satisfactory proof of course completion to the Labor Commissioner by the fifteenth day after the date the employee is determined to be in noncompliance;
- (12) Any such employee who is determined to be in noncompliance may continue to work on a public building construction project for a maximum of fourteen consecutive calendar days while bringing his or her status into compliance;
- (13) The Labor Commissioner may make complaint to the prosecuting authorities regarding any employer or agent of the employer, or officer or agent of the corporation who files a false certified payroll with respect to the status of an employee who is performing manual labor on a public building construction project;
- (14) The statute provides the minimum standards required for the completion of a safety course by manual laborers on public construction contracts; any contractor can exceed these minimum requirements; and
- (15) Regulations clarifying the statute are currently in the regulatory process, and shall be posted on the CTDOL website as soon as they are adopted in final form.
- (16) Any questions regarding this statute may be directed to the Wage and Workplace Standards Division of the Connecticut Labor Department via the internet website of <http://www.ctdol.state.ct.us/wgwkstnd/wgemenu.htm>; or by telephone at (860)263-6790.

THE ABOVE INFORMATION IS PROVIDED EXCLUSIVELY AS AN EDUCATIONAL RESOURCE, AND IS NOT INTENDED AS A SUBSTITUTE FOR LEGAL INTERPRETATIONS WHICH MAY ULTIMATELY ARISE CONCERNING THE CONSTRUCTION OF THE STATUTE OR THE REGULATIONS.

Sec. 31-53b. Construction safety and health course. New miner training program. Proof of completion required for mechanics, laborers and workers on public works projects. Enforcement. Regulations. Exceptions.

(a) Each contract for a public works project entered into on or after July 1, 2009, by the state or any of its agents, or by any political subdivision of the state or any of its agents, described in subsection (g) of section 31-53, shall contain a provision requiring that each contractor furnish proof with the weekly certified payroll form for the first week each employee begins work on such project that any person performing the work of a mechanic, laborer or worker pursuant to the classifications of labor under section 31-53 on such public works project, pursuant to such contract, has completed a course of at least ten hours in duration in construction safety and health approved by the federal Occupational Safety and Health Administration or, has completed a new miner training program approved by the Federal Mine Safety and Health Administration in accordance with 30 CFR 48 or, in the case of telecommunications employees, has completed at least ten hours of training in accordance with 29 CFR 1910.268.

(b) Any person required to complete a course or program under subsection (a) of this section who has not completed the course or program shall be subject to removal from the worksite if the person does not provide documentation of having completed such course or program by the fifteenth day after the date the person is found to be in noncompliance. The Labor Commissioner or said commissioner's designee shall enforce this section.

(c) Not later than January 1, 2009, the Labor Commissioner shall adopt regulations, in accordance with the provisions of chapter 54, to implement the provisions of subsections (a) and (b) of this section. Such regulations shall require that the ten-hour construction safety and health courses required under subsection (a) of this section be conducted in accordance with federal Occupational Safety and Health Administration Training Institute standards, or in accordance with Federal Mine Safety and Health Administration Standards or in accordance with 29 CFR 1910.268, as appropriate. The Labor Commissioner shall accept as sufficient proof of compliance with the provisions of subsection (a) or (b) of this section a student course completion card issued by the federal Occupational Safety and Health Administration Training Institute, or such other proof of compliance said commissioner deems appropriate, dated no earlier than five years before the commencement date of such public works project.

(d) This section shall not apply to employees of public service companies, as defined in section 16-1, or drivers of commercial motor vehicles driving the vehicle on the public works project and delivering or picking up cargo from public works projects provided they perform no labor relating to the project other than the loading and unloading of their cargo.

(P.A. 06-175, S. 1; P.A. 08-83, S. 1.)

History: P.A. 08-83 amended Subsec. (a) by making provisions applicable to public works project contracts entered into on or after July 1, 2009, replacing provision re total cost of work with reference to Sec. 31-53(g), requiring proof in certified payroll form that new mechanic, laborer or worker has completed a 10-hour or more construction safety course and adding provision re new miner training program, amended Subsec. (b) by substituting "person" for "employee" and adding "or program", amended Subsec. (c) by adding "or in accordance with Federal Mine

Safety and Health Administration Standards" and setting new deadline of January 1, 2009, deleted former Subsec. (d) re "public building", added new Subsec. (d) re exemptions for public service company employees and delivery drivers who perform no labor other than delivery and made conforming and technical changes, effective January 1, 2009.

November 29, 2006

Notice
To All Mason Contractors and Interested Parties
Regarding Construction Pursuant to Section 31-53 of the
Connecticut General Statutes (Prevailing Wage)

The Connecticut Labor Department Wage and Workplace Standards Division is empowered to enforce the prevailing wage rates on projects covered by the above referenced statute.

Over the past few years the Division has withheld enforcement of the rate in effect for workers who operate a forklift on a prevailing wage rate project due to a potential jurisdictional dispute.

The rate listed in the schedules and in our Occupational Bulletin (see enclosed) has been as follows:

Forklift Operator:

- **Laborers (Group 4) Mason Tenders** - operates forklift solely to assist a mason to a maximum height of nine feet only.
- **Power Equipment Operator (Group 9)** - operates forklift to assist any trade and to assist a mason to a height over nine feet.

The U.S. Labor Department conducted a survey of rates in Connecticut but it has not been published and the rate in effect remains as outlined in the above Occupational Bulletin.

Since this is a classification matter and not one of jurisdiction, effective January 1, 2007 the Connecticut Labor Department will enforce the rate on each schedule in accordance with our statutory authority.

Your cooperation in filing appropriate and accurate certified payrolls is appreciated.

Statute 31-55a

Last Updated: April 22, 2010

You are here: [DOL Web Site](#) » [Wage and Workplace Standards](#) » Statute 31-55a

- Special Notice -

To All State and Political Subdivisions, Their Agents, and Contractors

Connecticut General Statute 31-55a - Annual adjustments to wage rates by contractors doing state work.

Each contractor that is awarded a contract on or after October 1, 2002, for (1) the construction of a state highway or bridge that falls under the provisions of section 31-54 of the general statutes, or (2) the construction, remodeling, refinishing, refurbishing, rehabilitation, alteration or repair of any public works project that falls under the provisions of section 31-53 of the general statutes shall contact the Labor Commissioner on or before July first of each year, for the duration of such contract, to ascertain the prevailing rate of wages on an hourly basis and the amount of payment or contributions paid or payable on behalf of each mechanic, laborer or worker employed upon the work contracted to be done, and shall make any necessary adjustments to such prevailing rate of wages and such payment or contributions paid or payable on behalf of each such employee, effective each July first.

- The prevailing wage rates applicable to any contract or subcontract awarded on or after October 1, 2002 are subject to annual adjustments each July 1st for the duration of any project which was originally advertised for bids on or after October 1, 2002.
- Each contractor affected by the above requirement shall pay the annual adjusted prevailing wage rate that is in effect each July 1st, as posted by the Department of Labor.
- It is the **contractor's** responsibility to obtain the annual adjusted prevailing wage rate increases directly from the Department of Labor's Web Site. The annual adjustments will be posted on the Department of Labor Web page: www.ctdol.state.ct.us. For those without internet access, please contact the division listed below.
- The Department of Labor will continue to issue the initial prevailing wage rate schedule to the Contracting Agency for the project. All subsequent annual adjustments will be posted on our Web Site for contractor access.

Any questions should be directed to the Contract Compliance Unit, Wage and Workplace Standards Division, Connecticut Department of Labor, 200 Folly Brook Blvd., Wethersfield, CT 06109 at (860)263-6790.

←-- [Workplace Laws](#)

Published by the Connecticut Department of Labor, Project Management Office

Project: Asbestos Removal At 429 Marlborough Road And 131 Addison Road

**Minimum Rates and Classifications
for Heavy/Highway Construction**

H 14443

**Connecticut Department of Labor
Wage and Workplace Standards Division**

By virtue of the authority vested in the Labor Commissioner under provisions of Section 31-53 of the General Statutes of Connecticut, as amended, the following are declared to be the prevailing rates and welfare payments and will apply only where the contract is advertised for bid within 20 days of the date on which the rates are established. Any contractor or subcontractor not obligated by agreement to pay to the welfare and pension fund shall pay this amount to each employee as part of his/her hourly wages.

Project Number: GL-2011-18

Project Town Glastonbury

FAP Number:

State Number:

Project: Asbestos Removal At 429 Marlborough Road And 131 Addison Road

CLASSIFICATION

Hourly Rate

Benefits

01) Asbestos/Toxic Waste Removal Laborers: Asbestos removal and encapsulation (except its removal from mechanical systems which are not to be scrapped), toxic waste removers, blasters. **See Laborers Group 5 and 7**

1) Boilermaker

\$33.79

34% + 8.96

1a) Bricklayer, Cement Masons, Cement Finishers, Plasterers, Stone Masons

\$32.43

21.58

2) Carpenters, Piledrivermen

\$29.03

19.27

2a) Diver Tenders

\$29.03

19.27

As of: Thursday, November 18, 2010

Project: Asbestos Removal At 429 Marlborough Road And 131 Addison Road

3) Divers	\$37.49	19.27
4) Painters: (Bridge Construction) Brush, Roller, Blasting (Sand, Water, etc.), Spray	\$40.25	14.75
4a) Painters: Brush and Roller	\$28.47	15.40
4b) Painters: Spray Only	\$31.47	15.40
4c) Painters: Steel Only	\$30.47	15.40
4d) Painters: Blast and Spray	\$31.47	15.40
4e) Painters: Tanks, Tower and Swing	\$30.47	15.40
5) Electrician (Trade License required: E-1,2 L-5,6 C-5,6 T-1,2 L-1,2 V-1,2,7,8,9)	\$35.40	20.76

Project: Asbestos Removal At 429 Marlborough Road And 131 Addison Road

6) Ironworkers: (Ornamental, Reinforcing, Structural, and Precast Concrete Erection	\$33.00	26.58 + a
---	---------	-----------

7) Plumbers (Trade License required: (P-1,2,6,7,8,9 J-1,2,3,4 SP-1,2) and Pipefitters (Including HVAC Work) (Trade License required: S-1,2,3,4,5,6,7,8 B-1,2,3,4 D-1,2,3,4 G-1, G-2, G-8, G-9)	\$37.62	22.51
--	---------	-------

----LABORERS---- - Last updated 5/10/10

8) Group 1: Laborer (Unskilled), Common or General, acetylene burner, concrete specialist	\$25.00	15.00
---	---------	-------

9) Group 2: Chain saw operators, fence and guard rail erectors, pneumatic tool operators, powdermen, air tool operator	\$25.25	15.00
--	---------	-------

10) Group 3: Pipelayers (Installation of water, storm drainage or sewage lines outside of the building line with P6, P7 license)	\$25.50	15.00
--	---------	-------

11) Group 4: Jackhammer/Pavement breaker (handheld); mason tenders (cement/concrete), catch basin builders, asphalt rakers, air track operators, block pavers and curb setters	\$25.50	15.00
--	---------	-------

12) Group 5: Toxic waste removal (non-mechanical systems)	\$27.00	15.00
---	---------	-------

Project: Asbestos Removal At 429 Marlborough Road And 131 Addison Road

13) Group 6: Blasters	\$26.75	15.00
-----------------------	---------	-------

Group 7: Asbestos Removal, non-mechanical systems (does not include leaded joint pipe)	\$26.00	15.00
--	---------	-------

Group 8: Traffic control signalmen	\$16.00	15.00
------------------------------------	---------	-------

----LABORERS (TUNNEL CONSTRUCTION, FREE AIR). Shield Drive and Liner Plate Tunnels in Free Air.---- Last updated 5/10/10----

13a) Miners, Motormen, Mucking Machine Operators, Nozzle Men, Grout Men, Shaft & Tunnel Steel & Rodmen, Shield & Erector, Arm Operator, Cable Tenders	\$29.44	15.00 + a
---	---------	-----------

13b) Brakemen, Trackmen	\$28.58	15.00 + a
-------------------------	---------	-----------

----CLEANING, CONCRETE AND CAULKING TUNNEL----Last updated 5/10/10----

14) Concrete Workers, Form Movers, and Strippers	\$28.58	15.00 + a
--	---------	-----------

Project: Asbestos Removal At 429 Marlborough Road And 131 Addison Road

15) Form Erectors	\$28.88	15.00 + a
-------------------	---------	-----------

----ROCK SHAFT LINING, CONCRETE, LINING OF SAME AND
TUNNEL IN FREE AIR:----Last updated 5/10/10----

16) Brakemen, Trackmen, Tunnel Laborers, Shaft Laborers	\$28.58	15.00 + a
---	---------	-----------

17) Laborers Topside, Cage Tenders, Bellman	\$28.48	15.00 + a
---	---------	-----------

18) Miners	\$29.44	15.00 + a
------------	---------	-----------

----TUNNELS, CAISSON AND CYLINDER WORK IN COMPRESSED
AIR: ----Last updated 5/10/10----

18a) Blaster	\$35.21	15.00 + a
--------------	---------	-----------

19) Brakemen, Trackmen, Groutman, Laborers, Outside Lock Tender, Gauge Tenders	\$35.04	15.00 + a
---	---------	-----------

Project: Asbestos Removal At 429 Marlborough Road And 131 Addison Road

20) Change House Attendants, Powder Watchmen, Top on Iron Bolts	\$33.27	15.00 + a
---	---------	-----------

21) Mucking Machine Operator	\$35.75	15.00 + a
------------------------------	---------	-----------

----TRUCK DRIVERS----(*see note below)

Two axle trucks	\$27.88	14.53 + a
-----------------	---------	-----------

Three axle trucks; two axle ready mix	\$27.98	14.53 + a
---------------------------------------	---------	-----------

Three axle ready mix	\$28.03	14.53 + a
----------------------	---------	-----------

Four axle trucks, heavy duty trailer (up to 40 tons)	\$28.08	14.53 + a
--	---------	-----------

Four axle ready-mix	\$28.13	14.53 + a
---------------------	---------	-----------

As of: Thursday, November 18, 2010

Project: Asbestos Removal At 429 Marlborough Road And 131 Addison Road

Heavy duty trailer (40 tons and over)	\$28.33	14.53 + a
Specialized earth moving equipment other than conventional type on-the road trucks and semi-trailer (including Euclids)	\$28.13	14.53 + a

----POWER EQUIPMENT OPERATORS----

Group 1: Crane handling or erecting structural steel or stone, hoisting engineer (2 drums or over), front end loader (7 cubic yards or over), Work Boat 26 ft. & Over. (Trade License Required)	\$35.05	18.60 + a
Group 2: Cranes (100 ton rated capacity and over); Backhoe/Excavator over 2 cubic yards; Piledriver (\$3.00 premium when operator controls hammer). (Trade License Required)	\$34.73	18.60 + a
Group 3: Excavator; Cranes (under 100 ton rated capacity), Gradall; Master Mechanic; Hoisting Engineer (all types of equipment where a drum and cable are used to hoist or drag material regardless of motive power of operation), Rubber Tire Excavator (Drott-1085 or similar); Grader Operator; Bulldozer Fine Grade (slopes, shaping, laser or GPS, etc.). (Trade License Required)	\$33.99	18.60 + a
Group 4: Trenching Machines; Lighter Derrick; Concrete Finishing Machine; CMI Machine or Similar; Koehring Loader (Skooper)	\$33.60	18.60 + a
Group 5: Specialty Railroad Equipment; Asphalt Paver; Asphalt Spreader; Asphalt Reclaiming Machine; Line Grinder; Concrete Pumps; Drills with Self Contained Power Units; Boring Machine; Post Hole Digger; Auger; Pounder; Well Digger; Milling Machine (over 24" Mandrell)	\$33.01	18.60 + a

Project: Asbestos Removal At 429 Marlborough Road And 131 Addison Road

Group 5 continued: Side Boom; Combination Hoe and Loader; Directional Driller.	\$33.01	18.60 + a
Group 6: Front End Loader (3 up to 7 cubic yards); Bulldozer (rough grade dozer).	\$32.70	18.60 + a
Group 7: Asphalt Roller; Concrete Saws and Cutters (ride on types); Vermeer Concrete Cutter; Stump Grinder; Scraper; Snooper; Skidder; Milling Machine (24" and Under Mandrel).	\$32.36	18.60 + a
Group 8: Mechanic, Grease Truck Operator, Hydroblaster, Barrier Mover, Power Stone Spreader; Welder; Work Boat under 26 ft.; Transfer Machine.	\$31.96	18.60 + a
Group 9: Front End Loader (under 3 cubic yards), Skid Steer Loader regardless of attachments (Bobcat or Similar); Fork Lift, Power Chipper; Landscape Equipment (including hydroseeder).	\$31.53	18.60 + a
Group 10: Vibratory Hammer, Ice Machine, Diesel and Air Hammer, etc.	\$29.49	18.60 + a
Group 11: Conveyor, Earth Roller; Power Pavement Breaker (whiphammer), Robot Demolition Equipment.	\$29.49	18.60 + a
Group 12: Wellpoint Operator.	\$29.43	18.60 + a

Project: Asbestos Removal At 429 Marlborough Road And 131 Addison Road

Group 13: Compressor Battery Operator.	\$28.85	18.60 + a
Group 14: Elevator Operator; Tow Motor Operator (Solid Tire No Rough Terrain).	\$27.71	18.60 + a
Group 15: Generator Operator; Compressor Operator; Pump Operator; Welding Machine Operator; Heater Operator.	\$27.30	18.60 + a
Group 16: Maintenance Engineer/Oiler	\$26.65	18.60 + a
Group 17: Portable asphalt plant operator; portable crusher plant operator; portable concrete plant operator.	\$30.96	18.60 + a
Group 18: Power Safety Boat; Vacuum Truck; Zim Mixer; Sweeper; (minimum for any job requiring CDL license).	\$28.54	18.60 + a

**NOTE: SEE BELOW

----LINE CONSTRUCTION----(Railroad Construction and Maintenance)----Last updated 9/3/2010----

Project: Asbestos Removal At 429 Marlborough Road And 131 Addison Road

20) Lineman, Cable Splicer, Dynamite Man \$44.36 3% + 13.70

21) Heavy Equipment Operator \$39.92 3% + 13.70

22) Equipment Operator, Tractor Trailer Driver, Material Men \$37.71 3% + 13.70

23) Driver Groundmen \$33.27 3% + 13.70

----LINE CONSTRUCTION----Last updated 4/17/09----

24) Driver Groundmen \$30.92 6.5% + 9.70

25) Groundmen \$22.67 6.5% + 6.20

26) Heavy Equipment Operators \$37.10 6.5% + 10.70

Project: Asbestos Removal At 429 Marlborough Road And 131 Addison Road

27) Linemen, Cable Splicers, Dynamite Men	\$41.22	6.5% + 12.20
28) Material Men, Tractor Trailer Drivers, Equipment Operators	\$35.04	6.5% + 10.45

Project: Asbestos Removal At 429 Marlborough Road And 131 Addison Road

Welders: Rate for craft to which welding is incidental.

**Note: Hazardous waste removal work receives additional \$1.25 per hour for truck drivers.*

***Note: Hazardous waste premium \$3.00 per hour over classified rate*

Crane with 150 ft. boom (including jib) - \$1.50 extra
Crane with 200 ft. boom (including jib) - \$2.50 extra
Crane with 250 ft. boom (including jib) - \$5.00 extra
Crane with 300 ft. boom (including jib) - \$7.00 extra
Crane with 400 ft. boom (including jib) - \$10.00 extra

All classifications that indicate a percentage of the fringe benefits must be calculated at the percentage rate times the "base hourly rate".

Apprentices duly registered under the Commissioner of Labor's regulations on "Work Training Standards for Apprenticeship and Training Programs" Section 31-51-d-1 to 12, are allowed to be paid the appropriate percentage of the prevailing journeymen hourly base and the full fringe benefit rate, providing the work site ratio shall not be less than one full-time journeyman instructing and supervising the work of each apprentice in a specific trade.

~~Connecticut General Statute Section 31-55a: Annual Adjustments to wage rates by contractors doing state work~~

The Prevailing wage rates applicable to this project are subject to annual adjustments each July 1st for the duration of the project.

Each contractor shall pay the annual adjusted prevailing wage rate that is in effect each July 1st, as posted by the Department of Labor.

It is the contractor's responsibility to obtain the annual adjusted prevailing wage rate increases directly from the Department of Labor's website.

The annual adjustments will be posted on the Department of Labor's Web page: www.ct.gov/dol.

The Department of Labor will continue to issue the initial prevailing wage rate schedule to the Contracting Agency for the project.

All subsequent annual adjustments will be posted on our Web Site for contractor access.

As of: Thursday, November 18, 2010

Project: Asbestos Removal At 429 Marlborough Road And 131 Addison Road

Effective October 1, 2005 - Public Act 05-50: any person performing the work of any mechanic, laborer, or worker shall be paid prevailing wage

All Person who perform work ON SITE must be paid prevailing wage for the appropriate mechanic, laborer, or worker classification.

All certified payrolls must list the hours worked and wages paid to All Persons who perform work ON SITE regardless of their ownership i.e.: (Owners, Corporate Officers, LLC Members, Independent Contractors, et. al)

Reporting and payment of wages is required regardless of any contractual relationship alleged to exist between the contractor and such person.

~~Unlisted classifications needed for work not included within the scope of the classifications listed may be added after award only as provided in the labor standards contract clause (29 CFR 5.5 (a) (1) (ii)).

Please direct any questions which you may have pertaining to classification of work and payment of prevailing wages to the Wage and Workplace Standards Division, telephone (860)263-6790.

Connecticut Department of Labor
Wage and Workplace Standards Division
FOOTNOTES

Please Note: If the “Benefits” listed on the schedule for the following occupations includes a letter(s) (+ a or + a+b for instance), refer to the information below.

Benefits to be paid at the appropriate prevailing wage rate for the listed occupation.

If the “Benefits” section for the occupation lists only a dollar amount, disregard the information below.

**Bricklayers, Cement Masons, Cement Finishers, Concrete Finishers (including caulking),
Stone Masons**
(Building Construction) and
(Residential- Hartford, Middlesex, New Haven, New London and Tolland Counties)

- a. Paid Holiday: Employees shall receive 4 hours for Christmas Eve holiday provided the employee works the regularly scheduled day before and after the holiday. Employers may schedule work on Christmas Eve and employees shall receive pay for actual hours worked in addition to holiday pay.

Bricklayer (Residential- Fairfield County)

- a. Paid Holiday: If an employee works on Christmas Eve until noon he shall be paid for 8 hours.

Electricians

Fairfield County: West of the Five Mile River in Norwalk

- a. \$2.00 per hour not to exceed \$14.00 per day.

Elevator Constructors: Mechanics

- a. Paid Holidays: New Year’s Day, Memorial Day, Independence Day, Labor Day, Veterans’ Day, Thanksgiving Day, Christmas Day, plus the Friday after Thanksgiving.
- b. Vacation: Employer contributes 8% of basic hourly rate for 5 years or more of service or 6% of basic hourly rate for 6 months to 5 years of service as vacation pay credit.

Glaziers

- a. Paid Holidays: Labor Day and Christmas Day.

Power Equipment Operators

(Heavy and Highway Construction & Building Construction)

- a. Paid Holidays: New Year's Day, Good Friday, Memorial day, Independence Day, Labor Day, Thanksgiving Day and Christmas Day, provided the employee works 3 days during the week in which the holiday falls, if scheduled, and if scheduled, the working day before and the working day after the holiday. Holidays falling on Saturday may be observed on Saturday, or if the employer so elects, on the preceding Friday.

Ironworkers

- a. Paid Holiday: Labor Day provided employee has been on the payroll for the 5 consecutive work days prior to Labor Day.

Laborers (Tunnel Construction)

- a. Paid Holidays: New Year's Day, Memorial Day, Independence Day, Labor Day, Thanksgiving Day and Christmas Day. No employee shall be eligible for holiday pay when he fails, without cause, to work the regular work day preceding the holiday or the regular work day following the holiday.

Roofers

- a. Paid Holidays: July 4th, Labor Day, and Christmas Day provided the employee is employed 15 days prior to the holiday.

Sprinkler Fitters

- a. Paid Holidays: Memorial Day, July 4th, Labor Day, Thanksgiving Day and Christmas Day, provided the employee has been in the employment of a contractor 20 working days prior to any such paid holiday.

Truck Drivers

(Heavy and Highway Construction & Building Construction)

- a. Paid Holidays: New Year's Day, Memorial Day, Independence Day, Labor Day, Thanksgiving Day, Christmas day, and Good Friday, provided the employee has at least 31 calendar days of service and works the last scheduled day before and the first scheduled day after the holiday, unless excused.

Attachment B

Pre-Demolition ACM and Lead Based Paint Survey
For 429 Marlborough Road
Prepared by Triton Environmental, LLC



June 30, 2009

Mr. Daniel Pennington, PE
Town Engineer/Manager of Physical Services
Town of Glastonbury
2155 Main Street
Glastonbury, CT 06033

**Subject: Pre-Demolition ACM and Lead-Based Paint Survey
429 Marlborough Road – Glastonbury, Connecticut**

Dear Mr. Pennington:

Triton Environmental, Inc. (Triton) has completed a survey for the potential presence of asbestos containing materials (ACM) and lead-based paint (LBP) at the former Arbor Acres property located at 429 Marlborough Road in Glastonbury, Connecticut (the site). The approximate location of the site is depicted on Figure 1. The purpose of the survey was to attempt to identify the presence of ACM and LBP within the existing buildings that may be present at concentrations that would require special handling and disposal during building demolition activities.

Asbestos Containing Materials (ACM) Discussion and Results

The site consists of an approximate 75-acre parcel (former poultry farm) and is developed with 18 site buildings. The asbestos survey was completed for each of the site buildings in accordance with Environmental Protection Agency (EPA) and State of Connecticut regulations. The ACM survey was performed by licensed asbestos inspectors (State of Connecticut license # 000015, 000249, and 000661). A walk through of the building structures was first completed to establish the locations of various suspect ACM. Once the location and quantity of each suspect ACM was documented, representative samples of each ACM were collected. Since the survey was performed for demolition purposes, destructive sampling techniques were used in select locations in an attempt to observe and obtain samples of suspect building materials.

The EPA recommends that a minimum of three samples from each suspect homogeneous material be collected and analyzed in order to determine that a material is negative for asbestos content (exceptions apply when only a small amount of a material (less than three linear or square feet) is present. In accordance with this protocol, suspect ACM samples were collected and submitted to Environmental Hazards Services, LLC (EHS), a licensed analytical laboratory. The samples were analyzed via the Polarized Light Microscopy (PLM) method (EPA 600/R-93/116 Method).

The survey was performed during an approximately two week period from May 18 through June 1, 2009. A total of 810 suspect ACM samples obtained from the 18 site buildings

were collected and submitted to EHS for PLM bulk analysis (see Figure 2). The following table summarizes the PLM bulk analysis results for positive ACM detections. Analytical results may be found in the Mystic Air Quality Consultants (MAQC) analytical reports included as Appendix A.

**Summary of Identified Asbestos Containing Materials
429 Marlborough Road – Glastonbury, CT**

Sample Nos.	Material Type	Sample Location	Asbestos Content (%)	Material Quantity (Approx)
<i>Main Office Building</i>				
4-6	1x1 White Floor Tile/Mastic	Lobby #1 and Room #2- top layer Hallway #3, 4 - only layer Room #3 - under plywood, bottom layer	3% Chrysotile 3% Total Asbestos	~5,200 SF
7-9	9x9 Green Floor Tile/Mastic	Lobby #1, Room #2 - bottom layer Offices 1-6 - only layer	4% Chrysotile 4% Total Asbestos	~2,050 SF
10-12	9x9 Red Floor Tile/Mastic	Waiting Room & Office #7 - only layer	4-5% Chrysotile 4-5% Total Asbestos	~345 SF
13-15	9x9 Tan Floor Tile/Mastic	Hallway #1 – only layer	5% Chrysotile 5% Total Asbestos	~820 SF
16-18	Linoleum	Room #3 - top layer	20% Chrysotile 20% Total Asbestos	~455 SF
22-24	9x9 Tan Floor Tile/Yellow Mastic	Office #10 & #11 - only layer	4% Chrysotile 4% Total Asbestos	~140 SF
25-27	9x9 White Floor Tile/Black Mastic	Offices 8, 26, 29 - only layer	5% Chrysotile 5% Total Asbestos	~895 SF
28-30	9x9 Light Tan Floor Tile/Black Mastic	Office #9 & Hallway #6	4% Chrysotile 4% Total Asbestos	~1,610 SF
37-39	Tan Floor Tile	Storage Room #3	2% Chrysotile 2% Total Asbestos	~60 SF
40-42	Linoleum & mastic	Room #4	2% Chrysotile* 2% Total Asbestos	~285 SF
43-45	Transite Panels/Wall &	Storage Rm. #4 & #33 - ceiling only	20% Chrysotile 20% Total	~2,100 SF

	Ceiling		Asbestos	
46-48	Floor tile	Room B – Section 1D - Basement	4% Chrysotile 4% Total Asbestos	~220 SF
49-51	Floor Tile/Black Mastic	Room C – Section 1D - Basement	4% Chrysotile 4% Total Asbestos	~720 SF
69-71	Mastic/Light Grey Cove Base	Offices #1-7, Open Room C, Hallway #9 & #10, Main Entrance Stairwell -2 nd Floor	2% Chrysotile 2% Total Asbestos	~1,780 LF
101	Pipe Insulation	Bottom of Basement #2 Stairs - pipe elbow behind wall	60% Chrysotile 60% Total Asbestos	1 elbow
102-104	Flashing Tar	Interior – top of wall in open rooms – levels #1 and #2	10% Chrysotile 10% Total Asbestos	~50 SF
107-109	Glazing	Exterior Windows	2% Chrysotile 2% Total Asbestos	25 Windows
114-115	Silver Paint	Built Up Roofing - Roof B	3% Chrysotile 3% Total Asbestos	~7,000 SF
119	Silver Paint	Built Up Roofing - Roof A	2% Chrysotile, 2% Total Asbestos	~10,000 SF
120-122	Tar-Silver Paint	Siding of Tower - Roof A	7% Chrysotile 7% Total Asbestos	~250 SF
126-128	Flashing	All Roofs - around penetrations, seams, edges, bottom of ducts & rolled on roofing	8% Chrysotile 8% Total Asbestos	~1,000 SF
<i>Truck Wash Building</i>				
10-12	Roof Flashing	Roofs #1 & #2 - around penetrations	5% Chrysotile 5% Total Asbestos	~20 SF
<i>Laboratory Storage Building</i>				
1-5	1x1 Floor Tile Mastic	Hallway #1, Main Room #1, Room #2, Offices 1-4, men's & women's bathrooms	3% Chrysotile 3% Total Asbestos	~1,250 SF

12-14	Transite Panels	Throughout building except basement & equipment storage	20% Chrysotile 20% Total Asbestos	~7,350 SF
32-34	Exterior Window Caulking	Room #1	2% Chrysotile 2% Total Asbestos	6 Windows
51-53, 60-62	Tar-Silver Roofing Paint	Flat Roof	4-15% Chrysotile, 4- 15% Total	~7,250 SF
54-56	Flashing	Around Penetrations & on concrete wall - Flat Roof	15-18% Chrysotile, 15- 18% Total	~50 SF
57-59	Roof Tar	Seams of rolled roofing & Patching - Flat Roof	4% Chrysotile 4% Total Asbestos	~1,000 SF
<i>Shower/Laundry Building</i>				
36-38	Silver Paint	Top Layer on Flat Roofs 1 & 2 – built up roofing	2% Chrysotile 2% Total Asbestos	~3,000 SF
39-41	Flashing	Around Penetrations, patches & edges of Flat Roofs	15% Chrysotile 15% Total Asbestos	~150 SF
46	Furnace Cement	Furnace Room and around furnace pipe	55% Chrysotile 55% Total Asbestos	~6 SF
47	Silver Paint	On Penetrations on Flat Roof	5% Chrysotile 5% Total Asbestos	~3 SF
<i>Production Office</i>				
1-3	Transite Panel	Above Drop Ceilings – Rooms #1, #2	20% Chrysotile 20% Total Asbestos	~800 SF
13-15	1x1 Floor Tile & Mastic	Open Room #1 – only layer	5% Actinolite 5% Total Asbestos	~1,000 SF
19-21	Floor Tile	Bath #1 & #2	3% Chrysotile 3% Total Asbestos	~160 SF
22-24	2x4 Transite Panels	Drop Ceiling Panels – Room 10, furnace & panel room	18% Chrysotile 18% Total Asbestos	~380 SF
28-30, 32	Built Up Roofing	Main Roof - all Layers	4% Chrysotile 4% Total Asbestos	~5,508 SF

34-36	Flashing	Around Penetrations & Edges of Roof	12% Chrysotile 12% Total Asbestos	~350 SF
<i>Poultry House #45</i>				
4-6	Flashing Tar - Silver Brittle Coating	Roof	2-7% Chrysotile 2-7% Total Asbestos**	~1,000 SF
<i>Poultry House #49</i>				
7-9	Silver Paint	On Roofing	2% Chrysotile 2% Total Asbestos**	ALL
10-12	Flashing Tar	On Roof	4% Chrysotile 4% Total Asbestos	~1,000 SF
<i>Poultry House #55</i>				
1-3	Transite Panels	3 rd Floor Room - next to Front Entrance – Wall and ceiling panels	25% Chrysotile 25% Total Asbestos	~300
4-6, 10	Silver Paint	On Built up Roofing – around hatch and ceramic trim	<1% Chrysotile <1% Total Asbestos**	All
7-9	Flashing	Edge and Trim of Roofing Field	<1% Chrysotile <1% Total Asbestos**	~200 SF
<i>Residential Apartment #2</i>				
4-6	Flooring Material beneath Plywood	Kitchen	2% Chrysotile 2% Total Asbestos	~180 SF
<i>Residential Apartment #4</i>				
22-24	Flooring Material beneath Plywood	Kitchen	4% Chrysotile 4% Total Asbestos	~150 SF
25-27	Flooring Material Beneath Plywood	Bedroom	5% Chrysotile 5% Total Asbestos	~80 SF
<i>Residential House #1</i>				
14-16	Linoleum	Hallway and Basement Stairs – Top Layer	20% Chrysotile 20% Total Asbestos	~80 SF

29-31	Flooring	Room 4	2% Chrysotile 2% Total Asbestos	~40 SF
<i>Furnace Building</i>				
10	Flue Cement	Around Furnace Pipe on Wall	70% Chrysotile 70% Total Asbestos	~5 SF
<i>Residential House #2</i>				
13-15	Roof Flashing	Roof Seams & Around Chimney	15% Chrysotile 15% Total Asbestos	All
22-24	1x1 Black and Off White Floor Tile	Kitchen #1	2% Chrysotile 2% Total Asbestos	~155 SF
25-27	Textured Paint	Dining Room #1	2% Chrysotile 2% Total Asbestos	~370 SF
52-54	9x9 Black Tile	Sun Room	5% Chrysotile 5% Total Asbestos	~180 SF
<i>Residential House #3</i>				
23-25	Linoleum	First Floor Kitchen and Hallway	18% Chrysotile 18% Total Asbestos	~350 SF
35-37	Linoleum	Second Floor Bathroom #3	45% Chrysotile 45% Total Asbestos	~75 SF
41-43	Joint Compound	Bathroom #3	<1% Chrysotile <1% Total Asbestos†	~75 SF
53-55	Floor Tile	Bathroom #5	3% Chrysotile 3% Total Asbestos	~60 SF
59-61	Mastic on Cove Base	Throughout Basement – except bathroom #5	3% Chrysotile 3% Total Asbestos	~130 LF
68-70	Roof Flashing Tar	Around penetrations on Roof	12% Chrysotile 12% Total Asbestos	~20 SF
<i>Residential House #4</i>				
20-22	Cream/Beige Linoleum & Mastic	Second Floor Room 8 – Bath & Room 9 – Shower Room	25% Chrysotile 25% Total Asbestos	~50 SF

26-28	Brown 9x9 Floor Tile	Basement	4% Chrysotile 4% Total Asbestos	~400 SF
29-31	Beige Linoleum	Kitchen & Room 3	20% Chrysotile 20% Total Asbestos	~400 SF
<i>Residential Apartment #6</i>				
10-12	Glazing	Exterior Windows	<1% Chrysotile <1% Total Asbestos	10 Windows
25-27	Linoleum/Mastic Beneath Plywood	Baths #1 & 2, Kitchens #1 & 2, and Living room #1	20% Chrysotile 20% Total Asbestos	~225 SF
28-30	Floor Tile Beneath Plywood	Both Baths, Kitchens, Living Rooms – bottom layer * under two layers of plywood except in living room #2	3% Chrysotile 3% Total Asbestos	~400 SF
<i>Residential Apartment #5</i>				
22-24	Linoleum/Mastic Beneath Plywood	Bathroom	20% Chrysotile 20% Total Asbestos	~180 SF

LF = Linear Feet SF = Square Feet

* Possible contamination from fibrous backing.

** Trace, chrysotile present in tar-like material and/or 2 to 3% chrysotile present in silver paint material.

*** 4 to 5% chrysotile present in silver paint.

**** 9% chrysotile present in brown fibrous material.

† 2% chrysotile present in the gray joint compound like material over white texture.

Special Considerations

- Main Office Building – Any of the non-asbestos roofing materials with flashing, roof tar or silver paint attached will need to be treated as asbestos-contaminated and be cut out with it when abated.
- Truck Wash Building – Any of the non-asbestos roofing materials with flashing attached will need to be treated as asbestos-contaminated and be cut out with it when abated.
- Laboratory Storage Building – Any of the non-asbestos roofing materials with flashing, roof tar or silver paint attached will need to be treated as asbestos-contaminated and be cut out with it when abated.
- Shower Laundry Building – Any of the non-asbestos roofing materials with flashing or silver paint attached will need to be treated as asbestos-contaminated and be cut out with it when abated.

-
- Production Office – Any of the non-asbestos roofing materials with flashing attached will need to be treated as asbestos-contaminated and be cut out with it when abated.
 - Poultry House, Building #45 – Any of the non-asbestos roofing materials with flashing or silver brittle surface coating attached will need to be treated as asbestos-contaminated and be cut out with it when abated.
 - Poultry House, Building #49 – Any of the non-asbestos roofing materials with flashing or silver paint attached will need to be treated as asbestos-contaminated and be cut out with it when abated.
 - Poultry House, Building #55 – Any of the non-asbestos roofing materials with flashing or silver paint attached will need to be treated as asbestos-contaminated and be cut out with it when abated.
 - Residential House #2 – Any of the non-asbestos roofing materials with flashing attached will need to be treated as asbestos-contaminated and be cut out with the flashing when abated.
 - Residential House #3 – The sheetrock is not asbestos. However, because the joint compound is asbestos, the sheetrock should not be sanded, abraded, or ground and only properly trained workers are to be involved in renovation/demolition activities. When demolition occurs the sheetrock system may be disposed of as non-asbestos waste.
 - Residential House #4 – ACM was identified in the linoleum and mastic on the second floor (Room 8 and Room 9 shower room), 9x9 basement floor tile, and linoleum in kitchen and Room 3 (samples 20A/B, 26A, 27B, 28B, and 29A). Materials not referred to as asbestos-containing in this area can be treated as such.
 - Furnace Building – ACM was identified in the flue cement around the furnace pipe on the wall (sample 10). Materials not referred to as asbestos-containing in this area can be treated as such.

Lead Based Paint (LBP) Testing Results and Discussion

TCLP lead sampling at the site to determine if debris generated from the demolition of buildings at the site would be suitable for landfill disposal or if it would require special handling as a hazardous waste. A total of fifteen composite building material samples (such as wood, drywall, plaster, glass, metal, etc.) were collected in representative weight proportions to those present in the expected building demolition debris.

The results of the TCLP lead-based paint survey indicate that no TCLP lead was detected at concentrations equal to or greater than 5.0 mg/L. Therefore, lead-based paint waste materials will not require special handling.

Recommendations

Based on the results of this survey, ACM were found within all of the site structures at 429 Marlborough Road in Glastonbury, Connecticut, with the exception of the vehicle maintenance garage, Apartment #1 and Apartment #3. Triton recommends the removal and off-site disposal of identified ACM by a licensed State of Connecticut asbestos abatement contractor prior to any demolition or renovation work being conducted. Preliminary ACM abatement costs have been provided in the attached Table.

Limitations

This survey was completed for demolition purposes and involved the use of destructive sampling techniques to investigate suspect ACM. Although efforts were made to inspect all building materials, it should be noted that ACM might be present behind fixed building components such as walls, ceilings, and floors that were not accessed. If suspect ACM is encountered during demolition activities, demolition work should be halted until the suspect ACM is sampled and analyzed.

Triton has relied upon information provided by subcontractors (testing laboratories) in completing the ACM and LBP survey. Triton provides no warranty regarding the accuracy and completeness of the information provided by subcontractors.

This letter is intended solely to summarize the results of the Pre-Demolition ACM and Lead-Based Paint Survey conducted at the site. This letter is not intended to serve as a technical specification for building demolition and should not be used as such. All demolition activities should be conducted in accordance with all applicable local, State, and Federal regulations and OSHA guidelines.

Closing

Triton has appreciated the opportunity to assist the Town of Glastonbury with this project. We are available to discuss these conclusions and recommendations with you at your convenience. If you should have any questions or comments regarding this letter or the enclosed report, please contact us at 203.458.7200.

Sincerely,



Darby Hittle, LEP
Senior Project Manager



J. Carver Glezen, L.E.P.
Senior Vice President

Figure 1	Site Location Map
Figure 2	Site Plan Showing Building Locations
Table 1	ACM Abatement Cost Summary
Appendix A	Testing and Laboratory Reports



Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

June 5, 2009

Mr. Frank Kehoe
 Triton Environmental
 385 Church Street, Suite 201
 Guilford, Connecticut 06437

Re: **Pre-Demo/Renovation Asbestos Survey and TCLP Analysis (5/27/09)**
 429 Marlborough Road; Glastonbury, Connecticut; Location: Main Office Building

Dear Mr. Kehoe:

As requested, Mystic Air Quality Consultants, Inc. conducted a survey of accessible materials prior to demolition at the location noted above. This survey was directed on May 27, 2009, by our State of Connecticut licensed asbestos inspector, Christopher Eident, (license # 000015) to determine the presence of asbestos-containing materials. The samples were analyzed at Environmental Hazards Services (NVLAP # 101882-0) in Virginia.

In addition to the asbestos survey, composites or TCLP samples were collected and analyzed for lead to determine if the demolition materials would have to be considered lead waste. The sample analysis was also done by Environmental Hazards Services.

Summary of the Asbestos Findings- Upon testing by polarized light microscopy, the following materials were found to be asbestos containing:

<u>Sample #s</u>	<u>Material/Location</u>	<u>Estimated Affected Area</u>
4 - 6	Mastic/1x1 white floor tile -Lobby #1 and Room #2 -top layer -Hallway #3, 4 -only layer, Room #3 -under plywood bottom layer	5,200 sq. ft. ✓
7 - 9	9x9 Green floor tile and mastic/Lobby #1 & Room #2 -bottom layer Offices 1 - 6 -only layer	2,050 sq. ft. ✓
10 - 12	9x9 Red floor tile and mastic/Waiting Room & Office #7 -only layer	345 sq. ft. ✓
13 - 15	9x9 Tan floor tile/Hallway #1 -only layer	820 sq. ft. ✓
16 - 18	Linoleum/Room #3 -top layer	455 sq. ft. ✓
22 - 24	9x9 Tan floor tile/Office #10 & #11 -only layer	140 sq. ft. ✓
25 - 27	9x9 White floor tile & mastic/Offices #8, #26 -29 -only layer	895 sq. ft. ✓
28 - 30	9x9 Light tan floor tile/Office #9 & Hallway #6	1,610 sq. ft. ✓
37 - 39	Tan floor tile/Storage Room #3	60 sq. ft. ✓
40 - 42	Linoleum & mastic/Room #4	285 sq. ft. ✓
43 - 45	Transite Panels/Wall & Ceiling -Storage Rm. #4 & #33 -ceiling only	2,100 sq. ft. ✓
46 - 48	Floor tile/Room B -Section 1D -Basement	220 sq. ft.
49 - 51	Floor tile & mastic/Room C -Section 1D -Basement	720 sq. ft.
69 - 71	Mastic/ Light grey cove base -Offices #1-7, Open Room C, Hallway #9 & #10, Main Entrance Stairwell -2 nd floor	1,780 linear ft.

Communications (24 hours):

Office: (860) 449-8903

FAX: (860) 449-8860

Toll Free: 1 (800) 247-7746

website: www.mysticair.com

e-mail: maqc2@aol.com



Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

Sample #s	Material/Location	Estimated Affected Area
101	Pipe Insulation/Bottom of basement #2 stairs –pipe elbow behind wall	1 elbow
102–104	Flashing Tar/Interior -top of wall in open rooms –levels #1 & #2	50 sq. ft.
107–109	Glazing/Exterior Windows	25 windows
114–115	Silver Paint/Built-up roofing –Roof B	7,000 sq. ft.
119	Silver Paint/Built-up roofing –Roof A	10,000 sq. ft.
120–122	Tar-Silver Paint/Siding of Tower –Roof A	250 sq. ft.
126–128	Flashing/All Roofs –around penetrations, seams, edges, bottom of ducts & on rolled roofing	1,000 sq. ft.

Special Considerations

Any of the non-asbestos roofing materials with flashing, roof tar or silver paint attached will need to be treated as asbestos-contaminated and be cut out with it when abated.

Non-asbestos containing materials

The roster of suspect materials (Enclosure 3), lists the materials tested. Those that are not already referred to as asbestos containing or assumed asbestos, can be categorized as non-asbestos containing materials. See *Enclosure 1 for asbestos lab results, Enclosure 2 for chain of custody, Enclosure 4 for inspector's diagram, Enclosure 5 for TCLP results and chain of custody.*

Implications of the findings

As required by state and federal regulations prior to renovation or demolition, any asbestos-containing materials listed above that could be disturbed by a renovation, will need to be removed by a licensed asbestos abatement contractor employing trained and certified personnel who follow all pertinent asbestos abatement regulations.

Limitations of the Asbestos survey

This survey and report only deal with accessible areas of the building. Additionally, there may be other non-accessible materials above ceilings, behind walls, and below floors that become evident during your renovation activity. Should the requisite EPA/OSHA competent person working for the contractor discover such materials they will need to be tested for asbestos content so determinations of their abatement and disposal (if required) can be made.

TCLP Analysis results

The results of the TCLP analyses indicate that the building materials subsequent to demolition do not need to be disposed of as lead waste. The sample results were below the EPA's TCLP standard of 5 mg/l for lead.

Please do not hesitate to contact us with questions relating to the sample results. We thank you for the opportunity to conduct this survey.

Sincerely,

Christopher J. Eident CIH, CSP, RS
CEO

Communications (24 hours): _____

Office: (860) 449-8903

FAX: (860) 449-8860

Toll Free: 1 (800) 247-7746

website: www.mysticair.com

e-mail: maq2@aol.com

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

7469 WHITE PINE ROAD - RICHMOND, VA 23237

804-275-4788 FAX 804-275-4907

BULK ASBESTOS SAMPLE ANALYSIS SUMMARY

CLIENT: Mystic Air Quality Consultants
1204 North Road, Rt. 117
Groton, CT 06340

DATE OF RECEIPT: 29 May 2009
DATE OF ANALYSIS: 30 May 2009
DATE OF REPORT: 01 Jun 2009

CLIENT NUMBER: 7-2564 SB
EHS PROJECT #: 2009-05-1357
PROJECT: 429 Marlborough Rd.; Main Office Bldg.; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
01A	1 (a)-Cove Base/ Gray Vinyl	NAD	100% Non-Fibrous
01B	1 (b)-Mastic/ Tan/Yellow/Brown Adhes.	Trace, <1% Chrysotile <1% Total Asbestos	2% Cellulose 98% Non-Fibrous
02A	2 (a)-Cove Base/ Gray Vinyl	NAD	100% Non-Fibrous
02B	2 (b)-Mastic/ Tan/Yellow Adhes.	NAD	3% Cellulose 97% Non-Fibrous
03A	3 (a)-Cove Base/ Gray Vinyl	NAD	100% Non-Fibrous
03B	3 (b)-Mastic/ Tan/Yellow/Brown Adhes.	Trace, <1% Chrysotile <1% Total Asbestos	3% Cellulose 97% Non-Fibrous
04A	4 (a)-Tile/ Tan Vinyl	NAD	100% Non-Fibrous
04B	4 (b)-Mastic/ Black Tar-Like	3% Chrysotile 3% Total Asbestos	5% Cellulose 92% Non-Fibrous
05A	5 (a)-Tile/ Tan Vinyl	NAD	100% Non-Fibrous
05B	5 (b)-Mastic/	DID NOT ANALYZE	
06A	6 (a)-Tile/ Tan Vinyl	NAD	100% Non-Fibrous
06B	6 (b)-Mastic/	DID NOT ANALYZE	
07A	7 (a)-Tile/ Green Vinyl	4% Chrysotile 4% Total Asbestos	96% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-1357

PROJECT: 429 Marlborough Rd.; Main Office Bldg.; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
07B	7 (b)-Mastic/ Black Tar-Like	6% Chrysotile 6% Total Asbestos	3% Cellulose 91% Non-Fibrous
08	8/	DID NOT ANALYZE	
09	9/	DID NOT ANALYZE	
10A	10 (a)-Tile/ Brown Vinyl	4% Chrysotile 4% Total Asbestos	96% Non-Fibrous
10B	10 (b)-Mastic/ Black Tar-Like	5% Chrysotile 5% Total Asbestos	4% Cellulose 91% Non-Fibrous
11	11/	DID NOT ANALYZE	
12	12/	DID NOT ANALYZE	
13A	13 (a)-Tile/ Tan Vinyl	5% Chrysotile 5% Total Asbestos	95% Non-Fibrous
13B	13 (b)-Mastic/ Black Tar-Like	NAD	2% Cellulose 98% Non-Fibrous
14A	14 (a)-Tile/	DID NOT ANALYZE	
14B	14 (b)-Mastic/ Black Tar-Like	NAD	2% Cellulose 98% Non-Fibrous
15A	15 (a)-Tile/	DID NOT ANALYZE	
15B	15 (b)-Mastic/ Black Tar-Like	NAD	2% Cellulose 98% Non-Fibrous
16	16/ Tan Vinyl; Gray Fib.	20% Chrysotile 20% Total Asbestos	20% Cellulose 60% Non-Fibrous
17	17/	DID NOT ANALYZE	
18	18/	DID NOT ANALYZE	
19	19/ Brown Fib.	NAD	60% Cellulose 10% Fibrous Glass 30% Non-Fibrous
20	20/ Brown Fib.	NAD	60% Cellulose 10% Fibrous Glass 30% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-1357

PROJECT: 429 Marlborough Rd.; Main Office Bldg.; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
21	21/ Brown Fib.	NAD	60% Cellulose 10% Non-Fibrous 30% Non-Fibrous
22A	22 (a)-Tile/ Tan Vinyl	4% Chrysotile 4% Total Asbestos	96% Non-Fibrous
22B	22 (b)-Mastic/ Yellow Adhes.	NAD	2% Cellulose 98% Non-Fibrous
23A	23 (a)-Tile/	DID NOT ANALYZE	
23B	23 (b)-Mastic/ Yellow Adhes.	NAD	2% Cellulose 98% Non-Fibrous
24A	24 (a)-Tile/	DID NOT ANALYZE	
24B	24 (b)-Mastic/ Yellow Adhes.	NAD	2% Cellulose 98% Non-Fibrous
25A	25 (a)-Tile/ Tan Vinyl	5% Chrysotile 5% Total Asbestos	95% Non-Fibrous
25B	25 (b)-Mastic/ Black Tar-Like	6% Chrysotile 6% Total Asbestos	3% Cellulose 91% Non-Fibrous
26	26/	DID NOT ANALYZE	
27	27/	DID NOT ANALYZE	
28A	28 (a)-Tile/ Yellow Vinyl	4% Chrysotile 4% Total Asbestos	96% Non-Fibrous
28B	28 (b)-Mastic/ Black Tar-Like	NAD	2% Cellulose 98% Non-Fibrous
29A	29 (a)-Tile/	DID NOT ANALYZE	
29B	29 (b)-Mastic/ Black Tar-Like	NAD	2% Cellulose 98% Non-Fibrous
30A	30 (a)-Tile/	DID NOT ANALYZE	
30B	30 (b)-Mastic/ Black Tar-Like	NAD	2% Cellulose 98% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-1357

PROJECT: 429 Marlborough Rd.; Main Office Bldg.; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE # LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
31A	31 (a)-Tile/ Beige Vinyl	NAD	100% Non-Fibrous
31B	31 (b)-Mastic/ Yellow Adhes.	NAD	100% Non-Fibrous
32A	32 (a)-Tile/ Beige Vinyl	NAD	100% Non-Fibrous
32B	32 (b)-Mastic/ Yellow Adhes.	NAD	100% Non-Fibrous
33A	33 (a)-Tile/ Beige Vinyl	NAD	100% Non-Fibrous
33B	33 (b)-Mastic/ Yellow Adhes.	NAD	100% Non-Fibrous
34A	34 (a)-Tile/ Beige Vinyl	NAD	100% Non-Fibrous
34B	34 (b)-Mastic/ Yellow Adhes.	NAD	2% Cellulose 98% Non-Fibrous
35A	35 (a)-Tile/ Beige Vinyl	NAD	100% Non-Fibrous
35B	35 (b)-Mastic/ Yellow Adhes.	NAD	2% Cellulose 98% Non-Fibrous
36A	36 (a)-Tile/ Beige Vinyl	NAD	100% Non-Fibrous
36B	36 (b)-Mastic/ Yellow Adhes.	NAD	2% Cellulose 98% Non-Fibrous
37A	37 (a)-Tile/ Brown Vinyl	2% Chrysotile 2% Total Asbestos	98% Non-Fibrous
37B	37 (b)-Mastic/ Yellow Adhes.	NAD	2% Cellulose 98% Non-Fibrous
38A	38 (a)-Tile/	DID NOT ANALYZE	
38B	38 (b)-Mastic/ Yellow Adhes.	NAD	2% Cellulose 98% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-1357

PROJECT: 429 Marlborough Rd.; Main Office Bldg.; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
39A	39 (a)-Tile/	DID NOT ANALYZE	
39B	39 (b)-Mastic/ Yellow Adhes.	NAD	3% Cellulose 97% Non-Fibrous
40A	40 (a)-Linoleum/ Brown Vinyl; White Fib.	25% Chrysotile 25% Total Asbestos	30% Cellulose 45% Non-Fibrous
40B	40 (b)-Mastic/ Yellow Adhes.	2% Chrysotile ★ 2% Total Asbestos ★Possible contamination from fibrous backing.	2% Cellulose 96% Non-Fibrous
41A	41 (a)-Linoleum/	DID NOT ANALYZE	
41B	41 (b)-Mastic/	DID NOT ANALYZE	
42A	42 (a)-Linoleum/	DID NOT ANALYZE	
42B	42 (b)-Mastic/	DID NOT ANALYZE	
43	43/ Gray Cementitious; Fib.	20% Chrysotile 20% Total Asbestos	80% Non-Fibrous
44	44/	DID NOT ANALYZE	
45	45/	DID NOT ANALYZE	
46A	46 (a)-Tile/ Brown Vinyl	4% Chrysotile 4% Total Asbestos	96% Non-Fibrous
46B	46 (b)-Mastic/ Black Adhes.	NAD	2% Cellulose 98% Non-Fibrous
47A	47 (a)-Tile/	DID NOT ANALYZE	
47B	47 (b)-Mastic/ Black Adhes.	NAD	2% Cellulose 98% Non-Fibrous
48A	48 (a)-Tile/	DID NOT ANALYZE	
48B	48 (b)-Mastic/ Black Adhes.	NAD	2% Cellulose 98% Non-Fibrous
49A	49 (a)-Tile/ Gray Vinyl	4% Chrysotile 4% Total Asbestos	96% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-1357

PROJECT: 429 Marlborough Rd.; Main Office Bldg.; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
49B	49 (b)-Mastic/ Black Adhes.	2% Chrysotile 2% Total Asbestos	98% Non-Fibrous
50A	50 (a)-Tile/	DID NOT ANALYZE	
50B	50 (b)-Mastic/	DID NOT ANALYZE	
51A	51 (a)-Tile/	DID NOT ANALYZE	
51B	51 (b)-Mastic/	DID NOT ANALYZE	
52	52/ White Powder; Brown Fib.	NAD	30% Cellulose 70% Non-Fibrous
53	53/ Brown Powder	NAD	6% Cellulose 94% Non-Fibrous
54	54/ Gray Powder; Brown Fib.	NAD	30% Cellulose 70% Non-Fibrous
55	55/ Gray Powder; Brown Fib.	NAD	30% Cellulose 70% Non-Fibrous
56	56/ Gray Powder; Brown Fib.	NAD	30% Cellulose 70% Non-Fibrous
57	57/ Gray Powder; Brown Fib.	NAD	30% Cellulose 70% Non-Fibrous
58	58/ Gray Powder; Brown Fib.	NAD	30% Cellulose 70% Non-Fibrous
59	59/ Gray Powder; Brown Fib.	NAD	30% Cellulose 70% Non-Fibrous
60	60/ Gray Powder; Brown Fib.	NAD	30% Cellulose 70% Non-Fibrous
61	61/ Gray Powder; Brown Fib.	NAD	30% Cellulose 70% Non-Fibrous
62	62/ Gray Powder; Brown Fib.	NAD	30% Cellulose 70% Non-Fibrous
63	63/ Gray Powder; Brown Fib.	NAD	30% Cellulose 70% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-1357

PROJECT: 429 Marlborough Rd.; Main Office Bldg.; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
64	64/ Gray Powder; Brown Fib.	NAD	30% Cellulose 70% Non-Fibrous
65	65/ Gray Powder; Brown Fib.	NAD	30% Cellulose 70% Non-Fibrous
66A	66 (a)-Cove Base/ Brown Vinyl	NAD	100% Non-Fibrous
66B	66 (b)-Mastic/ Yellow Adhes.	NAD	2% Cellulose 98% Non-Fibrous
67A	67 (a)-Cove Base/ Brown Vinyl	NAD	100% Non-Fibrous
67B	67 (b)-Mastic/ Yellow Adhes.	NAD	100% Non-Fibrous
68A	68 (a)-Cove Base/ Brown Vinyl	NAD	100% Non-Fibrous
68B	68 (b)-Mastic/ Yellow Adhes.	NAD	100% Non-Fibrous
69A	69 (a)-Cove Base/ Gray Vinyl	NAD	100% Non-Fibrous
69B	69 (b)-Mastic/ Brown/Yellow Adhes.	NAD	2% Cellulose 98% Non-Fibrous
70A	70 (a)-Cove Base/ Gray Vinyl	NAD	100% Non-Fibrous
70B	70 (b)-Mastic/ Brown/Yellow Adhes.	2% Chrysotile 2% Total Asbestos	2% Cellulose 96% Non-Fibrous
71A	71 (a)-Cove Base/ Gray Vinyl	NAD	100% Non-Fibrous
71B	71 (b)-Mastic/	DID NOT ANALYZE	
72	72/ Brown Brittle; Adhes.	NAD	2% Cellulose 98% Non-Fibrous
73	73/ Brown Brittle; Adhes.	NAD	2% Cellulose 98% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-1357

PROJECT: 429 Marlborough Rd.; Main Office Bldg.; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
74	74/ Brown Brittle; Adhes.	NAD	2% Cellulose 98% Non-Fibrous
75	75/ Beige/White Fib.	NAD	30% Cellulose 55% Fibrous Glass 15% Non-Fibrous
76	76/ Beige/White Fib.	NAD	30% Cellulose 55% Fibrous Glass 15% Non-Fibrous
77	77/ Beige/White Fib.	NAD	30% Cellulose 55% Fibrous Glass 15% Non-Fibrous
78	78/ White Fib.	NAD	85% Fibrous Glass 15% Non-Fibrous
79	79/ White Fib.	NAD	85% Fibrous Glass 15% Non-Fibrous
80	80/ White Fib.	NAD	85% Fibrous Glass 15% Non-Fibrous
81A	81 (a)-Cove Base/ Brown Vinyl	NAD	100% Non-Fibrous
81B	81 (b)-Mastic/ Yellow Adhes.	NAD	100% Non-Fibrous
82A	82 (a)-Cove Base/ Brown Vinyl	NAD	100% Non-Fibrous
82B	82 (b)-Mastic/ Yellow Adhes.	NAD	100% Non-Fibrous
83A	83 (a)-Cove Base/ Brown Vinyl	NAD	100% Non-Fibrous
83B	83 (b)-Mastic/ Yellow Adhes.	NAD	100% Non-Fibrous
84	84/ White Chalky; Brown Fib.	NAD	10% Cellulose 5% Fibrous Glass 85% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-1357

PROJECT: 429 Marlborough Rd.; Main Office Bldg.; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
85	85/ White Chalky; Brown Fib.	NAD	10% Cellulose 5% Fibrous Glass 85% Non-Fibrous
86	86/ White Chalky; Brown Fib.	NAD	10% Cellulose 5% Fibrous Glass 85% Non-Fibrous
87	87/ Gray Gran.	NAD	100% Non-Fibrous
88	88/ Gray Gran.	NAD	100% Non-Fibrous
89	89/ Gray Powder; Gray Fib.	NAD	45% Cellulose 55% Non-Fibrous
90	90/ Gray Powder; Gray Fib.	NAD	45% Cellulose 55% Non-Fibrous
91	91/ Gray Powder; Gray Fib.	NAD	45% Cellulose 55% Non-Fibrous
92A	92 (a)-Cove Base/ Brown Vinyl	NAD	100% Non-Fibrous
92B	92 (b)-Mastic/ Yellow Adhes.	NAD	2% Cellulose 98% Non-Fibrous
93A	93 (a)-Cove Base/ Brown Vinyl	NAD	100% Non-Fibrous
93B	93 (b)-Mastic/ Yellow Adhes.	NAD	2% Cellulose 98% Non-Fibrous
94A	94 (a)-Cove Base/ Brown Vinyl	NAD	100% Non-Fibrous
94B	94 (b)-Mastic/ Yellow Adhes.	NAD	2% Cellulose 98% Non-Fibrous
95A	95 (a)-Cove Base/ Black Vinyl	NAD	100% Non-Fibrous
95B	95 (b)-Mastic/ Yellow Adhes.	NAD	100% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-1357

PROJECT: 429 Marlborough Rd.; Main Office Bldg.; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
96A	96 (a)-Cove Base/ Black Vinyl	NAD	100% Non-Fibrous
96B	96 (b)-Mastic/ Yellow Adhes.	NAD	100% Non-Fibrous
97A	97 (a)-Cove Base/ Black Vinyl	NAD	100% Non-Fibrous
97B	97 (b)-Mastic/ Yellow Adhes.	NAD	100% Non-Fibrous
98	98/ Gray Gran.	NAD	100% Non-Fibrous
99	99/ Gray Gran.	NAD	100% Non-Fibrous
100	100/ Gray Gran.	NAD	100% Non-Fibrous
101	101/ Gray Fib.	60% Chrysotile 60% Total Asbestos	40% Non-Fibrous
102	102/ Black Tar-Like	10% Chrysotile 10% Total Asbestos	5% Cellulose 85% Non-Fibrous
103	103/	DID NOT ANALYZE	
104	104/	DID NOT ANALYZE	
105	105/ White Pliable	NAD	100% Non-Fibrous
106	106/ White Pliable	NAD	2% Cellulose 98% Non-Fibrous
107	107/ Beige Gran.	2% Chrysotile 2% Total Asbestos	98% Non-Fibrous
108	108/	DID NOT ANALYZE	
109	109/	DID NOT ANALYZE	
110	110/ White Pliable	NAD	100% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-1357

PROJECT: 429 Marlborough Rd.; Main Office Bldg.; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
111	111/ White Pliable	NAD	100% Non-Fibrous
112	112/ White Pliable	NAD	100% Non-Fibrous
113	113/ Black Tar-Like	Trace, <1% Chrysotile <1% Total Asbestos	20% Cellulose 10% Fibrous Glass 70% Non-Fibrous
114	114/ Black Tar-Like; Silver Paint-Like	Trace, <1% Chrysotile ★ <1% Total Asbestos ★Trace, chrysotile present in tar-like material and 2% chrysotile present in silver paint alone.	30% Cellulose 10% Fibrous Glass 60% Non-Fibrous
115	115/ Black Tar-Like; Silver Paint-Like	Trace, <1% Chrysotile ★ <1% Total Asbestos ★3% chrysotile present in silver paint-like material.	30% Cellulose 10% Fibrous Glass 60% Non-Fibrous
116	116/ Black Tar-Like	NAD	20% Fibrous Glass 80% Non-Fibrous
117	117/ Black Tar-Like	NAD	25% Cellulose 75% Non-Fibrous
118	118/ Black Tar-Like; Silver Paint	NAD	25% Cellulose 5% Fibrous Glass 70% Non-Fibrous
119	119/ Black Tar-Like; Silver Paint	Trace, <1% Chrysotile ★ <1% Total Asbestos ★2% chrysotile present in silver paint-like material.	20% Cellulose 10% Fibrous Glass 70% Non-Fibrous
120	120/ White Paint-Like; Black Tar-Like; Silver Paint	7% Chrysotile ★ 7% Total Asbestos ★Present in tar material on bottom layer and silver paint.	33% Cellulose 60% Non-Fibrous
121	121/	DID NOT ANALYZE	
122	122/	DID NOT ANALYZE	
123	123/ Silver Foil; Black Tar-Like	NAD	100% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-1357

PROJECT: 429 Marlborough Rd.; Main Office Bldg.; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
124	124/ Silver Foil; Black Tar-Like	NAD	100% Non-Fibrous
125	125/ Silver Foil; Black Tar-Like	NAD	100% Non-Fibrous
126	126/ Black Tar-Like	8% Chrysotile 8% Total Asbestos	22% Cellulose 20% Fibrous Glass 50% Non-Fibrous
127	127/	DID NOT ANALYZE	
128	128/	DID NOT ANALYZE	
129	129/ White Fib.; Black Tar-Like	NAD	30% Fibrous Glass 70% Non-Fibrous
130	130/ White Fib.; Black Tar-Like	NAD	35% Fibrous Glass 65% Non-Fibrous
131	131/ White Fib.; Black Tar-Like	NAD	30% Fibrous Glass 70% Non-Fibrous
132	132/ Tan/White Rubbery	NAD	100% Non-Fibrous
133	133/ Tan/White Rubbery	NAD	100% Non-Fibrous
134	134/ Tan/White Rubbery	NAD	100% Non-Fibrous
135	135/ Gray Rubbery	NAD	100% Non-Fibrous
136	136/ Gray Rubbery	NAD	100% Non-Fibrous
137	137/ Gray Rubbery	NAD	100% Non-Fibrous
138	138/ White Foam; Beige/Gray Gran.	NAD	25% Fibrous Glass 75% Non-Fibrous
139	139/ White Foam; Beige/Gray Gran.	NAD	30% Fibrous Glass 70% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB
 EHS PROJECT #: 2009-05-1357
 PROJECT: 429 Marlborough Rd.; Main Office Bldg.; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE # LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
140	140/ White Fib.; Beige/Gray Gran.	NAD	35% Fibrous Glass 65% Non-Fibrous

QC SAMPLE: M1-1999-2
 M1-1991-1
 M21995-2

QC BLANK: SRM 1866 Fiberglass

REPORTING LIMIT: 1% Asbestos

METHOD: Polarized Light Microscopy, EPA Method 600/R-93/116 *

ANALYST: Christian H. Schaible
 Kathy Sizemore
 Sami Hosn

Reviewed By Authorized Signatory: _____


 Howard Varner, General Manager
 Irma Faszewski, Quality Assurance Coordinator

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C. California Certification #2319 NY ELAP #11714. All information concerning sampling location, date, and time can be found on Chain-of-Custody. Environmental Hazards Services, L.L.C. does not perform any sample collection.

Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), for enhanced detection capabilities) for materials regulated by the EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

* All California samples analyzed by Polarized Light Microscopy, EPA Method 600/M4-82-020, Dec. 1982.

LEGEND NAD = no asbestos detected
 SCF = suspected ceramic fibers

plm1.dot/05AUG2008/REV3/pd

-- PAGE 13 of 13 -- END OF REPORT --

EHS 2009-05-1357 / IRONMENTAL HAZARDS SERVICES, L.L.C.
 rd. Richmond, Virginia 23237 Phone: (804) 276-4788 Fax: (804) 276-4907

CHAIN OF CUSTODY FORM

(40 pm)

Company Name: Mystic Air Quality Consultants Date: 5/27/09
 Address: 1204 North Road Contact Name: CHRIS GEDANS
Groton, CT 06340 Sampler Name: CHRIS GEDANS
 City, State, Zip: Groton, CT 06340 Project #: 429-Marketway Rd - maintenance Bldg
 EHS Client Account #: 7-2564 B Fax #: 860-449-8860
 Phone #: 860-449-8903 Client: TRIZAL
 P.O. #: TRIZAL

Sample Number	Sample Date & Time	Asbestos				Lead				Other Metals (Specify metals below)				Indoor Air Quality				Particulate: Total Nuisance (NIOSH 0500) Respirable (NIOSH 0600)	Comments
		Bulk ID by PLM	PLM Fiber Count	PLM Gravimetric	PLM Point Count	Soil	Wipe* (See Note)	TCLP (Pb)	Waste Water	TCLP PCRA 8	Welding Fume	Toxic Metal Profile	Bioassette	Slide	Surface Swab	Surface Tape	Biok		
1-3	5/27/09	X																Coverseal - Glue Floor tile - mastic (x)	
4-6																		" " " - (9x9)	
7-9																		" " " - (9x9)	
10-12																		" " " - (9x9)	
13-15																		LINOLEUM	
16-18																		Ceiling Tiles (x4)	
19-21																		Floor tile - yellow - (9x9)	
22-24																		Floor tile - blue - (9x9)	
25-27																		" " " "	
28-30																		" " " "	

* Do wipe samples submitted meet ASTM E1792 requirements? Yes No

Signature: B. Woodward Date/Time: 5/27/09
 Signature: H. S. S. S. Date/Time: 5-29-09 10a
 Signature: H. S. S. S. Date/Time:

★ POSITIVE STOP ★

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.
7469 Whitepine Road, Richmond, Virginia 23237 Phone (804) 275-4788 Fax (804) 275-4907

CHAIN OF CUSTODY FORM

Company Name: Mystic Air Quality Consultants Date: 5/27/09
 Address: 1204 North Road Contact Name: CHRIS EDDEN
 City, State, Zip: Groton, CT 06340 Sampler Name: CHRIS EDDEN
 EHS Client Account #: 7-2564 B Project #: 429-Northborough Rd - main office Bldg
 Phone #: 860-449-8903 Fax #: 860-449-8860 GLASBOROUGH, CT
 P.O. #: TRETON

Sample Number	Sample Date & Time	Asbestos				Lead				Other Metals (Specify metals below)				Indoor Air Quality				Particulate: Total Nuisance (NIOSH 0500) Respirable (NIOSH 0600)	Comments	
		Bulk ID by PLM	(PCM) Fiber Count	PLM Point Count	PLM Gravimetric	Waste Water	Soil	Paint (PPM)	Paint (mg/cm ²)	Wipe * (See Note)	TCLP (Pb)	TCLP RCRA 8	Welding Fume	Toxic Metal Profile	Bioaerosol	Slide	Surface Swab			Surface Tape
31-33	5/27/09	X																	Bulks	Yellow
34-36																				11
37-39																				11
40-42																				11
43-45																				11
46-48																				11
49-51																				11
52-58																				11
59-65																				11
66-68																				11

Do Wipe samples submitted meet ASTM E1792 requirements? Yes No

Released by: B. Woodward Signature: B. Woodward Date/Time: 5/27/09
 Received by: K. Sigman Signature: K. Sigman Date/Time: 5-29-09 10:20

★ POSITIVE STOP ★

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.
7469 Whitepine Road, Richmond, Virginia 23237 Phone (804) 275-4788 Fax (804) 275-4907

CHAIN OF CUSTODY FORM

Company Name: Mystic Air Quality Consultants Date: 5/27/09
 Address: 1204 North Road Contact Name: CHRIS EXPERT
Groton, CT 06340 Sampler Name: CHRIS EXPERT
 City, State, Zip: Project #: 429-Marchwood Rd - main office Bldg
Glastonbury, CT
 EHS Client Account #: 7-2564 B Fax #: 860-449-8860
 Phone #: 860-449-8903

Client: TRITON

Sample Number	Sample Date & Time	Asbestos				Lead				Other Metals (Specify metals below)			Indoor Air Quality				Comments		
		Bulk ID by P/M	(PCM) Fiber Count	P/M Point Count	P/M Gravimetric	Soil	Paint (mg/cm ²)	Paint (PPM)	Paint (%)	Waste Water	TCLP RCRA 8	Welding Fume	Toxic Metal Profile	Bioassette	Slide	Surface Swab		Surface Tape	Bulk
95-97	5/27/09	X																	Concrete - Glue
98-100																			Plaster Ceiling
101																			PIPE INSULATION
102-104																			FLASHING
105																			GLAZING
106																			Caulking
107-109																			GLAZING
110-112																			Caulking
113																			Builtup Roofing
114																			" "

Date/Time: 5/27/09
 Date/Time: 5-29-09
 Date/Time: 11/09

Signature: B. Woodard
 Signature: WOM
 Signature: _____

* Do Wipe samples submitted meet ASTM E1792 requirements? Yes No
 Released by: B. Woodard
 Received by: R. D. GEMMEL

★ POSITIVE STOP ★

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.
7468 Whitepine Road, Richmond, Virginia 23237 Phone (804) 275-4788 Fax (804) 275-4907

CHAIN OF CUSTODY FORM

Company Name: Mystic Air Quality Consultants

Address: 1204 North Road

City, State, Zip: Groton, CT 06340

EHS Client Account #: 7-2564 B

Phone #: 860-449-8903

Fax #: 860-449-8860

Date: 5/27/09

Contact Name: CHRIS EDDART

Sampler Name: CHRIS EDDART

Project #: 429-Market Street Rd - maintenance Bldg

Glastonbury, CT


Client: TREXCO

Sample Number	Sample Date & Time	Asbestos				Lead				Other Metals (Specify metals below)				Indoor Air Quality				Particulate: Total Nuisance (NIOSH 0500) Respirable (NIOSH 0600)	Comments					
		Bulk ID by PLM	(PCM) Fiber Count	PLM Point Count	PLM Gravimetric	PLM Gravimetric	PLM Point Count	Paint (%)	Paint (PPM)	Paint (mg/cm ²)	Soil	Wine* (See Note)	TCLP (Pb)	Waste Water	TCLP RCRA 8	Welding Fume	Toxic Metal Profile			Bioassess	Slide	Surface Swab	Surface Tape	Bulk
115	5/27/09	X																						Built up Roofing
116																								" "
117																								" "
118																								" "
119																								" "
120-121																								SIDING
123-125																								ROOFING
126-128																								FLASHING
129-131																								DUCT WRAP
132-134																								Expansion Joint Caulk

Date/Time: 5/27/09
Date/Time: 5-29-09
Date/Time:
Date/Time:

Signature: B. Woodward
Signature: [Signature]
Signature: [Signature]

* Do wipe samples submitted meet ASTM E1792 requirements? Yes No



Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

Asbestos Containing Suspect Materials Roster

Site: 429 Marlborough Rd - main office Bldg
Glastonbury, CT

Demo

Sample
Numbers

Type Of Material	Amount of Material	Condition of Material	Specific Location of Suspect ACM at Site
1-3 Cover Base - Glue	2250 LNFT	DAMAGED	See attached
4-6 Floor tile - ^{Black} mastic (ixi)	5200 FT ²	White	
7-9 " " - (9x9)	2050 FT ²	Green	
10-12 " " - (9x9)	345 FT ²	Red	
13-15 " " - (9x9)	820 FT ²	TAN	
16-18 LINDOLEUM	455 FT ²		
19-21 Ceiling Tiles (2x4)	25865 FT ²		
22-24 Floor tile - ^{Yellow} mastic (9x9)	140 FT ²	TAN	
25-27 Floor tile - ^{Black} mastic (9x9)	895 FT ²	White	
28-30 " " "	1610 FT ²	light TAN	
31-33 Floor tile - ^{Yellow} mastic - (ixi)	510 FT ²		
34-36 " " "	60 FT ²	X White	X

EPA considers the materials above as "suspect" asbestos-containing materials.

Date: 5/27/09

Inspector C. Fidal

Telecommunications (24 hours): _____

ENCLOSURE 3 PAGE 1 OF 7

Office: (203) 449-8903

CT Toll Free: 1 (800) 247-774



Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

Asbestos Containing Suspect Materials Roster

Site: 429 Marlborough Rd - main office Bldg
Glastonbury, CT

DEMO

Sample
Numbers

Type Of Material	Amount of Material	Condition of Material	Specific Location of Suspect ACM at Site	
37-39 Floor tile ^{Yellow} mastic	60 FT ²	Damaged TAN	See ATTACHED	
40-42 LINOLEUM	285 FT ²			
43-45 TRANSITE	2100 FT ²			
46-48 Floor tile ^{Black} mastic	220 FT ²			
49-51 " "	720 FT ²			
52-58 SheetRock-walls	-			
59-65 SheetRock-Ceilings	-			
66-68 Covebase-Glue	1225 LNFT			Brown
69-71 " "	1780 LNFT			Light Grey
72-74 Glue dobbs	-			
75-77 Ceiling Tiles-(2x1)	4250 FT ²			
78-80 " " ^{- (6x12)}	240 FT ²	X	X	

EPA considers the materials above as "suspect" asbestos-containing materials.

Date: 5/27/09


Inspector *C. J. J. J.*

Telecommunications (24 hours): _____

ENCLOSURE 3 PAGE 2 OF 7

Office: (203) 449-8903

CT Toll Free: 1 (800) 247-774



Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

Asbestos Containing Suspect Materials Roster

Site: 429 Marlborough Rd - main office Bldg.
Glastonbury, CT

Demo

Sample Numbers

81-83

84-86

87

88

* 89-91

92-94

95-97

98-100

101

102-104

105

106

Type Of Material	Amount of Material	Condition of Material	Specific Location of Suspect ACM at Site
Cove Base-Glue	675 LNFT	Damaged ^{light brown}	See ATTACHED
Sheetrock Ceiling Panels	900 FT ²		Kitchen, Kitchen Storage, Service Room Section 1 D- Basement
Flue Cement	6 FT ²		around Furnace Pipes- Furnace Room # 1
Caulking	2 Furnaces		Interior of Furnaces on Siding " "
Insulation	9 doors		Inside the Fire doors- Stairwell (A) and (B) Office # 33, Open Room (C), Office (V), Conference Room (B),
Cove Base-Glue	225 LNFT		margin End of Hallway # 9, Storage Room # 3, Landing (A)
" "	35 LNFT		Black OFFICE # 30- Basement # 2
Plaster Ceiling	1375 FT ²		OFFICE # 30 and Garage Bay
Pipe Insulation	1 Elbow		on pipe Elbow behind Wall- Bottom of Stairs- Basement # 2
Flashing	50 FT ²		Interior- Top of Wall in open Rooms Levels # 1 and # 2
Glazing	7 windows		Interior of windows, Stairs locker room open Room # 2
Caulking	1 window	X Interior of window- Workshop # 2	

EPA considers the materials above as "suspect" asbestos-containing materials.

Date: 5/27/09

Inspector C. J. J. J.

Telecommunications (24 hours): _____

ENCLOSURE 3 PAGE 3 OF 7

Office: (203) 449-8903

CT Toll Free: 1 (800) 247-7746

FAX: (203) 449-8900

NE Toll Free: 1 (800) 722-7746



Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

Asbestos Containing Suspect Materials Roster

Site: 429 Marlborough Rd - main Office Bldg.
Glastonbury, Ct

Demo

Sample
numbers

Sample numbers	Type Of Material	Amount of Material	Condition of Material	Specific Location of Suspect ACM at Site.
107109	Glazing	25 Windows	Damaged	Exterior of Windows
110-112	Caulking	14 Windows		" " "
113	Built up Roofing	1800 FT ²		See ROOF Diagram - ROOF (C)
114	" "	7000 FT ²		" " - ROOF (B)
115	" "	7000 FT ²		" " - " "
116	" "	1800 FT ²		" " - ROOF (E)
117	" "	6500 FT ²		" " - ROOF (D)
118	" "	1500 FT ²		" " - ROOF (F)
119	" "	10,000 FT ²		" " - ROOF (A)
120-122	Siding	250 FT ²		Siding of Tower - ROOF (A)
123-125	Roofing	1000 FT ²		ON Edge of ROOF (A)
126-128	Flashing	1,000 FT ²	X	ON All ROOFS, around penetrations, on Rolled roofing. ON SEAMS, ROOF FIELD, Edge of ROOFS, bottom of duct.

EPA considers the materials above as "suspect" asbestos-containing materials.

Date: 5/27/09

Inspector *C. Fidal*

Telecommunications (24 hours): _____

ENCLOSURE 3 PAGE 4 OF 7

Office: (203) 449-8903

CT Toll Free: 1 (800) 247-774



Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

Asbestos Containing Suspect Materials Roster

Site: 429 Marlborough Rd - main Office Bldg
Glastonbury, CT

Demo

Sample numbers

Type Of Material	Amount of Material	Condition of Material	Specific Location of Suspect ACM at Site
129-131 DUCT WRAP	500 FT	Damaged	around ducts on Roof & bottom of walls on Roof
132-134 Expansion Joint Caulk	2000 LWT	↓ Brown	In between Siding on Bldg
135-137 Caulking	92 windows		Exterior of windows - Newer windows
138-141 EFIS	-	↓	Siding of Bldg

EPA considers the materials above as "suspect" asbestos-containing materials.

Date: 5/27/09

Inspector C. Fidal

Telecommunications (24 hours): _____

ENCLOSURE 3 PAGE 5 OF 7

Office: (203) 449-8903

CT Toll Free: 1 (800) 247-7746

FAX: (203) 449-8860

NE Toll Free: 1 (800) 722-7746


5/27/09

429 Marlborough Rd - main office Bldg.
GLASTONBURY, CT

Sample Numbers	TYPE OF MATERIAL	LOCATION
1-3	Covebase-Glue	Hallway #1, Hallway #6, main Entrance Foyer, Room #12, Rooms A, B, #C, Conference Room A, part of Open Room A, KITCHEN, Kitchen Storage, Service Room, Foyer #2, Hallway #5 and Hallway #8
1-6	(White) Floor tile - Black mastic (ixi)	Top Layer in Lobby #1 and Room #2 and only Layer in Hallway #4, # Hallway #3 and its the bottom Layer under plywood in Room #3
7-9	(Green) Floor tile - Black mastic (9x9)	Bottom Layer in Lobby #1 and Room #2 and only Layer in offices #1, #2, #3, #4, #5, #6
10-12	(Red) " "	ONLY Layer in the Waiting Room and Office #7
13-15	(TAN) " "	ONLY Layer in Hallway #1
16-18	Linoleum	Top Layer in Room #3
19-21	Ceiling Tiles (2x4)	Throughout BLDG.
22-24	(TAN) Floor tile - Yellow mastic (9x9)	ONLY Layer in Office #10 and Office #11
25-27	(White) Floor tile - Black mastic (9x9)	ONLY Layer in Office #8, Office #26, Office #27, Office #28, and Office #29
28-30	(Light TAN) " "	Office #9 and Hallway #6
31-33	Yellow Floor tile - mastic (ixi)	Room #6, Locker Room, Panel Box Rooms #1 and #2, and Copy Rooms #1 and #2
34-36	(White) " "	Storage Room #3
37-39	(TAN) " "	" "

Sample Numbers	TYPE of material	Location
0-42	LINOLEUM	Room #4
3-45	TRANSITE	Wall and Ceiling Panels in Storage Room #4 and only Ceiling panels in Room #33
5-48	Flortile- ^{Black} mastic	ROOM B - Section 1 D - Basement
9-51	" "	Room C - " "
2-58	SHEETROCK- Walls	Throughout
9-65	SHEETROCK- Ceilings	" "
6-68 (Brown)	Cove Base- Glue	Lobby #1, Rooms #2, #3, #4, Sitower, Locker Room, Equipment Room, Hallway #3, & Entry way
9-71 (light Grey)	" "	Offices #1, #2, #3, #4, #5, #6, #7, open Room C, Hallway #10, most of Hallway #9, and main Entrance Stairwell - 2 nd Floor
72-74	Glue dobs	above 1x1 ceiling tiles in Hallway #6, OFFICES #8 and #9, Foyer in Main Entrance, OFFICES #24, #25, #26, #27, #28, #29, Rooms #6, #7, #8, #9, #10, #11, Hallway (A), Bathrooms #3 and #4, Bathroom (F), OFFICES O, P, Q, R, S, T, & U, Conference Room (B), and Hallway #9
75-77	Ceiling tiles - (1x1)	Office #8, End of Hallway #6, Bathrooms #3 and #4, Hallway (A), and Rooms #6, #7, #8, #9, #10, #11, and #12
78-80	Ceiling tiles - (18x18)	Room (A) and main Entrance Foyer.



449 Marlborough Rd - main office area
 5/25/09 1st Floor - Section 1A



FRONT

409 Marlborough Rd - main office Bldg.
Glastonbury, CT


ROOF DIAGRAM



- ROOF F = 1500 FT²
- ROOF E = NO Field Samples Taken
- ROOF A = 10,000 FT²
- ROOF C = 1800 FT²
- ROOF B = 7000 FT²
- ROOF D = 6500 FT²
- ROOF E = 1800 FT²

ROOF D


Section 1D - Basement



409 MacLearough Rd - Main Office 10-11-00
Glanumbury, CT

SECTION 1 - 2nd Floor


5/27/09




101 11th Vermont 150-1111-1111
Glastonbury, CT

The upper levels above the shops

5/27/09



Basement #2
409 Marlborough Rd - main office Bldg.
Glastonbury, CT



ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

7469 WHITE PINE ROAD - RICHMOND, VA 23237

804-275-4788 FAX 804-275-4907

TCLP (LEAD) ANALYSIS SUMMARY

CLIENT: Mystic Air Quality Consultants
1204 North Road, Rt. 117
Groton, CT 06340

DATE OF SAMPLING: 17 May 2009
DATE OF RECEIPT: 29 May 2009
DATE OF ANALYSIS: 03 Jun 2009
DATE OF REPORT: 03 Jun 2009

CLIENT NUMBER: 7-2564 SB
EHS PROJECT #: 2009-05-1358
PROJECT: 429 Marlborough Rd.; Main Office Bldg.; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE # LABORATORY GROSS DESCRIPTION	SAMPLE WEIGHT (g)	INITIAL pH	CONCENTRATION PPM (mg/L)
01	TCLP#1/ Building Debris	100	5.97	<0.50
02	TCLP#2/ Building Debris	100	5.95	1.0


QUALITY CONTROL DATA

BATCH#:	060809T-1
INCLUSIVE EHS SAMPLE NUMBERS:	01-02
Initial Calibration Verification (5.00ppm Pb)	100% Recovery
Continuing Calibration Verification 5 (5.00ppm Pb)	100% Recovery
Laboratory Control Standard	91.6% Recovery
Matrix Spike	116% Recovery
Duplicate Relative Percent Difference	10.2 RPD
Regulatory Limit	5.0mg/L
Reporting Limit	0.50mg/L
Method Detection Limit	0.060mg/L

METHOD: EPA SW846 1311/3010A/7420

ANALYST: Aubrey Simonds

Reviewed By Authorized Signatory:


Howard Varner, General Manager
Irma Faszewski, Quality Assurance Coordinator
David Xu, MS, Senior Chemist

Method EPA SW846 1311 recommends 100g for analysis.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume etc., was provided by the client. This report shall not be reproduced, except in full, without the written consent of Environmental Hazards Services, L.L.C. California Certification #2319 NY ELAP #11714

LEGEND g = gram ug = microgram ppm = parts per million
ml = milliliter Pb = lead mg/L = milligrams per liter

tc1ppb2.doi/AA220/05AUG2008/REV4/te

— PAGE 01 of 01 — END OF REPORT —

ENCLOSURE 5 PAGE 1 OF 2



Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

June 1, 2009

Mr. Frank Kehoe
Triton Environmental
385 Church Street, Suite 201
Guilford, Connecticut 06437

Re: **Pre-Demo/Renovation Asbestos Survey and TCLP Analysis (5/22/09)**
429 Marlborough Road; Glastonbury, Connecticut
Location: Laboratory Storage Building

Dear Mr. Kehoe:

As requested, Mystic Air Quality Consultants, Inc. conducted a survey of accessible materials prior to demolition at the location noted above. This survey was directed on May 22, 2009, by our State of Connecticut licensed asbestos inspector, Christopher Eident, (license # 000015) to determine the presence of asbestos-containing materials. The samples were analyzed at Environmental Hazards Services (NVLAP # 101882-0) in Virginia.

In addition to the asbestos survey, composites or TCLP samples were collected and analyzed for lead to determine if the demolition materials would have to be considered lead waste. The sample analysis was also done by Environmental Hazards Services.

Summary of the Asbestos Findings

Upon testing by polarized light microscopy, the following materials were found to be asbestos containing:

<u>Sample #s</u>	<u>Material/Location</u>	<u>Estimated Affected Area</u>
1 - 5	1x1 Floor tile mastic/Hallway #1, Main room #1, Room #2, Offices 1-4, mens & womens bathrooms	1,250 sq. ft.
12 - 14	Transite panels/Throughout building except bsmt & equipment storage	7,350 sq. ft.
32 - 34	Caulking/Exterior windows -Room #1	6 windows
51-53, 60-62	Tar-Silver Paint/Roofing-Flat roof	7,250 sq. ft.
54 - 56	Flashing/Around penetrations & on concrete wall -flat roof	50 sq. ft.
57 - 59	Roof Tar/Seams of rolled roofing & patching -flat roof	1,000 sq. ft.

Special Considerations

Any of the non-asbestos roofing materials with flashing, roof tar or silver paint attached will need to be treated as asbestos-contaminated and be cut out with it when abated.

Non-asbestos containing materials

The roster of suspect materials (Enclosure 3), lists the materials tested. Those that are not already referred to as asbestos containing or assumed asbestos, can be categorized as non-asbestos containing materials.

Communications (24 hours): _____

Office: (860) 449-8903

FAX: (860) 449-8860

Toll Free: 1 (800) 247-7746

website: www.mysticair.com

e-mail: maq2@aol.com



Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

Implications of the findings

As required by state and federal regulations prior to renovation or demolition, any asbestos-containing materials listed above that could be disturbed by a renovation, will need to be removed by a licensed asbestos abatement contractor employing trained and certified personnel who follow all pertinent asbestos abatement regulations.

Limitations of the Asbestos survey

This survey and report only deal with accessible areas of the building. Additionally, there may be other non-accessible materials above ceilings, behind walls, and below floors that become evident during your renovation activity. Should the requisite EPA/OSHA competent person working for the contractor discover such materials they will need to be tested for asbestos content so determinations of their abatement and disposal (if required) can be made.

TCLP Analysis results

The results of the TCLP analyses indicate that the building materials subsequent to demolition do not need to be disposed of as lead waste. The sample results were below the EPA's TCLP standard of 5 mg/l for lead.

Please do not hesitate to contact us with questions relating to the sample results. We thank you for the opportunity to conduct this survey.

Sincerely,

A handwritten signature in black ink, appearing to read "C. Eident".

Christopher J. Eident CIH, CSP, RS
CEO

- Enclosure 1: Laboratory Results
- Enclosure 2: Chain of Custody
- Enclosure 3: Roster of Suspect Materials
- Enclosure 4: Inspector's Diagram of Property
- Enclosure 5: TCLP Analysis and Chain of Custody

Communications (24 hours): _____

Office: (860) 449-8903

FAX: (860) 449-8860

Toll Free: 1 (800) 247-7746

website: www.mysticair.com

e-mail: maqc2@aol.com

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

7469 WHITE PINE ROAD - RICHMOND, VA 23237

804-275-4788 FAX 804-275-4907

BULK ASBESTOS SAMPLE ANALYSIS SUMMARY

CLIENT: Mystic Air Quality Consultants
1204 North Road, Rt. 117
Groton, CT 06340

DATE OF RECEIPT: 26 May 2009
DATE OF ANALYSIS: 26 May 2009
DATE OF REPORT: 27 May 2009

CLIENT NUMBER: 7-2564 SB
EHS PROJECT #: 2009-05-1157
PROJECT: 429 Marlborough Rd.; Laboratory Storage Bldg.; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
01A	1 (a)-Tile/ Light Gray Vinyl	NAD	100% Non-Fibrous
01B	1 (b)-Mastic/ Black Tar-Like	3% Chrysotile 3% Total Asbestos	2% Cellulose 95% Non-Fibrous
02A	2 (a)-Tile/ Light Gray Vinyl	NAD	100% Non-Fibrous
02B	2 (b)-Mastic/	DID NOT ANALYZE	
03A	3 (a)-Tile/ Light Gray Vinyl	NAD	100% Non-Fibrous
03B	3 (b)-Mastic/	DID NOT ANALYZE	
04A	4 (a)-Tile/ Light Gray Vinyl	NAD	100% Non-Fibrous
04B	4 (b)-Mastic/	DID NOT ANALYZE	
05A	5 (a)-Tile/ Light Gray Vinyl	NAD	100% Non-Fibrous
05B	5 (b)-Mastic/	DID NOT ANALYZE	
06A	6 (a)-Tile/ Light Gray Vinyl	NAD	100% Non-Fibrous
06B	6 (b)-Mastic/ Yellow Adhes.	NAD	100% Non-Fibrous
07A	7 (a)-Tile/ Light Gray Vinyl	NAD	100% Non-Fibrous
07B	7 (b)-Mastic/ Yellow Adhes.	NAD	100% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-1157

PROJECT: 429 Marlborough Rd.; Laboratory Storage Bldg.; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
08A	8 (a)-Tile/ Light Gray Vinyl	NAD	100% Non-Fibrous
08B	8 (b)-Mastic/ Yellow Adhes.	NAD	100% Non-Fibrous
09	9/ Beige Fib.; White Powder	NAD	30% Cellulose 40% Fibrous Glass 30% Non-Fibrous
10	10/ Beige Fib.; White Powder	NAD	30% Cellulose 40% Fibrous Glass 30% Non-Fibrous
11	11/ Beige Fib.; White Powder	NAD	30% Cellulose 40% Fibrous Glass 30% Non-Fibrous
12	12/ Gray Hard; Fib.	20% Chrysotile 20% Total Asbestos	5% Cellulose 75% Non-Fibrous
13	13/	DID NOT ANALYZE	
14	14/	DID NOT ANALYZE	
15A	15 (a)-Cove Base/ Gray Rubbery	NAD	100% Non-Fibrous
15B	15 (b)-Mastic/ Tan Adhes.	NAD	100% Non-Fibrous
16A	16 (a)-Cove Base/ Gray Rubbery	NAD	100% Non-Fibrous
16B	16 (b)-Mastic/ Tan Adhes.	NAD	100% Non-Fibrous
17A	17 (a)-Cove Base/ Gray Rubbery	NAD	100% Non-Fibrous
17B	17 (b)-Mastic/ Tan Adhes.	NAD	100% Non-Fibrous
18	18/ Off-White Powder; Tan Fib.	NAD	26% Cellulose 74% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-1157

PROJECT: 429 Marlborough Rd.; Laboratory Storage Bldg.; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
19	19/ Off-White Powder; Tan Fib.	NAD	25% Cellulose 75% Non-Fibrous
20	20/ Off-White Powder; Tan Fib.	NAD	26% Cellulose 74% Non-Fibrous
21	21/ Off-White Powder; Tan Fib.	NAD	28% Cellulose 72% Non-Fibrous
22	22/ Off-White Powder; Tan Fib.	NAD	28% Cellulose 72% Non-Fibrous
23	23/ Black Rubbery; Off-White Brittle	NAD	3% Talc 97% Non-Fibrous
24	24/ Black Rubbery; Off-White Brittle	NAD	3% Talc 97% Non-Fibrous
25	25/ Black Rubbery; Off-White Brittle	NAD	2% Talc 98% Non-Fibrous
26	26/ Black Fib.; Tar-Like; Tan Gran.	NAD	70% Cellulose 30% Non-Fibrous
27	27/ Black Fib.; Tar-Like; Tan Gran.	NAD	70% Cellulose 30% Non-Fibrous
28	28/ Black Fib.; Tar-Like; Tan Gran.	NAD	70% Cellulose 30% Non-Fibrous
29	29/ White Rubbery	NAD	100% Non-Fibrous
30	30/ White Rubbery	NAD	100% Non-Fibrous
31	31/ White Rubbery	NAD	100% Non-Fibrous
32	32/ Black Rubbery	2% Chrysotile 2% Total Asbestos	1% Talc 97% Non-Fibrous
33	33/	DID NOT ANALYZE	
34	34/	DID NOT ANALYZE	

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-1157

PROJECT: 429 Marlborough Rd.; Laboratory Storage Bldg.; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
35	35/ Silver Paint	NAD	2% Polyethylene 98% Non-Fibrous
36	36/ Silver Paint	NAD	100% Non-Fibrous
37	37/ Silver Paint	NAD	100% Non-Fibrous
38	38/ Gray Brittle	NAD	100% Non-Fibrous
39	39/ Gray Brittle	NAD	100% Non-Fibrous
40	40/ Gray Brittle	NAD	100% Non-Fibrous
41	41/ Gray Powder; Fib.; White Paint	NAD	1% Cellulose 40% Fibrous Glass 59% Non-Fibrous
42	42/ Black Tar-Like	NAD	25% Cellulose 75% Non-Fibrous
43	43/ Black Tar-Like	NAD	28% Fibrous Glass 72% Non-Fibrous
44	44/ Black Tar-Like	NAD	28% Fibrous Glass 72% Non-Fibrous
45	45/ Black Tar-Like	NAD	26% Cellulose 74% Non-Fibrous
46	46/ Black Tar-Like	NAD	26% Cellulose 74% Non-Fibrous
47	47/ Black Tar-Like	NAD	26% Cellulose 74% Non-Fibrous
48	48/ Black Fib.; Tar-Like	NAD	80% Cellulose 20% Non-Fibrous
49	49/ Black Fib.; Tar-Like	NAD	80% Cellulose 20% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-1157

PROJECT: 429 Marlborough Rd.; Laboratory Storage Bldg.; Glastonbury, CT


EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
50	50/ Black Fib.; Tar-Like	NAD	80% Cellulose 20% Non-Fibrous
51	51/ Black Tar-Like; Tan Fib.; Silver Paint	Trace, <1% Chrysotile ★ <1% Total Asbestos ★5% chrysotile present in silver paint.	10% Cellulose 20% Fibrous Glass 70% Non-Fibrous
52	52/ Black Tar-Like; Tan Fib.; Silver Paint	Trace, <1% Chrysotile ★ <1% Total Asbestos ★4% chrysotile present in silver paint.	12% Cellulose 20% Fibrous Glass 68% Non-Fibrous
53	53/ Black Tar-Like; Silver Paint	15% Chrysotile ★ 15% Total Asbestos ★Chrysotile present throughout sample.	15% Cellulose 70% Non-Fibrous
54	54/ Black Tar-Like	18% Chrysotile 18% Total Asbestos	82% Non-Fibrous
55	55/	DID NOT ANALYZE	
56	56/	DID NOT ANALYZE	
57	57/ Black Tar-Like; Silver Paint	Trace, <1% Chrysotile ★ <1% Total Asbestos ★4% chrysotile present in silver paint.	2% Wollastonite 98% Non-Fibrous
58	58/ Black Tar-Like; Silver Paint	Trace, <1% Chrysotile ★ <1% Total Asbestos ★4% chrysotile present in silver paint.	2% Wollastonite 98% Non-Fibrous
59	59/ Black Tar-Like; Silver Paint	Trace, <1% Chrysotile ★ <1% Total Asbestos ★4% chrysotile present in silver paint.	2% Wollastonite 98% Non-Fibrous
60	60/ Silver Paint	5% Chrysotile 5% Total Asbestos	95% Non-Fibrous
61	61/	DID NOT ANALYZE	
62	62/	DID NOT ANALYZE	

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB
EHS PROJECT #: 2009-05-1157
PROJECT: 429 Marlborough Rd.; Laboratory Storage Bldg.; Glastonbury, CT

QC SAMPLE: NIST REF
QC BLANK: SRM 1866 Fiberglass
REPORTING LIMIT: 1% Asbestos
METHOD: Polarized Light Microscopy, EPA Method 600/R-93/116 *
ANALYST: Vickie Holmes

Reviewed By Authorized Signatory:



Howard Varner, General Manager

Irma Paszewski, Quality Assurance Coordinator

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C. California Certification #2319 NY ELAP #11714. All information concerning sampling location, date, and time can be found on Chain-of-Custody. Environmental Hazards Services, L.L.C. does not perform any sample collection.

Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), for enhanced detection capabilities) for materials regulated by the EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

* All California samples analyzed by Polarized Light Microscopy, EPA Method 600/M4-82-020, Dec. 1982.

LEGEND NAD = no asbestos detected
 SCF = suspected ceramic fibers

plm1.dot/05AUG2008/REV3/pd

-- PAGE 06 of 06 -- END OF REPORT --

ENCLOSURE / PAGE 6 OF 6

CHAIN OF CUSTODY FORM

EHS 2009-05-1157

Mystic Air Quality Consultants

1204 North Road

Groton, CT 06340

7-2564 B

860-449-8903

Fax #:

860-449-8860

Date: 5/20/09

Contact Name: CHRIS EPPERT

Sampler Name: CHRIS EPPERT

Project #:

860-449-8860

Client:

499 Marlborough Rd - Lebanon
Glastonbury, CT

☆ Positive Stop ☆

Sample Number	Sample Date & Time	Asbestos						Lead						Other Metals						Air Quality				Particulates: Total Nuisance (NIOSH 0500) Respirable (NIOSH 0600)		Comments
		Blk ID by PLM	(PCM) Fiber Count	PLM Point Count	PLM Gravimetric	TEM 50/50	TEM 10/10	TEM 10/10	Blk ID by PLM	Paint (%)	Paint (PPM)	Paint (ng/cm ²)	Soil	Wine * (See Note)	TCLP (Pb)	Waste Water	TCLP RCRA 8	Welding Fume	Toxic Metal Profile	Biocassette	Slide	Surface Swab	Surface Tape	Bulk	Air Volume (L) OR Wipe Area (ft ²) OR Scrape Area (cm ²)	
7-5	5/20/09	X																								Floortile - Mastik
6-8																										Floortile - Mastik
9-11																										Ceiling Tiles - (adv)
12-14																										TRANSIC Panels
15-17																										COVERBASE - GLUP
18-22																										SITE STRUCK - Leads
23-25																										Caulking
26-29																										Vapor Barrier
29-31																										Caulking
32-34		X																								" "

SAMPLE CONDITION
Acceptable
Unacceptable

* Do Wipe samples submitted meet ASTM E1792 requirements? Yes No

Released by: [Signature]
Received by: [Signature]
Released by: [Signature]

Date/Time: 5/20/09
Date/Time: 5-26-09 10:30
Date/Time:
Date/Time:

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.
 7400 Whitepine Road, Richmond, Virginia 23237 Phone (804) 275-4788 Fax (804) 275-4907

CHAIN OF CUSTODY FORM

Company Name: Mystic Air Quality Consultants Date: 5/20/09
 Address: 1204 North Road Contact Name: CHRIS EIDEM
 City, State, Zip: Groton, CT 06340 Sampler Name: CHRIS EIDEM
 EHS Client Account #: 7-2564 B Project #: 429 Macdonough Rd - Laboratory Storage Bldg
 Phone #: 860-449-8903 Fax #: 860-449-8860 Glastonbury, CT
 P.O. #: _____ Client: _____

★ Positive Stop ★

Sample Number	Sample Date & Time	Asbestos				Lead				Other Metals (Specify metals below)				Indoor Air Quality				Particulate: Total Nuisance (NIOSH 0500)		Comments		
		Bulk ID by PLM	(PCM) Fiber Count	PLM Point Count	PLM Gravimetric	NEW AIR (Pb)	NEW AIR (Pb)	NEW AIR (Pb)	NEW AIR (Pb)	Wine* (See Note)	TCLP (Pb)	Waste Water	TCLP RCRA 8	Welding Fume	Toxic Metal Profile	Bioassess	Slide	Surface Swab	Surface Tape		Spilk	Air Volume (L) OR Wipe Area (ft²) OR Scrape Area (cm²)
35-37	5/10/09	X																		Bulk		Silver Paint
38-40																						Glanzing
41																						Flux Cement
42-44																						SHingle
45-47																						" "
48-50																						ROOF FELT
51-53																						ROOFING
54-56																						FLASHING
57-59																						ROOF TAR
60-62																						Silver Paint

* Do Wipe samples submitted meet ASTM E1792 requirements? Yes No

Released by: Bruce K. Leland Signature: Bruce K. Leland Date/Time: 5/20/09
 Received by: M. Sigeman Signature: M. Sigeman Date/Time: 5.26.09 1030
 Released by: _____ Signature: _____ Date/Time: _____



Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

Asbestos Containing Suspect Materials Roster

Site: 409 Marlborough Rd - LABORATORY STORAGE Bldg.
Glastonbury, CT # Demo

Sample numbers

Sample numbers	Type Of Material	Amount of Material	Condition of Material	Specific Location of Suspect ACM at Site
1-5	FLOOR TILE - BLACK MASTIC (1x1)	1250 FT ²	Damaged	Hallway #1, Main Room #1, Room #2, Room #3, Office #1, #2, #3, #4, Mens bathroom, and the Womens Bathroom - ON 1 st LAYER
6-8	FLOOR TILE - Yellow MASTIC (1x1)	385 FT ²		Room #3 and the Kitchen - ONLY LAYER
9-11	Ceiling Tile (2x4)	700 FT ²		Landing, 1/2 of Hallway #1, Room #3, Office #1, #2, #3, #4,
12-14	TRANSITE Panels	7350 FT ²		Throughout Bldg Except Basement & equipment storage
15-17	Coversse - G-lve	700 LNFT		Bottom of Walls - Throughout
18-22	Sheetrock - Walls	-		Throughout
23-25	Caulking	22 Windows	White	Exterior of Windows
26-28	VAPOR Barrier	-		Under Siding on Bldg.
29-31	Caulking	2 doors	White	Exterior of doors at Entrance #1 and Entrance #2
32-34	Caulking	6 Windows	Brown	Exterior of Windows - ROOM #1
35-37	Silver paint	100 LNFT		In Furnace Room on Bite of Furnace Fan pipes around fan
38-40	Glazing	1 Window	X	Interior of Window in Garage Bay #1
41	Flue Cement			around furnace in Furnace Room Pipe

EPA considers the materials above as "suspect" asbestos-containing materials.

Date: 5/22/09

Inspector C. J. J. J.

ENCLOSURE 3 PAGE 1 OF 2

Telecommunications (24 hours):

Office: (203) 449-8903

CT Toll Free: 1 (800) 247-7746

NE Toll Free: 1 (800) 722-7746



Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

Asbestos Containing Suspect Materials Roster

site: 429 Marlborough Rd - Laboratory Storage Bldg.
Glastonbury, CT

DEMO

Sample numbers

Type Of Material	Amount of Material	Condition of Material	Specific Location of Suspect ACM at Site
Shingle	1,050	Damaged	ONLY Layer - Roof #1, Roof #2, and Well House
" "	615 FT ²		ONLY Layer - Roof #3
ROOF FEEL	615 FT ²		Under Shingles - Roof #3
ROOFING	7,250 FT ²		ONLY Layer - FLAT ROOF
FLASHING	50 FT ²	X	around penetrations & on concrete wall - Flat Roof
ROOF TAR	1,000 FT ²		ON SEAMS of Rolled Roofing & patching - Flat Roof
Silver paint	7,250 FT ²		ON Rolled Roofing - ROOF Flat Roof

EPA considers the materials above as "suspect" asbestos-containing materials.

Date: 5/22/09

Inspector *C. J. J. J.*


Telecommunications (24 hours): _____

Office: (203) 449-8903
 FAX: (203) 449-8900

CT Toll Free: 1 (800) 247-7746
 NE Toll Free: 1 (800) 702-7746

5/22/09


LABORATORY Storage Bldg.



Roof Diagram

LABORATORY STORAGE BLDG.

Parking Lot



ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

7469 WHITE PINE ROAD - RICHMOND, VA 23237

804-275-4788 FAX 804-275-4907

TCLP (LEAD) ANALYSIS SUMMARY

CLIENT: Mystic Air Quality Consultants
1204 North Road, Rt. 117
Groton, CT 06340

DATE OF SAMPLING: 20 May 2009
DATE OF RECEIPT: 26 May 2009
DATE OF ANALYSIS: 29 May 2009
DATE OF REPORT: 29 May 2009

CLIENT NUMBER: 7-2564 SB
EHS PROJECT #: 2009-05-1169
PROJECT: 429 Marlborough Rd.; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	SAMPLE WEIGHT (g)	INITIAL pH	CONCENTRATION PPM (mg/L)
01	TCLP #1/ Building Debris	100	8.28	0.50
02	TCLP #2/ Building Debris	100	8.64	<0.50

QUALITY CONTROL DATA

BATCH#:	052909T-1
INCLUSIVE EHS SAMPLE NUMBERS:	01-02
Continuing Calibration Verification 10 (10.0ppm Pb)	99.6% Recovery
Continuing Calibration Verification 5 (5.00ppm Pb)	103% Recovery
Laboratory Control Standard	101% Recovery
Matrix Spike	103% Recovery
Duplicate Relative Percent Difference	0.00 RPD
Regulatory Limit	5.0mg/L
Reporting Limit	0.50mg/L
Method Detection Limit	0.060mg/L

METHOD: EPA SW846 1311/3010A/7420

ANALYST: Aubrey Simonds

Reviewed By Authorized Signatory: 

Howard Varner, General Manager

Irma Faszewski, Quality Assurance Coordinator

David Xu, MS, Senior Chemist

Method EPA SW846 1311 recommends 100g for analysis.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume etc., was provided by the client. This report shall not be reproduced, except in full, without the written consent of Environmental Hazards Services, L.L.C. California Certification #2319 NY ELAP #11714

LEGEND g = gram ug = microgram ppm = parts per million
ml = milliliter Pb = lead mg/L = milligrams per liter

tcipb2.dot/AA220/05AUG2008/REV4/pd

-- PAGE 01 of 01 -- END OF REPORT --

ENCLOSURE 5 PAGE 1 OF 2



Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

May 26, 2009

Mr. Frank Kehoe
Triton Environmental
385 Church Street, Suite 201
Guilford, Connecticut 06437

Re: **Pre-Demolition Asbestos Survey and TCLP Analysis (5/18/09)**
429 Marlborough Road; Glastonbury, Connecticut
Location: Residential House -#1

Dear Mr. Kehoe:

As requested, Mystic Air Quality Consultants, Inc. conducted a survey of accessible materials prior to demolition at the location noted above. This survey was conducted on May 18, 2009, by our State of Connecticut licensed asbestos inspector, Nicholas Carafeno, (license # 000249) to determine the presence of asbestos-containing materials. The samples were analyzed at Environmental Hazards Services (NVLAP # 101882-0) in Virginia.

In addition to the asbestos survey, a composite or TCLP sample was collected and analyzed for lead to determine if the demolition materials would have to be considered lead waste. The sample analysis was also done by Environmental Hazards Services.

Summary of the Asbestos Findings

Upon testing by polarized light microscopy, the following materials were found to be asbestos containing:

Sample #s	Material/Location	Estimated Affected Area
14 - 16	Linoleum/Hallway & Basement Stairs -Top layer	80 sq. ft.
29 - 31	Flooring/Room 4 -Bottom layer	40 sq. ft.

Non-asbestos containing materials

The roster of suspect materials (Enclosure 3), lists the materials tested. Those that are not already referred to as asbestos containing or assumed asbestos, can be categorized as non-asbestos containing materials.

Implications of the findings

As required by state and federal regulations prior to renovation or demolition, any asbestos-containing materials listed above that could be disturbed by a renovation, will need to be removed by a licensed asbestos abatement contractor employing trained and certified personnel who follow all pertinent asbestos abatement regulations.

Communications (24 hours): _____

Office: (860) 449-8903

FAX: (860) 449-8860

Toll Free: 1 (800) 247-7746

website: www.mysticair.com

e-mail: maq2@aol.com



Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

Limitations of the Asbestos survey

This survey and report only deal with accessible areas of the building. Additionally, there may be other non-accessible materials above ceilings, behind walls, and below floors that become evident during your renovation activity. Should the requisite EPA/OSHA competent person working for the contractor discover such materials they will need to be tested for asbestos content so determinations of their abatement and disposal (if required) can be made.

TCLP Analysis results

The results of the TCLP analysis indicate that the building materials subsequent to demolition do not need to be disposed of as lead waste. The sample results were below the EPA's TCLP standard of 5 mg/l for lead.

Please do not hesitate to contact us with questions relating to the sample results. We thank you for the opportunity to conduct this survey.

Sincerely,

A handwritten signature in cursive script, appearing to read "C. Eident".

Christopher J. Eident CIH, CSP, RS
CEO

- Enclosure 1: Laboratory Results
- Enclosure 2: Chain of Custody
- Enclosure 3: Roster of Suspect Materials
- Enclosure 4: Inspector's Diagram of Property
- Enclosure 5: TCLP Analysis and Chain of Custody

Communications (24 hours): _____

Office: (860) 449-8903

FAX: (860) 449-8860

Toll Free: 1 (800) 247-7746

website: www.mysticair.com

e-mail: maq2@aol.com

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

7469 WHITE PINE ROAD - RICHMOND, VA 23237

804-275-4788 FAX 804-275-4907

BULK ASBESTOS SAMPLE ANALYSIS SUMMARY

CLIENT: Mystic Air Quality Consultants
1204 North Road, Rt. 117
Groton, CT 06340

DATE OF RECEIPT: 20 May 2009
DATE OF ANALYSIS: 20 May 2009
DATE OF REPORT: 21 May 2009

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-0971

PROJECT: Triton Env.; Ranch #1: Marlborough Rd.; Glasontbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
01	1/ Gray Powder; Brown Fib.	NAD	30% Cellulose 70% Non-Fibrous
02	2/ Gray Powder; Brown Fib.	NAD	30% Cellulose 70% Non-Fibrous
03	3/ Gray Powder; Brown Fib.	NAD	30% Cellulose 70% Non-Fibrous
04	4/ Gray Powder; Brown Fib.	NAD	30% Cellulose 70% Non-Fibrous
05	5/ Gray Powder; Brown Fib.	NAD	30% Cellulose 70% Non-Fibrous
06	6/ Gray Powder; Brown Fib.	NAD	30% Cellulose 70% Non-Fibrous
07	7/ Gray Powder; Brown Fib.	NAD	30% Cellulose 70% Non-Fibrous
08	8/ Gray Powder; Brown Fib.	NAD	30% Cellulose 70% Non-Fibrous
09	9/ Gray Powder; Brown Fib.	NAD	30% Cellulose 70% Non-Fibrous
10	10/ Gray Powder; Brown Fib.	NAD	30% Cellulose 70% Non-Fibrous
11	11/* Tan Vinyl; Tan Fib. *No mastic present.	NAD	40% Cellulose 60% Non-Fibrous
12A	12(a)-Linoleum/ Tan Vinyl; Tan Fib.	NAD	40% Cellulose 60% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-0971

PROJECT: Triton Env.; Ranch #1, Marlborough Rd.; Glasontbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
12B	12(b)-Mastic/ Yellow Adhes.	NAD	3% Cellulose 97% Non-Fibrous
13A	13(a)-Linoleum/ Tan Vinyl; Tan Fib.	NAD	40% Cellulose 60% Non-Fibrous
13B	13(b)-Mastic/ Yellow Adhes.	NAD	3% Cellulose 97% Non-Fibrous
14A	14(a)-Linoleum/ Brown Vinyl; Brown Fib.	20% Chrysotile 20% Total Asbestos	20% Cellulose 60% Non-Fibrous
14B	14(b)-Mastic/ Yellow Adhes.; Tan Gran.	NAD	2% Cellulose 98% Non-Fibrous
15A	15(a)-Linoleum/	DID NOT ANALYZE	
15B	15(b)-Mastic/ Yellow Adhes.; Tan Gran.	NAD	2% Cellulose 98% Non-Fibrous
16A	16(a)-Linoleum/	DID NOT ANALYZE	
16B	16(b)-Mastic/ Yellow Adhes.; Tan Gran.	NAD	2% Cellulose 98% Non-Fibrous
17	17/ Tan Vinyl; Brown/Black Fib.	NAD	40% Cellulose 60% Non-Fibrous
18	18/ Tan Vinyl; Brown/Black Fib.	NAD	40% Cellulose 60% Non-Fibrous
19	19/ Tan Vinyl; Brown/Black Fib.	NAD	40% Cellulose 60% Non-Fibrous
20A	20(a)-Cove Base/ Black Vinyl	NAD	100% Non-Fibrous
20B	20(b)-Mastic/ Tan Adhes.	NAD	5% Cellulose 95% Non-Fibrous
21A	21(a)-Cove Base/ Black Vinyl	NAD	100% Non-Fibrous
21B	21(b)-Mastic/ Tan Adhes.	NAD	5% Cellulose 95% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-0971

PROJECT: Triton Env.; Ranch #1; Marlborough Rd.; Glasontbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
22A	22(a)-Cove Base/ Black Vinyl	NAD	100% Non-Fibrous
22B	22(b)-Mastic/ Tan Adhes.	NAD	5% Cellulose 95% Non-Fibrous
27A	23(a)-Tile/ Gray Vinyl	NAD	100% Non-Fibrous
27B	23(b)-Mastic/ Tan Adhes.	NAD	1% Cellulose 99% Non-Fibrous
24A	24(a)-Tile/ Gray Vinyl	NAD	100% Non-Fibrous
24B	24(b)-Mastic/ Tan Adhes.	NAD	1% Cellulose 99% Non-Fibrous
25A	25(a)-Tile/ Gray Vinyl	NAD	100% Non-Fibrous
25B	25(b)-Mastic/ Tan Adhes.	NAD	1% Cellulose 99% Non-Fibrous
26	26/★ Tan Vinyl; Tan Fib. ★No mastic present.	NAD	30% Cellulose 10% Fibrous Glass 60% Non-Fibrous
27	27/★ Tan Vinyl; Tan Fib. ★No mastic present.	NAD	30% Cellulose 10% Fibrous Glass 60% Non-Fibrous
28A	28(a)-Linoleum/ Tan Vinyl; Tan Fib.	NAD	30% Cellulose 10% Fibrous Glass 60% Non-Fibrous
28B	28(b)-Mastic/ Yellow Adhes.	NAD	2% Cellulose 98% Non-Fibrous
29	29/ Gray Vinyl; Black Fib.	2% Chrysotile 2% Total Asbestos	38% Cellulose 60% Non-Fibrous
30	30/	DID NOT ANALYZE	

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-0971

PROJECT: Triton Env.; Ranch #1; Marlborough Rd.; Glasontbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
31	31/	DID NOT ANALYZE	
32	32/ Gray Gran.; Black Tar-Like	NAD	35% Cellulose 65% Non-Fibrous
33	33/ Gray Gran.; Black Tar-Like	NAD	35% Cellulose 65% Non-Fibrous
34	34/ Gray Gran.; Black Tar-Like	NAD	35% Cellulose 65% Non-Fibrous
35	35/ Green Gran.; Black Tar-Like	NAD	25% Cellulose 75% Non-Fibrous
36	36/ Green Gran.; Black Tar-Like	NAD	25% Cellulose 75% Non-Fibrous
37	37/ Green Gran.; Black Tar-Like	NAD	25% Cellulose 75% Non-Fibrous
38	38/ Tan Brittle	Trace, <1% Chrysotile <1% Total Asbestos	100% Non-Fibrous
39	39/ Tan Brittle	Trace, <1% Chrysotile <1% Total Asbestos	100% Non-Fibrous
40	40/ Tan Brittle	Trace, <1% Chrysotile <1% Total Asbestos	100% Non-Fibrous
41	41/ Gray Gran.; Black Tar-Like	NAD	35% Cellulose 65% Non-Fibrous
42	42/ Gray Gran.; Black Tar-Like	NAD	35% Cellulose 65% Non-Fibrous
43	43/ Gray Gran.; Black Tar-Like	NAD	35% Cellulose 65% Non-Fibrous
44	44/ White Adhes.	NAD	100% Non-Fibrous
45	45/ White Adhes.	NAD	100% Non-Fibrous
46	46/ White Adhes.	NAD	100% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-0971

PROJECT: Triton Env.; Ranch #1; : Marlborough Rd.; Glasontbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
47	47/ Black Fib.; Black Tar-Like	NAD	91% Cellulose 9% Non-Fibrous
48	48/ Black Fib.; Black Tar-Like	NAD	91% Cellulose 9% Non-Fibrous
49	49/ Black Fib.; Black Tar-Like	NAD	91% Cellulose 9% Non-Fibrous

QC SAMPLE: NY-83-8478

QC BLANK: SRM 1866 Fiberglass

REPORTING LIMIT: 1% Asbestos

METHOD: Polarized Light Microscopy, EPA Method 600/R-93/116 *

ANALYST: Christian H. Schaible

Reviewed By Authorized Signatory: *Howard Varner, General Manager**Irma Faszewski, Quality Assurance Coordinator*

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C. California Certification #2319 NY ELAP #11714. All information concerning sampling location, date, and time can be found on Chain-of-Custody. Environmental Hazards Services, L.L.C. does not perform any sample collection.

Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), for enhanced detection capabilities) for materials regulated by the EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

* All California samples analyzed by Polarized Light Microscopy, EPA Method 600/M4-82-020, Dec. 1982.

LEGEND NAD = no asbestos detected
SCF = suspected ceramic fibers

plm1.dot/05AUG2008/REV3/ MR

-- PAGE 05 of 05 -- END OF REPORT --

ENCLOSURE / PAGE 5 OF 5

EHS 2009-05-0971

1072

49 plm

ENVIRONMENTAL HAZARDS SERVICES, INC.

7469 White Pine Road
 Richmond, Virginia 23237
 (804) 275-4788 Fax (804) 275-4907

CHAIN OF CUSTODY FORM

Customer Information: Date: 5/18/09

Company Name: MYSTIC AIR QUALITY CONSULTANTS, INC. Phone: 860 449 8503

Address: 1204 NORTH RD. Fax: 860 441

City, State, Zip: GROTON, CT 06340 Project: ILION ENV.


Contact: _____ 800-247-7746
Cluster bay 4th floor

Ranch #1

Sample #	Sample Type	Sample Location	Time (min.)	Volume (Liters)
12	plm	wall sheet rock	nm 1	
34		"	nm 4	
5		"	nm 5	
6 7		Ceiling sheet rock	nm 1	
8 9		"	nm 3	
10		"	nm 4	
11 12 13		Lindum white	FTCHAM	
14 15 16		Lindum Toplay	HALLWAY	
17 18 19		Flooring Bottom layer	HALLWAY	
20 21 22		Cove Base water	nm 4	
23 24 25		12x12 Ftile	nm 4 Toplay	
26 27 28		Flooring	nm 4 Middle layer	
29 30 31		Flooring	nm 4 Bottom layer	

Handwritten notes: Handwritten notes - 3 top

CHAIN OF CUSTODY

Date/Time	Released By:	Date/Time	Received By:
		5-20-09 11:00	K. Sizemore

JFJ

ENVIRONMENTAL HAZARDS SERVICES, INC.

7469 White Pine Road
 Richmond, Virginia 23237
 (804) 275-4788 Fax (804) 275-4907

CHAIN OF CUSTODY FORM

Customer Information: _____

Date: 5/18/09

Company Name: MYSTIC AIR QUALITY CONSULTANTS, INC. Phone: 800 449 8803

Address: 1204 NORTH RD. Fax: 414 8860


City, State, Zip: GROTON, CT 06340 Project: TRISTAR ENV.

Contact: 800-247-7746 419 Marlborough rd - Groton, CT

Sample #	Sample Type	Sample Location	Time (min.)	Volume (Liters)
323334	PCM	Roofing shingles		
353637		Roof Toplog		
383940		Roof Bottom log		
414243		Window Glazing		
444546		Roofing shingles		
474849		Window caulking		
		Roof		
		Attic Floor		

Hazardous Waste Release step
CHAIN OF CUSTODY

Date/Time	Released By:	Date/Time	Received By:
	<i>[Signature]</i>	5:20 09 1100	<i>K. Szymanski</i>



Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

Asbestos Containing Suspect Materials Roster

Site: 429 Marlborough rd. RESIDENTIAL HOUSE #1
Clustering CT # Demo

Type Of Material	Amount of Material	Condition of Material	Specific Location of Suspect ACM at Site
1-5 Roof sheet rock	Less than 500sq ft	D	Through out
6-10 Ceiling sheet rock	11 11	2	11 11
11-13 Linoleum	150sq ft	D	rm 2
14-16 Linoleum	80sq ft	2	Hallway ^{Basement stairs} Top layer
17-19 Flooring	80sq ft	D	11 11 Bottom layer
20-22 Cove Base	11ft	D	rm 4
23-25 10' x 12' Floor tile	40sq ft	D	rm 4 Top layer
26-28 Flooring	40sq ft	D	rm 4 middle layer
29-31 Flooring	40sq ft	D	rm 4 Bottom layer
32-34 Roofing shingles	1600sq ft	D	Roof Top layer
35-37 11 11	11 11	D	Roof Bottom layer
38-40 Window Glazing compound	14w	D	Windows (House)

EPA considers the materials above as "suspect" asbestos-containing materials.

Date: 5/18/09

Inspector: 

ENCLOSURE 3 PAGE 1 OF 2

Telecommunications (24 hours): _____


Office: (203) 449-8903

FAX: (203) 449-8860

CT Toll Free: 1 (800) 247-7746

NE Toll Free: 1 (800) 722-7746

RESIDENTIAL HOUSE #1
429 Marlborough Rd.
GASTONBURY, CT



ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

7469 WHITE PINE ROAD - RICHMOND, VA 23237

804-275-4788 FAX 804-275-4907

TCLP (LEAD) ANALYSIS SUMMARY

CLIENT: Mystic Air Quality Consultants
1204 North Road, Rt. 117
Groton, CT 06340

DATE OF SAMPLING: 18 May 2009
DATE OF RECEIPT: 20 May 2009
DATE OF ANALYSIS: 22 May 2009
DATE OF REPORT: 22 May 2009

CLIENT NUMBER: 7-2564 SB
EHS PROJECT #: 2009-05-0950
PROJECT: 429 Marlborough Rd.; Residential #1; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	SAMPLE WEIGHT (g)	INITIAL pH	CONCENTRATION PPM (mg/L)
01	TCLP #1/ Building Debris	100	7.88	<0.50

QUALITY CONTROL DATA

BATCH#:	052209T-1
INCLUSIVE EHS SAMPLE NUMBERS:	01
Initial Calibration Verification (5.00ppm Pb)	99.6% Recovery
Continuing Calibration Verification 10 (10.0ppm Pb)	95.7% Recovery
Continuing Calibration Verification 5 (5.00ppm Pb)	96.0% Recovery
Laboratory Control Standard	101% Recovery
Matrix Spike	104% Recovery
Duplicate Relative Percent Difference	0.00 RPD
Regulatory Limit	5.0mg/L
Reporting Limit	0.50mg/L
Method Detection Limit	0.060mg/L

METHOD: EPA SW846 1311/3010A/7420

ANALYST: Aubrey Simonds

Reviewed By Authorized Signatory: 

Howard Varner, General Manager

Irma Faszewski, Quality Assurance Coordinator

David Xu, MS, Senior Chemist

Method EPA SW846 1311 recommends 100g for analysis.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume etc., was provided by the client. This report shall not be reproduced, except in full, without the written consent of Environmental Hazards Services, L.L.C. California Certification #2319 NY ELAP #11714

LEGEND g = gram ug = microgram ppm = parts per million
ml = milliliter Pb = lead mg/L = milligrams per liter

tclppb2.dot/AA220/05AUG2008/REV4/pd

-- PAGE 01 of 01 -- END OF REPORT --

ENCLOSURE 5 PAGE 1 OF 2

EHS 2009-05-0950 ENVIRONMENTAL HAZARDS SERVICES, L.L.C.
 18B TOLL
 ad. Richmond, Virginia 23237 Phone (804) 276-4788 Fax (804) 276-4807

CHAIN OF CUSTODY FORM

Company Name: Mystic Air Quality Consultants Date: 5/18/09
 Address: 1204 North Road Contact Name: CHARLES EDDEN
 City, State, Zip: Groton, CT 06340 Sampler Name: CHARLES EDDEN
 EHS Client Account #: 7-2564 B Project #: 429 (McLoroy) Rd - Residential #2
 Phone #: 860-449-8903 Fax #: 860-449-8860 Glastonbury, CT

Client: TRISTAR

Sample Number	Sample Date & Time	Asbestos					Lead					Other Metals					Indoor Air Quality					Particulate: Total Nuisance (NIOSH 0500)		Comments									
		Lead					Other Metals					Indoor Air Quality					Particulate: Total Nuisance (NIOSH 0500)																
		(PCM) Fiber Count	PLM Point Count	PLM Gravimetric	TEM Attract	TEM Orifice	Air	Paint (%)	Paint (PPM)	Paint (mg/cm²)	Soil	Wipe* (See Note)	TCLP (Pb)	X	Waste Water	TCLP RCRA 8	Welding Fume	Toxic Metal Profile	Bioassette	Slide	Surface Swab	Surface Tape	Bulk		Air Volume (L)	OR	Wipe Area (ft²)	OR	Scrape Area (cm²)	OR	Respirable (NIOSH 0500)	Total Nuisance (NIOSH 0500)	
18B TOLL #1	5/18/09																																

* Do Wipe samples submitted meet ASTM E1792 requirements? Yes No

Released by: B (Eden) Woodard Signature: Charles Edden Date/Time: 5/18/09
 Received by: J (Cannon) Woodard Signature: Charles Edden Date/Time: 5-20-09
 Released by: _____ Signature: _____ Date/Time: _____
 Received by: _____ Signature: _____ Date/Time: _____



Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

May 27, 2009

Mr. Frank Kehoe
Triton Environmental
385 Church Street, Suite 201
Guilford, Connecticut 06437

Re: **Asbestos Pre-Demolition Inspection (5/18/09)**
429 Marlborough Road; Glastonbury, Connecticut
Location: Residential House #2

Dear Mr. Kehoe:

As requested, Mystic Air Quality Consultants, Inc. conducted a survey of accessible materials prior to demolition at the location noted above. This survey was conducted on May 18, 2009, by our State of Connecticut licensed asbestos inspector, C.Dustin Maurice, (license # 000661) to determine the presence of asbestos-containing materials. The samples were analyzed at Environmental Hazards Services (NVLAP # 101882-0) in Virginia.

Summary of the Asbestos Findings

Upon testing by polarized light microscopy, the following materials were found to be asbestos containing:

<u>Sample #s</u>	<u>Material/Location</u>	<u>Estimated Affected Area</u>
13 – 15	Flashing/Roof Seams & Around Chimney	All
22 – 24	1x1 Black & Off White Floor Tile/Kitchen #1	155 sq. ft.
25 – 27	Textured Paint/Dining Room #1	370 sq. ft.
52 – 54	9x9 Floor Tile/Sun Room	180 sq. ft.

Special Considerations

Any of the non-asbestos roofing materials with flashing attached will need to be treated as asbestos-contaminated and be cut out with the flashing when abated.

Non-asbestos containing materials

The roster of suspect materials (Enclosure 3), lists the materials tested. Those that are not already referred to as asbestos containing or assumed asbestos, can be categorized as non-asbestos containing materials.

Communications (24 hours): _____


Office: (860) 449-8903

FAX: (860) 449-8860

Toll Free: 1 (800) 247-7746

website: www.mysticair.com

e-mail: maq2@aol.com



Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

Implications of the findings

As required by state and federal regulations prior to renovation or demolition, any asbestos-containing materials listed above that could be disturbed by a renovation, will need to be removed by a licensed asbestos abatement contractor employing trained and certified personnel who follow all pertinent asbestos abatement regulations.

Limitations of the Asbestos survey

This survey and report only deal with accessible areas of the building. Additionally, there may be other non-accessible materials above ceilings, behind walls, and below floors that become evident during your renovation activity. Should the requisite EPA/OSHA competent person working for the contractor discover such materials they will need to be tested for asbestos content so determinations of their abatement and disposal (if required) can be made.

Please do not hesitate to contact us with questions relating to the sample results. We thank you for the opportunity to conduct this survey.

Sincerely,

A handwritten signature in cursive script, appearing to read "C. Eident".

Christopher J. Eident CIH, CSP, RS
CEO

- Enclosure 1: Laboratory Results
- Enclosure 2: Chain of Custody
- Enclosure 3: Roster of Suspect Materials
- Enclosure 4: Inspector's Diagram of Property

Communications (24 hours): _____

Office: (860) 449-8903

FAX: (860) 449-8860

Toll Free: 1 (800) 247-7746

website: www.mysticair.com

e-mail: maq2@aol.com

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

7469 WHITE PINE ROAD - RICHMOND, VA 23237

804-275-4788 FAX 804-275-4907

BULK ASBESTOS SAMPLE ANALYSIS SUMMARY

CLIENT: Mystic Air Quality Consultants
1204 North Road, Rt. 117
Groton, CT 06340

DATE OF RECEIPT: 20 May 2009
DATE OF ANALYSIS: 20-21 May 2009
DATE OF REPORT: 21 May 2009

CLIENT NUMBER: 7-2564 SB
EHS PROJECT #: 2009-05-0969
PROJECT: 429 Marlborough Rd.-Residential House #2; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
01	1/ Black Brittle; Black Fib.; Multi-Colored Aggregate	NAD	20% Cellulose 80% Non-Fibrous
02	2/ Black Brittle; Black Fib.; Multi-Colored Aggregate	NAD	20% Cellulose 80% Non-Fibrous
03	3/ Black Brittle; Black Fib.; Multi-Colored Aggregate	NAD	20% Cellulose 80% Non-Fibrous
04	4/ Black/Translucent Pliable	NAD	8% Cellulose 35% Fibrous Glass 57% Non-Fibrous
05	5/ Black/Translucent Pliable	NAD	5% Cellulose 35% Fibrous Glass 60% Non-Fibrous
06	6/ Black/Translucent Pliable	NAD	5% Cellulose 35% Fibrous Glass 60% Non-Fibrous
07	7/ Gray/White Brittle	NAD	2% Cellulose 2% Wollastonite 96% Non-Fibrous
08	8/ Gray/White Brittle	NAD	2% Cellulose 2% Wollastonite 96% Non-Fibrous
09	9/ Gray/White Brittle	NAD	2% Cellulose 2% Wollastonite 96% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-0969

PROJECT: 429 Marlborough Rd.-Residential House #2; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
10	10/ Gray/White Brittle	NAD	1% Cellulose 2% Talc 97% Non-Fibrous
11	11/ Gray/White Brittle	NAD	1% Cellulose 1% Talc 98% Non-Fibrous
12	12/ Gray/White Brittle	NAD	1% Cellulose 1% Talc 98% Non-Fibrous
13	13/ Black Pliable	15% Chrysotile 15% Total Asbestos	3% Cellulose 82% Non-Fibrous
14	14/	DID NOT ANALYZE	
15	15/	DID NOT ANALYZE	
16	16/ Black Fib.	NAD	65% Cellulose 35% Non-Fibrous
17	17/ Black Fib.	NAD	65% Cellulose 35% Non-Fibrous
18	18/ Black Fib.	NAD	65% Cellulose 35% Non-Fibrous
19	19/ Pale Beige Brittle; Off-White Pliable	NAD	1% Cellulose 99% Non-Fibrous
20	20/ Tan Fib.; White/Beige Brittle	NAD	55% Cellulose 45% Non-Fibrous
21	21/ Tan Fib.; White/Beige Brittle	NAD	30% Cellulose 70% Non-Fibrous
22A	22 (a)-Black Tile/ Black Gran.	2% Chrysotile 2% Total Asbestos	2% Cellulose 96% Non-Fibrous
22B	22 (b)-Mastic on Black Tile/ Yellow Adhes.	NAD	4% Cellulose 96% Non-Fibrous
22C	22 (c)-Off-White Tile/ Off-White Gran.	2% Chrysotile 2% Total Asbestos	98% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-0969

PROJECT: 429 Marlborough Rd.-Residential House #2; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
22D	22 (d)-Mastic on Off-White Tile/ Dark Yellow Adhes.	NAD	4% Cellulose 96% Non-Fibrous
23A	23 (a)-Black Tile/	DID NOT ANALYZE	
23B	23 (b)-Mastic on Black Tile/ Yellow Adhes.	NAD	5% Cellulose 95% Non-Fibrous
23C	23 (c)-Off-White Tile/	DID NOT ANALYZE	
23D	23 (d)-Mastic on Off-White Tile/ Yellow Adhes.	NAD	4% Cellulose 96% Non-Fibrous
24A	24 (a)-Black Tile/	DID NOT ANALYZE	
24B	24 (b)-Mastic on Black Tile/ Yellow Adhes.	NAD	5% Cellulose 95% Non-Fibrous
24C	24 (c)-Off-White Tile/	DID NOT ANALYZE	
24D	24 (d)-Mastic on Off-White Tile/ Dark Yellow Adhes.	NAD	4% Cellulose 96% Non-Fibrous
25	25/ Beige/Off-White Brittle	2% Chrysotile * 2% Total Asbestos	1% Cellulose 1% Wollastonite 96% Non-Fibrous
		*Present in off-white texturing compound-type layer.	
26	26/	DID NOT ANALYZE	
27	27/	DID NOT ANALYZE	
28A	28 (a)-Surfacing Panel/ Off-White/Brown Brittle	NAD	60% Cellulose 40% Non-Fibrous
28B	28 (b)-Mastic/ Yellow Adhes.	NAD	7% Cellulose 93% Non-Fibrous
29A	29 (a)-Surfacing Panel/ Off-White/Brown Brittle	NAD	60% Cellulose 40% Non-Fibrous
29B	29 (b)-Mastic/ Yellow Adhes.	NAD	7% Cellulose 93% Non-Fibrous
30A	30 (a)-Surfacing Panel/ Off-White/Brown Brittle	NAD	60% Cellulose 40% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-0969

PROJECT: 429 Marlborough Rd.-Residential House #2; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
30B	30 (b)-Mastic/ Yellow Adhes.	NAD	7% Cellulose 93% Non-Fibrous
31A	31 (a)-Cove Base/ Gray/Black Vinyl-Like	NAD	100% Non-Fibrous
31B	31 (b)-Mastic/ Pale Yellow Adhes.	NAD	5% Cellulose 95% Non-Fibrous
32A	32 (a)-Cove Base/ Gray/Black Vinyl-Like	NAD	100% Non-Fibrous
32B	32 (b)-Mastic/ Pale Yellow Adhes.	NAD	5% Cellulose 95% Non-Fibrous
33A	33 (a)-Cove Base/ Gray/Black Vinyl-Like	NAD	100% Non-Fibrous
33B	33 (b)-Mastic/ Pale Yellow Adhes.	NAD	4% Cellulose 96% Non-Fibrous
34A	34 (a)-Surfacing Panel/ Pale Red/Brown Brittle	NAD	60% Cellulose 40% Non-Fibrous
34B	34 (b)-Mastic/ Dark Yellow Adhes.	NAD	10% Cellulose 90% Non-Fibrous
35A	35 (a)-Surfacing Panel/ Pale Red/Brown Brittle	NAD	60% Cellulose 40% Non-Fibrous
35B	35 (b)-Mastic/ Dark Yellow Adhes.	NAD	10% Cellulose 90% Non-Fibrous
36A	36 (a)-Surfacing Panel/ Pale Red/Brown Brittle	NAD	60% Cellulose 40% Non-Fibrous
36B	36 (b)-Mastic/ Dark Yellow Adhes.	NAD	10% Cellulose 90% Non-Fibrous
37A	37 (a)-Linoleum/ Brown Vinyl; Green Fib.	NAD	20% Cellulose 80% Non-Fibrous
37B	37 (b)-Mastic/ Brown Adhes.	NAD	100% Non-Fibrous
38	38/ Brown Vinyl; Green Fib.	NAD	20% Cellulose 80% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-0969

PROJECT: 429 Marlborough Rd.-Residential House #2; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
39A	39 (a)-Linoleum/ Brown Vinyl; Green Fib.	NAD	20% Cellulose 80% Non-Fibrous
39B	39 (b)-Mastic/ Brown Adhes.	NAD	100% Non-Fibrous
40	40/ Gray Vinyl; Brown Fib.	NAD	20% Cellulose 80% Non-Fibrous
41A	41 (a)-Linoleum/ Gray Vinyl; Beige Fib.	NAD	20% Cellulose 80% Non-Fibrous
41B	41 (b)-Mastic/ Yellow Adhes.	NAD	100% Non-Fibrous
42A	42 (a)-Linoleum/ Gray Vinyl; Brown Fib.	NAD	20% Cellulose 80% Non-Fibrous
42B	42 (b)-Mastic/ Yellow Adhes.	NAD	100% Non-Fibrous
43A	43 (a)-Mastic I/ Yellow Adhes.	NAD	100% Non-Fibrous
43B	43 (b)-Linoleum/ Red Vinyl; Brown Fib.	NAD	20% Cellulose 80% Non-Fibrous
43C	43 (c)-Mastic II/ Brown Adhes.	NAD	100% Non-Fibrous
44A	44 (a)-Mastic I/ Yellow Adhes.	NAD	100% Non-Fibrous
44B	44 (b)-Linoleum/ Red Vinyl; Brown Fib.	NAD	20% Cellulose 80% Non-Fibrous
44C	44 (c)-Mastic II/ Brown Adhes.	NAD	100% Non-Fibrous
45A	45 (a)-Mastic I/ Yellow Adhes.	NAD	100% Non-Fibrous
45B	45 (b)-Linoleum/ Red Vinyl; Brown Fib.	NAD	20% Cellulose 80% Non-Fibrous
45C	45 (c)-Mastic II/ Brown Adhes.	NAD	100% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-0969

PROJECT: 429 Marlborough Rd.-Residential House #2; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
46A	46 (a)-Tile/ Beige Vinyl	NAD	10% Cellulose 90% Non-Fibrous
46B	46 (b)-Mastic I/ Brown Adhes.	NAD	100% Non-Fibrous
46C	46 (c)-Felt I/ Black Fib.	NAD	98% Cellulose 2% Non-Fibrous
46D	46 (d)-Mastic II/ Brown Adhes.	NAD	100% Non-Fibrous
46E	46 (e)-Felt II/ Brown Fib.	NAD	98% Cellulose 2% Non-Fibrous
47A	47 (a)-Tile/ Beige Vinyl	NAD	10% Cellulose 90% Non-Fibrous
47B	47 (b)-Mastic I/ Brown Adhes.	NAD	100% Non-Fibrous
47C	47 (c)-Felt I/ Black Fib.	NAD	98% Cellulose 2% Non-Fibrous
47D	47 (d)-Mastic II/ Brown Adhes.	NAD	100% Non-Fibrous
47E	47 (e)-Felt II/ Brown Fib.	NAD	98% Cellulose 2% Non-Fibrous
48A	48 (a)-Tile/ Beige Vinyl	NAD	10% Cellulose 90% Non-Fibrous
48B	48 (b)-Mastic I/ Brown Adhes.	NAD	100% Non-Fibrous
48C	48 (c)-Felt I/ Black Fib.	NAD	98% Cellulose 2% Non-Fibrous
48D	48 (d)-Mastic II/ Brown Adhes.	NAD	100% Non-Fibrous
48E	48 (e)-Felt II/ Brown Fib.	NAD	98% Cellulose 2% Non-Fibrous
49A	49 (a)-Mastic I/ Brown Adhes.	NAD	100% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-0969

PROJECT: 429 Marlborough Rd.-Residential House #2; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
49B	49 (b)-Felt I/ Black Fib.	NAD	98% Cellulose 2% Non-Fibrous
49C	49 (c)-Mastic II/ Brown Adhes.	NAD	100% Non-Fibrous
49D	49 (d)-Felt II/ Brown Fib.	NAD	98% Cellulose 2% Non-Fibrous
49E	49 (e)-Mastic II/ Brown Adhes.	NAD	100% Non-Fibrous
50A	50 (a)-Mastic I/ Brown Adhes.	NAD	100% Non-Fibrous
50B	50 (b)-Felt/ Black Fib.	NAD	98% Cellulose 2% Non-Fibrous
50C	50 (c)-Mastic II/ Brown Adhes.	NAD	100% Non-Fibrous
51A	51 (a)-Mastic I/ Brown Adhes.	NAD	100% Non-Fibrous
51B	51 (b)-Felt I/ Black Fib.	NAD	98% Cellulose 2% Non-Fibrous
51C	51 (c)-Mastic II/ Brown Adhes.	NAD	100% Non-Fibrous
51D	51 (d)-Felt II/ Brown Fib.	NAD	98% Cellulose 2% Non-Fibrous
52A	52 (a)-Tile/ Gray Vinyl	5% Chrysotile 5% Total Asbestos	95% Non-Fibrous
52B	52 (b)-Mastic/ Black Adhes.	NAD	100% Non-Fibrous
53A	53 (a)-Tile/	DID NOT ANALYZE	
53B	53 (b)-Mastic/ Black Adhes.	NAD	100% Non-Fibrous
54A	54 (a)-Tile/	DID NOT ANALYZE	

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-0969

PROJECT: 429 Marlborough Rd.-Residential House #2; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
54B	54 (b)-Mastic/ Black Adhes.	NAD	100% Non-Fibrous
55	55/ Yellow Adhes.	NAD	20% Fibrous Glass 80% Non-Fibrous
56	56/ Brown Fib.	NAD	45% Cellulose 35% Fibrous Glass 20% Non-Fibrous
57	57/ Brown Fib.	NAD	45% Cellulose 35% Fibrous Glass 20% Non-Fibrous
58	58/ Brown Fib.	NAD	45% Cellulose 35% Fibrous Glass 20% Non-Fibrous
59	59/ Brown Fib.; Off-White Chalky	NAD	15% Cellulose 85% Non-Fibrous
60	60/ Brown Fib.; Off-White Chalky	NAD	15% Cellulose 85% Non-Fibrous
61	61/ Brown Fib.; Off-White Chalky	NAD	15% Cellulose 85% Non-Fibrous
62	62/ Brown Fib.; Off-White Chalky	NAD	15% Cellulose 85% Non-Fibrous
63	63/ Gray Paint-Like; Brown Fib.; White Chalky	NAD	15% Cellulose 85% Non-Fibrous
64	64/ White Paint-Like; Brown Fib.; Gray Chalky	NAD	15% Cellulose 85% Non-Fibrous
65	65/ Brown Fib.; White Chalky	NAD	15% Cellulose 85% Non-Fibrous
66	66/ White/Gray Chalky; Brown Fib.	NAD	15% Cellulose 85% Non-Fibrous
67	67/ White Paint-Like; Brown Fib.; Gray Chalky	NAD	15% Cellulose 85% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB

EHS PROJECT #: 2009-05-0969

PROJECT: 429 Marlborough Rd.-Residential House #2; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
68	68/ White Paint-Like; Brown Fib.; Gray Chalky	NAD	15% Cellulose 85% Non-Fibrous
69	69/ Brown Paint-Like; Fib.; Gran.; White Chalky	NAD	10% Cellulose 90% Non-Fibrous
70	70/ Red/Beige Fib.; White Chalky; Gray Gran.	NAD	10% Cellulose 90% Non-Fibrous
71	71/ Brown Fib.; Paint-Like; White Chalky; Gray Gran.	NAD	10% Cellulose 90% Non-Fibrous
72	72/ Beige/Red/Brown Fib.; White Chalky; Gray Gran.	NAD	10% Cellulose 90% Non-Fibrous
73	73/ Red/Brown Fib.; White Chalky; Gray Gran.	NAD	10% Cellulose 90% Non-Fibrous
74	74/ White Paint-Like; Gray Gran.	NAD	100% Non-Fibrous
75	75/ Brown Fib.; Beige Gran.	NAD	10% Cellulose 90% Non-Fibrous
76	76/ Brown Fib.; Beige Gran.	NAD	10% Cellulose 90% Non-Fibrous
77	77/ Brown Fib.; Gray Gran.	NAD	10% Cellulose 90% Non-Fibrous
78	78/ Brown Fib.; White Paint-Like; Gray Gran.	NAD	10% Cellulose 90% Non-Fibrous
79	79/ Beige Fib.	NAD	98% Cellulose 2% Non-Fibrous
80	80/ Beige Fib.	NAD	98% Cellulose 2% Non-Fibrous
81	81/ Beige Fib.	NAD	98% Cellulose 2% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB
 EHS PROJECT #: 2009-05-0969
 PROJECT: 429 Marlborough Rd.-Residential House #2; Glastonbury, CT

QC SAMPLE: M21995-2
 NY-33-3478


QC BLANK: SRM 1866 Fiberglass

REPORTING LIMIT: 1% Asbestos

METHOD: Polarized Light Microscopy, EPA Method 600/R-93/116 *

ANALYST: Mark Case
 Laura Holder

Reviewed By Authorized Signatory: _____



Howard Varner, General Manager
Irma Faszewski, Quality Assurance Coordinator

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C. California Certification #2319 NY ELAP #11714. All information concerning sampling location, date, and time can be found on Chain-of-Custody. Environmental Hazards Services, L.L.C. does not perform any sample collection.

Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), for enhanced detection capabilities) for materials regulated by the EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

* All California samples analyzed by Polarized Light Microscopy, EPA Method 600/M4-82-020, Dec. 1982.

LEGEND NAD = no asbestos detected
 SCF = suspected ceramic fibers

plm1.dot/05AUG2008/REV3/pd

-- PAGE 10 of 10 -- END OF REPORT --

81 PLW

ENVIRONMENTAL HAZARDOUS SERVICES, L.L.C.
7469 Whitepine Road, Richmond, Virginia 23237 Phone (804) 275-4788 Fax (804) 275-4907

CHAIN OF CUSTODY FORM

Company Name: Mystic Air Quality Consultants Date: 5/19/09
 Address: 1204 North Road Contact Name: CHAS EIDANT
 City, State, Zip: Groton, CT 06340 Sampler Name: CHAS EIDANT
 EHS Client Account #: 7-2564 B Project #: 429 (Purdum) - Residential House #2
 Phone #: 860-449-8903 Fax #: 860-449-8860
 P.O. #: _____ Client: TREX

Particulate: Total Nuisance (NIOSH 0500)
 Respirable (NIOSH 0800)

Sample Number	Sample Date & Time	Asbestos				Lead				Other Metals (Specify metals below)				Indoor Air Quality				Comments				
		PCM) Fiber Count	PLM Point Count	PLM Gravimetric	PLM) Fiber Count	Paint (%)	Paint (PPM)	Paint (mg/cm ²)	Soil	Wine* (See Note)	TCLP (Pb)	Waste Water	TCLP RCRA 8	Welding Fume	Toxic Metal Profile	Biocassette	Slide		Surface Swab	Surface Tape	Bulk	
1-3	5-18-09																					Shingles
4-6																						Felt
7-9																						Caulking
10-12																						Glazing
13-15																						Flashing
16-18																						Felt paper
19-21																						Popcorn Ceiling
22-24																						1x1 Floor Tile + Moist
25-27																						Textured Paint
28-30																						Formica / white

* Do wipe samples submitted meet ASTM E1792 requirements? Yes No

Released by: B. Grant R. Woodard Signature: B. Grant R. Woodard Date/Time: 5/19/09
 Received by: L. Holde Signature: L. Holde Date/Time: 5/20/09 11am
 Released by: _____ Signature: _____ Date/Time: _____
 Received by: _____ Signature: _____ Date/Time: _____

★ Positive Stop ★

★ Positive Stop ★

★ Positive Stop ★

Company Name: Mystic Air Quality Consultants Date: 5/18/09
 Address: 1204 North Road Contact Name: CHRIS EDGAR
Groton, CT 06340 Sampler Name: CHRIS EDGAR
 City, State, Zip: Project #: Residential Home #2 - 409 Northbrook Rd
 EHS Client Account #: 7-2564 B Fax #: 860-449-8860
860-449-8903 Client: IRBITA
 P.O. #: Glendonberry, CT

Sample Number	Sample Date & Time	Asbestos			Lead			Other Metals (Specify metals below)				Indoor Air Quality				Particulate: Total Nuisance (NIOSH 0600)		Comments						
		Bulk ID by PLM	(PCM) Fiber Count	PLM Gravimetric	PLM Point Count	Paint (%)	Paint (PPM)	Paint (mg/cm ²)	Soil	Wine* (See Note)	TCLP (Pb)	Waste Water	TCLP RCRA 8	Welding Fume	Toxic Metal Profile	Biocassette	Slide		Surface Swab	Surface Tape	Bulk	Air Volume (L) OR Wipe Area (ft ²) OR Scrape Area (cm ²)	Respirable (NIOSH 0600)	
31-35	5/18/09	✓																						Cave back
39-36																								Formica Bed
37-39																								Line beam / Red Jar
40-42																								Lead Hanger Gray
43-45																								11 Red
46-48																								Flooring + Mista
49-51																								Paper
52-54																								9x9 Floor Tile + Mista
55																								Flr Cement
56-58																								Ceramic Tile

POS

* Do Wipe samples submitted meet ASTM E1792 requirements? Yes No

Released by: Bob Woodward Signature: Bob Woodward Date/Time: 5/18/09
 Received by: L. Heiler Signature: L. Heiler Date/Time: 5/18/09 11:00am
 Released by: _____ Signature: _____ Date/Time: _____
 Received by: _____ Signature: _____ Date/Time: _____

ENVIRONMENTAL HAZARDOUS SERVICES, L.L.C.
 7469 Whitepine Road, Richmond, Virginia 23237 Phone (804) 275-4788 Fax (804) 275-4907

CHAIN OF CUSTODY FORM

Company Name: Mystic Air Quality Consultants Date: 5/18/09
 Address: 1204 North Road Contact Name: CHARLES EIDEN
 City, State, Zip: Groton, CT 06340 Sampler Name: CHARLES EIDEN
 EHS Client Account #: 7-2564 B Project #: Residential House #2 - 449 Marchwood Rd
 Phone #: 860-449-8903 Fax #: 860-449-8860
 P.O. #: Groton, CT Client: TROTON

Sample Number	Sample Date & Time	Asbestos				Lead				Other Metals			Indoor Air Quality				Particulates: Total Nuisance (NIOSH 0500)		Comments					
		Bulk ID by PLM	(PCM) Fiber Count	PLM Point Count	PLM Gravimetric	PLM Fiber Count	Paint (%)	Paint (PPM)	Paint (mg/cm ²)	Soil	Wipe* (See Note)	TCLP (Pb)	Waste Water	TCLP RCRA 8	Welding Fume	Toxic Metal Profile	Biocassette	Slide		Surface Swab	Surface Tape	Bulk	Air Volume (L) OR Wipe Area (ft ²) OR Scrape Area (cm ²)	Respirable (NIOSH 0600)
59-63	5-18-09	✓																						Sheetrock Walls
64-68																								"
69-73																								Plaster Walls
74-78																								Plaster Circings
79-81																								Blow Insulation

★ Positive Stop ★

* Do wipe samples submitted meet ASTM E1792 requirements? Yes No

Released by: B. Green, R. Winkler Signature: B. Green Date/Time: 5/18/09
 Received by: L. Holder Signature: L. Holder Date/Time: 5/20/09
 Released by: _____ Signature: _____ Date/Time: _____
 Received by: _____ Signature: _____ Date/Time: _____



Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

Asbestos Containing Suspect Materials Roster

Site: 429 Marlborough Rd. - Residential Home #2
Glastonbury, CT # Demo

Type Of Material	Amount of Material	Condition of Material	Specific Location of Suspect ACM at Site
(1-3) shingles	2500 Ft ²	Damaged	Roof
(4-6) Felt	2500 Ft ²		" ↓ "
(7-9) Caulking	34		Window
(10-12) Glazing	34		↓
(13-15) Flashing	Unknown		Roof Seam/Chimney
(16-18) Felt Paper	300 Ft ²		Sun Room against House Under Siding - Bath
(19-21) Popcorn Ceiling	2900 Ft ²		Sun Room / Throughout 2nd Floor / 3rd Floor
(22-24) 1X1 Floor Tile B+W w/ Marble	155 sq		Kitchen #1
(25-27) Textured Paint	370 Ft ²		DINING Room #1
(28-30) Formica/White	30 Ft ²		Kitch #1 Counter / A Wall
(31-32) Cove base	30 Linear Ft		Kitch #1
(33-36) Formica/Red	155 Ft ²	X	Kitchen #2

EPA considers the materials above as "suspect" asbestos-containing materials.

Date: 5/18/09

Inspector D. Maurice

ENCLOSURE 3 PAGE 1 OF 2

Telecommunications (24 hours):

Office: (203) 449-8903

FAX: (203) 449-8860

CT Toll Free: 1 (800) 247-7746

NE Toll Free: 1 (800) 722-7746



Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

Asbestos Containing Suspect Materials Roster

Site: 429 Marlborough Rd - Residential House #2
Glastonbury, CT # Demo

Type Of Material	Amount of Material	Condition of Material	Specific Location of Suspect ACM at Site
(37-39) Limestone / Tan	35 FT ²	Damaged	Hallway 1st Floor / under carpet
(40-42) Limestone / Gray	↓	↓	Kitchen #2 / Top Layer
(43-45) Limestone / Red	↓		Kitchen #2 / Top Layer under plyer
(46-48) Floor Tile / Tan	↓		Kitchen #2 / Bottom layer under plyer
(49-51) Paper 9x9 Tile	155		Kitchen #1
(52-54) Black Granite	180 FT ²		SUN Room
(55) Flue Cement	3 FT ²		Basement / Flue
(56-58) Cooking Tile	400 FT ²		Finest Basement
(59-63) Sheetrock Wall	~ 5000 FT ²		Throughout
(64-68) Sheetrock Ceiling	↓		↓
(69-73) Wall plaster	↓		↓
(74-77) Ceiling plaster	↓	↓	↓
(78-81) Blow Insulation			SUN ROOM

EPA considers the materials above as "suspect" asbestos-containing materials.

Date: 5/18/09

Inspector D. Maurice

ENCLOSURE 3 PAGE 2 OF 2

Telecommunications (24 hours):


Office: (203) 449-8903

FAX: (203) 449-8960


CT Toll Free: 1 (800) 247-7746

NE Toll Free: 1 (800) 722-7746

RESIDENTIAL HOUSE 2
429 MARLBOROUGH
GLASTONBURY, CT



Marlborough Rd





Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

May 26, 2009

Mr. Frank Kehoe
Triton Environmental
385 Church Street, Suite 201
Guilford, Connecticut 06437

Re: **Asbestos Pre-Demolition Inspection (5/18/09)**
429 Marlborough Road; Glastonbury, Connecticut
Location: Residential House #3

Dear Mr. Kehoe:

As requested, Mystic Air Quality Consultants, Inc. conducted a survey of accessible materials prior to demolition at the location noted above. This survey was conducted on May 18, 2009, by our State of Connecticut licensed asbestos inspector, C.Dustin Maurice, (license # 000661) to determine the presence of asbestos-containing materials. The samples were analyzed at Environmental Hazards Services (NVLAP # 101882-0) in Virginia.

Summary of the Asbestos Findings

Upon testing by polarized light microscopy, the following materials were found to be asbestos containing:

<u>Sample #s</u>	<u>Material/Location</u>	<u>Estimated Affected Area</u>
23 - 25	Linoleum/1 st floor -Kitchen & Hallway	350 sq. ft.
35 - 37	Linoleum/2 nd floor -Bathroom #3	75 sq. ft.
41 - 43	Joint Compound/Bathroom #3	75 sq. ft.
53 - 55	Floor Tile/Bathroom #5	60 sq. ft.
59 - 61	Mastic/On cove base throughout basement -except bathroom #5	130 linear ft.
68 - 70	Flashing Tar/Around penetrations on roof	20 sq. ft.

Special Considerations

*The sheetrock is not asbestos. However, because the joint compound is asbestos, the sheetrock should not be sanded, abraded, or ground and only properly trained workers are to be involved in renovation/demolition activities. When demolition occurs the sheetrock system may be disposed of as non-asbestos waste.

Any of the non-asbestos roofing materials with flashing attached will need to be treated as asbestos-contaminated and be cut out with the flashing when abated.

Communications (24 hours): _____

Office: (860) 449-8903

FAX: (860) 449-8860

Toll Free: 1 (800) 247-7746

website: www.mysticair.com

e-mail: maq2@aol.com



Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

Non-asbestos containing materials

The roster of suspect materials (Enclosure 3), lists the materials tested. Those that are not already referred to as asbestos containing or assumed asbestos, can be categorized as non-asbestos containing materials.

Implications of the findings

As required by state and federal regulations prior to renovation or demolition, any asbestos-containing materials listed above that could be disturbed by a renovation, will need to be removed by a licensed asbestos abatement contractor employing trained and certified personnel who follow all pertinent asbestos abatement regulations.

Limitations of the Asbestos survey

This survey and report only deal with accessible areas of the building. Additionally, there may be other non-accessible materials above ceilings, behind walls, and below floors that become evident during your renovation activity. Should the requisite EPA/OSHA competent person working for the contractor discover such materials they will need to be tested for asbestos content so determinations of their abatement and disposal (if required) can be made.

Please do not hesitate to contact us with questions relating to the sample results. We thank you for the opportunity to conduct this survey.

Sincerely,

A handwritten signature in cursive script, appearing to read "C. Eident".

Christopher J. Eident CIH, CSP, RS
CEO

- Enclosure 1: Laboratory Results
- Enclosure 2: Chain of Custody
- Enclosure 3: Roster of Suspect Materials
- Enclosure 4: Inspector's Diagram of Property

Communications (24 hours): _____

Office: (860) 449-8903

FAX: (860) 449-8860

Toll Free: 1 (800) 247-7746

website: www.mysticair.com

e-mail: maqc2@aol.com

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

7469 WHITE PINE ROAD - RICHMOND, VA 23237

804-275-4788 FAX 804-275-4907

BULK ASBESTOS SAMPLE ANALYSIS SUMMARY

CLIENT: Mystic Air Quality Consultants
1204 North Road, Rt. 117
Groton, CT 06340

DATE OF RECEIPT: 20 May 2009
DATE OF ANALYSIS: 20 May 2009
DATE OF REPORT: 21 May 2009

CLIENT NUMBER: 7-2564 SB
EHS PROJECT #: 2009-05-0968
PROJECT: Residential #3

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
01	1/ White Brittle	NAD	2% Talc 98% Non-Fibrous
02	2/ White Brittle	NAD	2% Talc 98% Non-Fibrous
03	3/ White Brittle	NAD	1% Talc 99% Non-Fibrous
04	4/ White Brittle	NAD	100% Non-Fibrous
05	5/ White Brittle	NAD	100% Non-Fibrous
06	6/ White Brittle	NAD	100% Non-Fibrous
07	7/ White Gran.	NAD	100% Non-Fibrous
08	8/ White Gran.	NAD	100% Non-Fibrous
09	9/ White Gran.	NAD	100% Non-Fibrous
10	10/ White Powder; Tan Fib.	NAD	26% Cellulose 74% Non-Fibrous
11	11/ White Powder; Tan Fib.	NAD	25% Cellulose 75% Non-Fibrous
12	12/ White Powder; Tan Fib.	NAD	25% Cellulose 75% Non-Fibrous
13	13/ White Powder; Tan Fib.	NAD	26% Cellulose 74% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB
 EHS PROJECT #: 2009-05-0968
 PROJECT: Residential #3

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
14	14/ Gray Gran.	NAD	100% Non-Fibrous
15	15/ Gray Gran.	NAD	100% Non-Fibrous
16	16/ White/Gray Gran.	NAD	100% Non-Fibrous
17	17/ White/Gray Gran.	NAD	100% Non-Fibrous
18	18/ White/Gray Gran.	NAD	100% Non-Fibrous
19	19/ White/Gray Gran.; Tan Fib.	NAD	14% Cellulose 2% Hair 84% Non-Fibrous
20	20/ Black Fib.; Tar-Like	NAD	80% Cellulose 20% Non-Fibrous
21	21/ Black Fib.; Tar-Like	NAD	80% Cellulose 20% Non-Fibrous
22	22/ Black Fib.; Tar-Like	NAD	80% Cellulose 20% Non-Fibrous
23A	23(a)-Linoleum/ Green Vinyl; White/Beige Fib.; Tan Glue	18% Chrysotile 18% Total Asbestos	5% Cellulose 10% Fibrous Glass 67% Non-Fibrous
23B	23(b)-Mastic/ Tan Adhes.	NAD	100% Non-Fibrous
24A	24(a)-Linoleum/	DID NOT ANALYZE	
24B	24(b)-Mastic/ Tan Adhes.	NAD	100% Non-Fibrous
25A	25(a)-Linoleum/	DID NOT ANALYZE	
25B	25(b)-Mastic/ Tan Adhes.	NAD	100% Non-Fibrous
26	26/ White Gran.	NAD	100% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB
 EHS PROJECT #: 2009-05-0968
 PROJECT: Residential #3

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
27	27/ White Gran.	NAD	100% Non-Fibrous
28	28/ White Gran.	NAD	100% Non-Fibrous
29A	29(a)-Formica/ Brown Hard; Fib.	NAD	40% Cellulose 60% Non-Fibrous
29B	29(b)-Mastic/ Tan Adhes.	NAD	2% Cellulose 98% Non-Fibrous
30A	30(a)-Formica/ Brown Hard; Fib.	NAD	40% Cellulose 60% Non-Fibrous
30B	30(b)-Mastic/ Tan Adhes.	NAD	1% Cellulose 99% Non-Fibrous
31A	31(a)-Formica/ Brown Hard; Fib.	NAD	40% Cellulose 60% Non-Fibrous
31B	31(b)-Mastic/ Tan Adhes.	NAD	2% Cellulose 98% Non-Fibrous
32A	32(a)-Cove Base/ Dk. Gray Vinyl	NAD	100% Non-Fibrous
32B	32(b)-Mastic/ Tan Adhes.	NAD	100% Non-Fibrous
33A	33(a)-Cove Base/ Dk. Gray Vinyl	NAD	100% Non-Fibrous
33B	33(b)-Mastic/ Tan Adhes.	NAD	100% Non-Fibrous
34A	34(a)-Cove Base/ Dk. Gray Vinyl	NAD	100% Non-Fibrous
34B	34(b)-Mastic/ Tan Adhes.	NAD	100% Non-Fibrous
35A	35(a)-Felt I/ Off-White Fib.	45% Chrysotile 45% Total Asbestos	35% Cellulose 20% Non-Fibrous
35B	35(b)-Mastic I/ Tan Adhes.	NAD	100% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB
 EHS PROJECT #: 2009-05-0968
 PROJECT: Residential #3

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
35C	35(c)-Felt II/ White Fib.	NAD	90% Cellulose 10% Non-Fibrous
35D	35(d)-Mastic II/ Brown Adhes.	NAD	2% Cellulose 98% Non-Fibrous
36	36/★ Tan Vinyl; Off-White Fib. ★ No mastic present.	20% Chrysotile ★ 20% Total Asbestos ★ Present in fibrous backing.	10% Cellulose 70% Non-Fibrous
37	37/	DID NOT ANALYZE	
38A	38(a)-Tile/ Beige Vinyl	NAD	100% Non-Fibrous
38B	38(b)-Mastic/ Brown Adhes.	NAD	100% Non-Fibrous
39A	39(a)-Felt/ Beige Vinyl	NAD	100% Non-Fibrous
39B	39(b)-Mastic/ Brown Adhes.	NAD	1% Cellulose 99% Non-Fibrous
40A	40(a)-Tile/ Beige Vinyl	NAD	100% Non-Fibrous
40B	40(b)-Mastic/ Brown Adhes.	NAD	100% Non-Fibrous
41	41/ White/Gray Gran.; Green Wallpaper; Tan Fib.	Trace, <1% Chrysotile ★ <1% Total Asbestos ★2% chrysotile present in the gray joint compound-like material over white texture.	35% Cellulose 65% Non-Fibrous
42	42/ White/Gray Gran.; Green Wallpaper; Tan Fib.	Trace, <1% Chrysotile ★ <1% Total Asbestos ★2% chrysotile present in the gray joint compound-like material over white texture.	35% Cellulose 65% Non-Fibrous
43	43/ White/Gray Gran.; Green Wallpaper; Tan Fib.	Trace, <1% Chrysotile ★ <1% Total Asbestos ★2% chrysotile present in the gray joint compound-like material over white texture.	35% Cellulose 65% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB
 EHS PROJECT #: 2009-05-0968
 PROJECT: Residential #3

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
44A	44(a)-Formica/ Blue/Brown Hard; Fib.	NAD	35% Cellulose 65% Non-Fibrous
44B	44(b)-Mastic/ Tan Adhes.	NAD	2% Cellulose 98% Non-Fibrous
45A	45(a)-Formica/ Blue/Brown Hard; Fib.	NAD	35% Cellulose 65% Non-Fibrous
45B	45(b)-Mastic/ Tan Adhes.	NAD	2% Cellulose 98% Non-Fibrous
46A	46(a)-Formica/ Blue/Brown Hard; Fib.	NAD	35% Cellulose 65% Non-Fibrous
46B	46(b)-Mastic/ Tan Adhes.	NAD	2% Cellulose 98% Non-Fibrous
47	47/ Black Tar-Like; Fib.	NAD	60% Cellulose 12% Synthetic 28% Non-Fibrous
48	48/ Black Tar-Like; Fib.	NAD	60% Cellulose 12% Synthetic 28% Non-Fibrous
49	49/ Black Tar-Like; Fib.	NAD	60% Cellulose 12% Synthetic 28% Non-Fibrous
50	50/ White/Gray Fib.	NAD	88% Fibrous Glass 12% Non-Fibrous
51	51/ White/Gray Fib.	NAD	88% Fibrous Glass 12% Non-Fibrous
52	52/ White/Gray Fib.	NAD	88% Fibrous Glass 12% Non-Fibrous
53A	53(a)-Tile/ Tan Vinyl	3% Chrysotile 3% Total Asbestos	97% Non-Fibrous
53B	53(b)-Mastic/ Tan Adhes.	NAD	100% Non-Fibrous
54A	54(a)-Tile/	DID NOT ANALYZE	
54B	54(b)-Mastic/ Tan Adhes.	NAD	100% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB
 EHS PROJECT #: 2009-05-0968
 PROJECT: Residential #3

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
55A	55(a)-Tile/	DID NOT ANALYZE	
55B	55(b)-Mastic/ Tan Adhes.	NAD	100% Non-Fibrous
56A	56(a)-Tile/ Brown Vinyl	NAD	100% Non-Fibrous
56B	56(b)-Mastic/ Cream Adhes.	NAD	100% Non-Fibrous
57A	57(a)-Tile/ Brown Vinyl	NAD	100% Non-Fibrous
57B	57(b)-Mastic/ Cream Adhes.	NAD	100% Non-Fibrous
58A	58(a)-Tile/ Brown Vinyl	NAD	100% Non-Fibrous
58B	58(b)-Mastic/ Cream Adhes.	NAD	100% Non-Fibrous
59A	59(a)-Cove Base/ Brown Vinyl	NAD	100% Non-Fibrous
59B	59(b)-Mastic/ Brown Adhes.	2% Chrysotile 2% Total Asbestos	2% Cellulose 96% Non-Fibrous
60A	60(a)-Cove Base/ Brown Vinyl	NAD	100% Non-Fibrous
60B	60(b)-Mastic/	DID NOT ANALYZE	
61A	61(a)-Cove Base/ Brown Vinyl	NAD	100% Non-Fibrous
61B	61(b)-Mastic/	DID NOT ANALYZE	
62	62/ Black Tar-Like	NAD	26% Cellulose 74% Non-Fibrous
63	63/ Black Tar-Like	NAD	26% Cellulose 74% Non-Fibrous
64	64/ Black Tar-Like	NAD	26% Cellulose 74% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 - SB
 EHS PROJECT #: 2009-05-0968
 PROJECT: Residential #3

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
65	65/ Black Tar-Like; Fib.	NAD	70% Cellulose 10% Synthetic 20% Non-Fibrous
66	66/ Black Tar-Like; Fib.	NAD	70% Cellulose 10% Synthetic 20% Non-Fibrous
67	67/ Black Tar-Like; Fib.	NAD	70% Cellulose 10% Synthetic 20% Non-Fibrous
68	68/ Black Tar-Like	12% Chrysotile 12% Total Asbestos	88% Non-Fibrous
69	69/	DID NOT ANALYZE	
70	70/	DID NOT ANALYZE	

QC SAMPLE: M1-1991-1
 QC BLANK: SRM 1866 Fiberglass
 REPORTING LIMIT: 1% Asbestos
 METHOD: Polarized Light Microscopy, EPA Method 600/R-93/116 *
 ANALYST: Vickie Holmes

Reviewed By Authorized Signatory: _____

Howard Varner, General Manager
Irma Faszewski, Quality Assurance Coordinator

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C. California Certification #2319 NY ELAP #11714. All information concerning sampling location, date, and time can be found on Chain-of-Custody. Environmental Hazards Services, L.L.C. does not perform any sample collection.

Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), for enhanced detection capabilities) for materials regulated by the EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

* All California samples analyzed by Polarized Light Microscopy, EPA Method 600/M4-82-020, Dec. 1982.

LEGEND NAD = no asbestos detected
 SCF = suspected ceramic fibers

plm1.dot\05AUG2008/REV3/ MR

-- PAGE 07 of 07 -- END OF REPORT --

ENCLOSURE 1 PAGE 7 OF 7

70 plm

EHS 2009-05-0968 Road Richmond, Virginia 232. Phone (804) 275-4788 Fax (804) 275-4907

ENVIRONMENTAL HAZARDOUS SERVICES, L.L.C.

CHAIN OF CUSTODY FORM

★ Positive Stop ★

Company Name: Mystic Air Quality Consultants Date: 5/18/09
 Address: 1204 North Road Contact Name: C. Eickert
 City, State, Zip: Groton, CT 06340 Sampler Name: C. Dusan Maurice
 EHS Client Account #: 7-2564 B Project #: Residential #3
 Phone #: 860-449-8903 Fax #: 860-449-8860 Client: Talon
 P.O. #: _____

Sample Number	Sample & Date	Asbestos					Lead					Other Metals				Indoor Air Quality				Particulate: Total Nuisance (NIOSH 0500)		Comments									
		Bulk ID by PLM	(PCM) Fiber Count	PLM Point Count	PLM Gravimetric	TEM (MFLV) (P)	TEM (MFLV) (B)	Air	Paint (%)	Paint (PPM)	Paint (mg/cm ²)	Soil	Wine * (See Note)	TCLP (Pb)	Waste Water	TCLP RCRA 8	Welding Fume	Toxic Metal Profile	Biocassette	Slide	Surface Swab		Surface Tape	Bulk	Variable Analysis	Air Volume (L) OR Wipe Area (ft ²) OR Scrape Area (cm ²)	Respirable (NIOSH 0600)				
1-3	5-18-09																														
4-6																															
7-9																															
10-14																															
15-19																															
20-22																															
23-25																															
26-28																															
29-31																															
32-34																															

* Do wipe samples submitted meet ASTM E1792 requirements? Yes No

Released by: Brian Winkler Signature: Brian Winkler Date/Time: 5/18/09
 Received by: H. Sizemore Signature: H. Sizemore Date/Time: 5/20/09 11:00
 Released by: _____ Signature: _____ Date/Time: _____
 Received by: _____ Signature: _____ Date/Time: _____

CHAIN OF CUSTODY FORM

Positive Stop

Company Name: Mystic Air Quality Consultants
 Address: 1204 North Road
 City, State, Zip: Groton, CT 06340
 EHS Client Account #: 7-2564 B
 Phone #: 860-449-8903 Fax #: 860-449-8860
 P.O. #: _____
 Date: 5/18/09
 Contact Name: C. Edwards
 Sampler Name: C. Newman
 Project #: Residential #3
 Client: Tilton

Sample Number	Sample & Date	Asbestos				Lead				Other Metals			Indoor Air Quality			Particulate: Total Nuisance (NIOSH 0500)		Comments		
		PLM		PCM		Paint		Soil		Waste			Air Quality			Respirable (NIOSH 0800)				
		Fiber Count	Fiber Count	(PPM)	(mg/cm ²)	Wine * (See Note)	TCLP (Pb)	Waste Water	TCLP RCRAs & Welding Fume	Toxic Metal Profile	Biocassette	Slide	Surface Swab	Surface Tape	Bulk	Viable Analysis	Air Volume (L) OR Wipe Area (ft ²) OR Scrape Area (cm ²)		Specify: -Total Fungal Count w/ID -Stachybotrys Culture w/Total Fungal Count & IDs -Total Thermophilic Fungal Count w/ID	
35-37	5/18/09																		Leadless Floor Tile - Asbestos Textured paint Formica Vapor Barrier Blown Insulation Floor Tile + Plaster Flooring Crown Molding Adhesive Joints	
38-40																				
41-43																				
44-46																				
47-49																				
50-52																				
53-55																				
56-58																				
59-61																				
62-64																				

Positive Stop



Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

Asbestos Containing Suspect Materials Roster

Site: Residential #3
Glastonbury, CT

Demo

Type Of Material	Amount of Material	Condition of Material	Specific Location of Suspect ACM at Site
1-3 Glazing	28 Windows	Damaged	Exterior of Windows
4-6 Caulking	28 Windows		" " "
7-9 POPCOB SPRAY PAINT	3,618 FT ²		Throughout Except Kitchen & Bathroom #1
10-14 SHEETROCK WALLS	—		" " "
15-19 PLASTER CEILING	3,918 FT ²		" " "
20-22 Vapor Barrier	—		under siding of House - Exterior
23-25 Flooring	350 FT ²		Kitchen & Hallway - 1 st Floor
26-28 Textured Paint	200 FT ²		Kitchen & Bathroom #2 - Ceilings
29-31 FORMICA	60 FT ²		Yellow Kitchen Counter tops & ^{on walls} above counter
32-34 Covebase - Glue	30 LBFT		Kitchen
35-37 LINOLEUM	75 FT ²		Bathroom #3 - 2 nd Floor
38-40 FLOOR TILE MASTIC	50 FT ²	X	Bathroom #4 - 2 nd Floor

EPA considers the materials above as "suspect" asbestos-containing materials.

Date: 5/18/01

Inspector

Telecommunications (24 hours): _____

ENCLOSURE 4 PAGE 1 OF 2

Office: (203) 449-8903

CT Toll Free: 1 (800) 247-7741

FAX: (203) 440-8860

NE Toll Free: 1 (800) 722-7741



Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

Asbestos Containing Suspect Materials Roster

Site: Residential House #3
Glastonbury, CT

Demo

Type Of Material	Amount of Material	Condition of Material	Specific Location of Suspect ACM at Site	
41-43 Textured Paint	75 FT ²	Damaged	Bathroom #3 - Ceiling	
44-46 Formica	20 FT ²	Green	Bathroom #3 - Countertops	
47-49 Vapor Barrier	2500 FT ²		Under Hardwood Floors - Throughout	
50-52 Blown In Insulation	3928 FT ²		Above Ceilings - Throughout	
53-55 Floor tile - mosaic	60 FT ²		Bathroom #5 - Basement	
56-58 Flooring	2400 FT ²		Basement - Except Bathroom #5	
59-61 Cove Base - Glue	130 LBS		Throughout Basement except Bathroom #5	
62-64 Shingles	3928 FT ²		Only Layer - Roof	
65-67 Roof Felt	3928 FT ²		Under Shingles - Roof	
68-70 Flashing	20 FT ²		X	Around penetrations - Roof

EPA considers the materials above as "suspect" asbestos-containing materials.

Date: 5/18/09

Inspector C. P.

ENCLOSURE 4 PAGE 2 OF 2

Telecommunications (24 hours):

Office: (203) 449-8903


FAX: (203) 449-8860

CT Toll Free: 1 (800) 247-7741

NE Toll Free: 1 (800) 722-7741


Residential House #3
1st Floor.

(2nd Floor - on Basic page)



FRONT

2nd Floor



Back



Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

May 26, 2009

Mr. Frank Kehoe
Triton Environmental
385 Church Street, Suite 201
Guilford, Connecticut 06437

Re: **Pre-Demolition Asbestos Survey and TCLP Analysis (5/18/09)**
429 Marlborough Road; Glastonbury, Connecticut
Location: Residential House -#4

Dear Mr. Kehoe:

As requested, Mystic Air Quality Consultants, Inc. conducted a survey of accessible materials prior to demolition at the location noted above. This survey was directed on May 18, 2009, by our State of Connecticut licensed asbestos inspector, Christopher Eident, (license # 000015) to determine the presence of asbestos-containing materials. The samples were analyzed at Environmental Hazards Services (NVLAP # 101882-0) in Virginia.

In addition to the asbestos survey, a composite or TCLP sample was collected and analyzed for lead to determine if the demolition materials would have to be considered lead waste. The sample analysis was also done by Environmental Hazards Services.

Summary of the Asbestos Findings

Upon testing by polarized light microscopy, the following materials were found to be asbestos containing:

<u>Sample #s</u>	<u>Material/Location</u>	<u>Estimated Affected Area</u>
20 - 22	Linoleum & Mastic/2 nd floor Room 8-bath & Room 9-shower room	50 sq. ft.
26 - 28	9x9 Floor Tile/Basement	400 sq. ft.
29 - 31	Linoleum/Kitchen & Room 3	200 sq. ft.

Non-asbestos containing materials

The roster of suspect materials (Enclosure 3), lists the materials tested. Those that are not already referred to as asbestos containing or assumed asbestos, can be categorized as non-asbestos containing materials.

Implications of the findings

As required by state and federal regulations prior to renovation or demolition, any asbestos-containing materials listed above that could be disturbed by a renovation, will need to be removed by a licensed asbestos abatement contractor employing trained and certified personnel who follow all pertinent asbestos abatement regulations.

Communications (24 hours): _____

Office: (860) 449-8903

FAX: (860) 449-8860

Toll Free: 1 (800) 247-7746

website: www.mysticair.com

e-mail: maq2@aol.com



Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

Limitations of the Asbestos survey

This survey and report only deal with accessible areas of the building. Additionally, there may be other non-accessible materials above ceilings, behind walls, and below floors that become evident during your renovation activity. Should the requisite EPA/OSHA competent person working for the contractor discover such materials they will need to be tested for asbestos content so determinations of their abatement and disposal (if required) can be made.

TCLP Analysis results

The results of the TCLP analysis indicate that the building materials subsequent to demolition do not need to be disposed of as lead waste. The sample results were below the EPA's TCLP standard of 5 mg/l for lead.

Please do not hesitate to contact us with questions relating to the sample results. We thank you for the opportunity to conduct this survey.

Sincerely,

Christopher J. Eident CIH, CSP, RS
CEO

- Enclosure 1: Laboratory Results
- Enclosure 2: Chain of Custody
- Enclosure 3: Roster of Suspect Materials
- Enclosure 4: Inspector's Diagram of Property
- Enclosure 5: TCLP Analysis and Chain of Custody

Communications (24 hours): _____

Office: (860) 449-8903

FAX: (860) 449-8860

Toll Free: 1 (800) 247-7746

website: www.mysticair.com

e-mail: maq2@aol.com

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

7469 WHITE PINE ROAD - RICHMOND, VA 23237

804-275-4788 - FAX 804-275-4907

BULK ASBESTOS SAMPLE ANALYSIS SUMMARY

CLIENT: Mystic Air Quality Consultants
1204 North Road, Rt. 117
Groton, CT 06340

DATE OF RECEIPT: 20 May 2009
DATE OF ANALYSIS: 21 May 2009
DATE OF REPORT: 21 May 2009

CLIENT NUMBER: 7-2564 SB
EHS PROJECT #: 2009-05-0970
PROJECT: Residence #4; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
01	1/ White Powdery; Beige Fib.	NAD	18% Cellulose 82% Non-Fibrous
02	2/ White Powdery; Beige Fib.	NAD	18% Cellulose 82% Non-Fibrous
03	3/ White Powdery; Beige Fib.	NAD	20% Cellulose 80% Non-Fibrous
04	4/ White Powdery	NAD	20% Cellulose 80% Non-Fibrous
05	5/ White Powdery; Beige Fib.	NAD	18% Cellulose 82% Non-Fibrous
06	6/ White Chalky; Gray Gran.	NAD	100% Non-Fibrous
07	7/ White Chalky; Gray Gran.	NAD	100% Non-Fibrous
08	8/ White Chalky; Gray Gran.	NAD	100% Non-Fibrous
09	9/ White Chalky	NAD	100% Non-Fibrous
10	10/ White Chalky; Gray Gran.; Beige Fib.	NAD	5% Cellulose 95% Non-Fibrous
11	11/ White Powdery; Beige Fib.	NAD	18% Cellulose 82% Non-Fibrous
12	12/ White Powdery; Beige Fib.	NAD	30% Cellulose 70% Non-Fibrous
13	13/ White Powdery; Beige Fib.	NAD	35% Cellulose 65% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB
 EHS PROJECT #: 2009-05-0970
 PROJECT: Residence #4; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
14	14/ White Chalky; Gray Gran.; Beige Fib.	NAD	4% Cellulose 96% Non-Fibrous
15	15/ Gray Gran.; Lt. Gray Powdery; Beige Fib.	NAD	7% Cellulose 93% Non-Fibrous
16	16/ White Chalky; Gray Gran.; Beige Fib.	NAD	5% Cellulose 95% Non-Fibrous
17	17/ White/Cream Paint-Like	NAD	100% Non-Fibrous
18	18/ White/Cream Paint-Like	NAD	100% Non-Fibrous
19	19/ White/Cream Paint-Like	NAD	100% Non-Fibrous
20A	20(a)-Linoleum/ Beige Vinyl; Fib.	25% Chrysotile ★ 25% Total Asbestos ★Present in fibrous backing.	10% Cellulose 65% Non-Fibrous
20B	20(b)-Mastic/ Cream Adhes.	2% Chrysotile ★ 2% Total Asbestos ★Possible contamination from fibrous backing.	98% Non-Fibrous
21A	21(a)-Linoleum/	DID NOT ANALYZE	
21B	21(b)-Mastic/	DID NOT ANALYZE	
22A	22(a)-Linoleum/	DID NOT ANALYZE	
22B	22(b)-Mastic/	DID NOT ANALYZE	
23	23/ Brown Adhes.	NAD	100% Non-Fibrous
24	24/ Brown Adhes.	NAD	100% Non-Fibrous
25	25/ Brown Adhes.	NAD	100% Non-Fibrous
26A	26(a)-Tile/ Brown Vinyl	4% Chrysotile 4% Total Asbestos	96% Non-Fibrous
26B	26(b)-Mastic/ Black Adhes.	Trace, <1% Chrysotile <1% Total Asbestos	100% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB
 EHS PROJECT #: 2009-05-0970
 PROJECT: Residence #4; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
27A	27(a)-Tile/	DID NOT ANALYZE	
27B	27(b)-Mastic/ Black Adhes.	Trace, <1% Chrysotile <1% Total Asbestos	100% Non-Fibrous
28A	28(a)-Tile/	DID NOT ANALYZE	
28B	28(b)-Mastic/ Black Adhes.	Trace, <1% Chrysotile <1% Total Asbestos	100% Non-Fibrous
29A	29(a)-Linoleum/ Beige Vinyl; Fib.	20% Chrysotile ★ 20% Total Asbestos ★Present in fibrous backing.	15% Cellulose 65% Non-Fibrous
29B	29(b)-Underlayment/ Gray/Green Fib.	NAD	75% Cellulose 15% Synthetic 10% Non-Fibrous
30A	30(a)-Linoleum/	DID NOT ANALYZE	
30B	30(b)-Underlayment/ Green/Gray Fib.	NAD	75% Cellulose 15% Synthetic 10% Non-Fibrous
30C	30(c)-Mastic/ Brown Adhes.	NAD	3% Cellulose 97% Non-Fibrous
31A	31(a)-Linoleum/	DID NOT ANALYZE	
31B	31(b)-Underlayment/ Gray/Green Fib.	NAD	75% Cellulose 10% Synthetic 15% Non-Fibrous
31C	31(c)-Mastic/ Brown Adhes.	NAD	100% Non-Fibrous
32A	32(a)-Linoleum/ Tan Vinyl; Fib.	NAD	25% Cellulose 10% Fibrous Glass 65% Non-Fibrous
32B	32(b)-Mastic/ Yellow Adhes.	NAD	5% Cellulose 95% Non-Fibrous
33A	33(a)-Linoleum/ Tan Vinyl; Fib.	NAD	25% Cellulose 10% Fibrous Glass 65% Non-Fibrous
33B	33(b)-Mastic/ Yellow Adhes.	NAD	5% Cellulose 95% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB
 EHS PROJECT #: 2009-05-0970
 PROJECT: Residence #4; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
34A	34(a)-Linoleum/ Tan Vinyl; Fib.	NAD	20% Cellulose 15% Fibrous Glass 65% Non-Fibrous
34B	34(b)-Mastic/ Yellow Adhes.	NAD	5% Cellulose 95% Non-Fibrous
35	35/ Cream Gran.	NAD	100% Non-Fibrous
36	36/ Cream Gran.	NAD	100% Non-Fibrous
37	37/ White/Cream Gran.	NAD	100% Non-Fibrous
38	38/ Black Tar-Like; Gray Gran.	NAD	10% Fibrous Glass 90% Non-Fibrous
39	39/ Black Tar-Like; Gray Gran.	NAD	10% Fibrous Glass 90% Non-Fibrous
40	40/ Black Tar-Like; Gray Gran.	NAD	10% Fibrous Glass 90% Non-Fibrous
41	41 Black Fib.; Tar-Like	NAD	85% Cellulose 15% Non-Fibrous
42	42/ Black Fib.; Tar-Like	NAD	85% Cellulose 15% Non-Fibrous
43	43/ Black Fib.; Tar-Like	NAD	85% Cellulose 15% Non-Fibrous
44	44/ Black Fib.	NAD	90% Cellulose 10% Non-Fibrous
45	45/ Black Fib.	NAD	90% Cellulose 10% Non-Fibrous
46	46/ Black Fib.	NAD	90% Cellulose 10% Non-Fibrous
47	47/ White Rubbery	NAD	100% Non-Fibrous
48	48/ White Rubbery	NAD	100% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 7-2564 SB
 EHS PROJECT #: 2009-05-0970
 PROJECT: Residence #4; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
49	49/ White Rubbery	NAD	100% Non-Fibrous

QC SAMPLE: M12000-3
 QC BLANK: SRM 1866 Fiberglass
 REPORTING LIMIT: 1% Asbestos
 METHOD: Polarized Light Microscopy, EPA Method 600/R-93/116 *
 ANALYST: Katherine Charles Harris

Reviewed By Authorized Signatory: _____

Howard Varner, General Manager
Irma Faszeiwski, Quality Assurance Coordinator

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C. California Certification #2319 NY ELAP #11714. All information concerning sampling location, date, and time can be found on Chain-of-Custody. Environmental Hazards Services, L.L.C. does not perform any sample collection.

Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), for enhanced detection capabilities) for materials regulated by the EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

* All California samples analyzed by Polarized Light Microscopy, EPA Method 600/M4-82-020, Dec. 1982.

LEGEND NAD = no asbestos detected
 SCF = suspected ceramic fibers

plm1.dot/05AUG2008/REV3/ MR

— PAGE 05 of 05 — END OF REPORT —

Lot 2

IS 2009-05-0970

49 pmH
45 plm

ENVIRONMENTAL HAZARDS SERVICES, INC.

7469 White Pine Road
Richmond, Virginia 23237
(804) 275-4788 Fax (804) 275-4907

CHAIN OF CUSTODY FORM

Customer Information:	Date: <u>5/18/09</u>
Company Name: <u>MYSTIC AIR QUALITY CONSULTANTS, INC.</u>	Phone: <u>860 949 8503</u>
Address: <u>1204 NORTH RD.</u>	Fax: <u>860 949 8800</u>
City, State, Zip: <u>GROTON, CT 06340</u>	Project: <u>TRUCK CAN.</u>
Contact: <u>800-247-7746</u>	<u>RESIDENCE #4</u> <u>CLINTONBURGH, CT</u>

Sample #	Sample Type	Sample Location	Time (min.)	Volume (Liters)
1 2	plm	wall sheet rock	Am 7	
3 4		ll "	am 3	
5		ll "	am 2	
6 7		wall plaster	am 1	
8 9		ll "	am 2	
10		ll "	am 4	
11 12 13		Ceiling sheet rock	throughout	SAVE
14 15 16		Ceiling plaster w/old sheet rock	throughout	ACCA
17 18 19		Calumet	throughout	
20 21 22		Linoleum	Basement & Barn	
23 24 25		Adhesive	Basement	
26 27 28		9x9 FLOOR MATS	Basement	
29 30 31		Linoleum w/ carpet	am 3 Fitcher	
32 33 34		Linoleum	am 4 1st Fl Barn	
Homogenous residue step				

CHAIN OF CUSTODY

Date/Time	Released By:	Date/Time	Received By:
	<i>[Signature]</i>	5-20-09	K. Syme

20f2

ENVIRONMENTAL HAZARDS SERVICES, INC.

7469 White Pine Road
Richmond, Virginia 23237
(804) 275-4788 Fax (804) 275-4907

CHAIN OF CUSTODY FORM

Customer Information: Date: 5/18/09
Company Name: MYSTIC AIR QUALITY CONSULTANTS, INC. Phone: 860-449-8903
Address: 1204 NORTH RD. Fax:
City, State, Zip: GROTON, CT 06340 Project: TYPED ENV.
Contact: HUSTON, J. Residue # 14

Table with 5 columns: Sample #, Sample Type, Sample Location, Time (min.), Volume (Liters). Rows include samples 353637, 3883940, 414243, 444546, 474845 with locations like window caulking, roofing shingle, vapor pipe, under wood siding.

Heterogeneous positive step

CHAIN OF CUSTODY

Table with 4 columns: Date/Time, Released By, Date/Time, Received By. Includes signature and date 5/20/09.



Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

Asbestos Containing Suspect Materials Roster


Site: Residence #4

Winstorbury Ct Northborough Ct. # _____

Type Of Material	Amount of Material	Condition of Material	Specific Location of Suspect ACM at Site
1-5 wall sheet rock	Less than 5000	D	through out
6-10 wall plaster	" "	D	" "
11-13 ceiling sheet rock	" "	D	" "
14-16 ceiling plaster	" "	D	" "
17-19 ceiling tile	" "	D	" "
20-22 Linoleum	50sq	D	2nd Fl Bath + Staircase
23-25 Adhesive	20sq	D	behind wall paneling + 2nd Fl hallway - Stairs
26-28 9x9 Ft tile mosaic	400sq	D	Basement
29-31 Linoleum	200sq	D	Kitchen #3
32-34 Linoleum	60sq	D	No 4 Bath
35-37 Underlayment compound		D	underlayment

EPA considers the materials above as "suspect" asbestos-containing materials.

Date: 5/18/09

Inspector: 



Mystic Air Quality Consultants, Inc.

1204 North Road (Rt. 117) Groton, Connecticut 06340

Asbestos Containing Suspect Materials Roster



Site: Residence #4
Easton CT Marlborough rd #

Type Of Material	Amount of Material	Condition of Material	Specific Location of Suspect ACM at Site
38-40 Roofing shingle	2000 sq ft	D	Roof
41-43 Vapor barrier	2000 sq ft	D	Roof
44-46 Vapor barrier	5000 sq ft	D	Under wood siding exterior + interior
47-49 Window caulking	2000	D	Windows

EPA considers the materials above as "suspect" asbestos-containing materials.

Date: 5/18/69 Inspector: [Signature]

429 Marlborough Rd.
Glastonbury, CT
Residential HOUSE
BIN-4)



ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

7469 WHITE PINE ROAD - RICHMOND, VA 23237

804-275-4788 FAX 804-275-4907

TCLP (LEAD) ANALYSIS SUMMARY

CLIENT: Mystic Air Quality Consultants
1204 North Road, Rt. 117
Groton, CT 06340

DATE OF SAMPLING: 18 May 2009
DATE OF RECEIPT: 20 May 2009
DATE OF ANALYSIS: 22 May 2009
DATE OF REPORT: 22 May 2009

CLIENT NUMBER: 7-2564 SB
EHS PROJECT #: 2009-05-0955
PROJECT: Residential #4; Glastonbury, CT

EHS SAMPLE #	CLIENT SAMPLE # LABORATORY GROSS DESCRIPTION	SAMPLE WEIGHT (g)	INITIAL pH	CONCENTRATION PPM (mg/L)
01	1/ Building Debris	100	5.47	1.1


QUALITY CONTROL DATA

BATCH#:	052209T-1
INCLUSIVE EHS SAMPLE NUMBERS:	01
Initial Calibration Verification (5.00ppm Pb)	99.6% Recovery
Continuing Calibration Verification 10 (10.0ppm Pb)	95.7% Recovery
Continuing Calibration Verification 5 (5.00ppm Pb)	96.0% Recovery
Laboratory Control Standard	101% Recovery
Matrix Spike	104% Recovery
Duplicate Relative Percent Difference	0.00 RPD
Regulatory Limit	5.0mg/L
Reporting Limit	0.50mg/L
Method Detection Limit	0.060mg/L

METHOD: EPA SW846 1311/3010A/7420

ANALYST: Aubrey Simonds

Reviewed By Authorized Signatory:



Howard Varner, General Manager

Irma Faszewski, Quality Assurance Coordinator

David Xu, MS, Senior Chemist

Method EPA SW846 1311 recommends 100g for analysis.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume etc., was provided by the client. This report shall not be reproduced, except in full, without the written consent of Environmental Hazards Services, L.L.C. California Certification #2319 NY ELAP #11714

LEGEND	g = gram	ug = microgram	ppm = parts per million
	ml = milliliter	Pb = lead	mg/L = milligrams per liter

tclppb2.dot/AA220/05AUG2008/REV4/pd

-- PAGE 01 of 01 -- END OF REPORT --

ENCLOSURE 5 PAGE 1 OF 2

1 PB TCFP

CHAIN OF CUSTODY FORM

Company Name: Mystic Air Quality Consultants Date: 5/18/09
 Address: 1204 North Road Contact Name: C. Eident
 City, State, Zip: Groton, CT 06340 Sampler Name: N. Carbone
 EHS Client Account #: 7-2564 B Project #: Residential #14
 Phone #: 860-449-8903 Fax #: 860-449-8860
 P.O. #: 615500101 CT
 Client: Intox


Sample Number	Sample Date & Time	Asbestos				Lead				Other Metals (Specify metals below)				Indoor Air Quality				Particulate: Total Nuisance (NIOSH 0600)		Comments
		Bulk ID by PLM	(PCM) Fiber Count	PLM Gravimetric	TEM Filterable	Waste Water	Welding Fume	TCLP RCRA 8	Toxic Metal Profile	Biocassette	Slide	Surface Swab	Surface Tape	Bulk	Air Volume (L) OR Wipe Area (ft²) OR Scrape Area (cm²)	Respirable (NIOSH 0600)				
	5/18/09					Wine * (See Note)														

* Do wipe samples submitted meet ASTM E1792 requirements? Yes No

Released by: B. Carbone Signature: B. Carbone Date/Time: 5/18/09
 Received by: _____ Signature: _____ Date/Time: _____
 Released by: J. Carbone Signature: J. Carbone Date/Time: 5-20-09
 Received by: _____ Signature: _____ Date/Time: _____


Attachment C

Site Plan
429 Marlborough Road




LOCATION PLAN
Scale: 1"=1000'


- Structures Previously Demolished
- Structures Included in Asbestos Removal Contract



REVISIONS		
NO.	DESCRIPTION	DATE
1.	CHANGE BUILDINGS UNDER CONTRACT	9/21/2010



SCALE: AS SHOWN	DATE: 10/2/2009
DRAWN BY: C.F.S.	CHECKED BY: R.S.E.
APPROVED BY: R.W.S.	ST. FILE:



PLAN
Depicting
ASBESTOS REMOVAL CONTRACT LIMITS
at
ARBOR ACRES FARM
located at
411, 429, 439, 447 & 467 MARLBOROUGH ROAD
GLASTONBURY, CONNECTICUT