

## Historic District Commission COA Narrative and photos

Removal of existing picket fence on the north and south sides of the property. The original wood fence was custom made and installed in approximately 1990. It has been painted numerous times and pickets have been replaced from time-to-time. A large section of the Meadow Road side was damaged beyond repair during Hurricane Isaias. A number of the sides of the fence are attached to tree stumps, where the original trees have since been cut down. Those stumps are now finally decomposing.

The removal would be of all the pickets, the standalone wooden fence posts, the wooden posts attached to the granite fence posts and the sidewalk end/decorative posts. All granite posts remain in place in the original historic location.

At this time there is not an application to install a new or replacement fence.

