



← North of Boat house


Cracked Concrete Ramp



Movement at
Scenic Overlook



Lateral and Vertical Movement
at Overlook



Excavated Patio to
Provide Load Relief

