

# TOWN OF GLASTONBURY

GL-2014-02

Fire & Security Alarm Systems Maintenance

ADDENDUM # 1

5/29/2013

Proposal Due Date Remains  
**June 5, 2013 @ 11:00 A.M.**

The attention of bidders submitting proposals for the above-referenced project is called to the following Addendum to the specifications. The items set forth herein, whether of omission, addition, substitution or other change, are all to be included in and form a part of the proposal as described in GL-2014-02

1 . Attachment: Fire-Security Device Count.xlsx

Note: This addendum consists of 3 pages including the above text.

END OF TEXT

Town of Glastonbury  
Number of Devices

Fire

Location	Pull Station	Smokes	Duct	Heats	Waterflow	Supervisory	Ansul	Horns	Strobes	Speakers	Beacon	CO Detector
Ambulance	7	5			1	4		5	5			
Bulky Waste												
Dog Pound	1	3		3				2	2			
Fire Co 1	4	1			1	1	1	3	3			
Fire Co 2	5	1		16	1		1	4	4			
Fire Co 3	7	3		24	1	2	1	4	4			
Fire Co 4	6	5		19	1	2	1	3	3			
Gideon Welles House	6	7		18	1	2		6	11			
Parks Garage	5	8		8				11	11			
Police Annex	3	1		5				3	3			
Police Facility	6	20		23				10	10			
Police Tower		3		3								
Rverfront Community	11	1	4	4	2	5			34	20		
Town Hall Complex	29	8	8	13	3	4		30	44	7		
Transfer Station												
Vehicle Maintenance	6			15				3	3			1
Water Pollution	27	48	1	17				33	46		3	
Welles Turner Library	17	15	6	3	1	2		73	73			
Williams St.	6	13	5	12				5	5			
Youth & Family	5	9		20				4	5			
Youth & Family Annex	4	2		5				4	4			

Number of Devices

Security

Location	Perimeter	Panic	Motion	Photo Eye	Panels	Supervisory	Other
Ambulance							
Bulky Waste	2	1	2				
Dog Pound	3		1				
Fire Co 1		1					
Fire Co 2							
Fire Co 3							
Fire Co 4							
Gideon Welles House							
Parks Garage	13		8				1 - Low Temp
Police Annex							
Police Facility	3	5 Hard					1 - High Heat in Tower
Police Tower	2	8 wireless					1 - High Heat
Rverfront Community	14	3	6			1- Repeater	1 - Freezer Temp.
Town Hall Complex	3	16	2				2 - Boiler, Generator
Transfer Station	6	1	2				1 - Low Temp
Vehicle Maintenance	5		3	2			2 - Glass Break, Low Temp.

13 Card Access Not Part of Maintenance, just repair

